

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/AIG21007957/URS3Q2
Date: 20/09/2021**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2100439355
Claimant Vehicle No :	SJM1517H	Insured Vehicle No :	SKW4087Y
Date of Loss:	23/07/2021	Nature of Claim:	TP
		Claim No:	2888419031SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJM1517H		
Make & Model:	HONDA FIT, 1.3 G (A)	Engine No:	L13A4135292
Reg. Date:	22/12/2008 (Man. Year: 2008)	Chassis No:	GE61122764
Colour:	Purple	Odometer:	177873 km
Engine Capacity:	1339 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	185/60 R14	Rear Tyre Size:	185/60 R14
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,429.68	791.12	1,638.56	67.44
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,640.00	860.00	780.00	47.56
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	4,069.68	1,651.12	2,418.56	59.43
Approved Total (Overridden) (S\$)		1,300.00		

(S\$)	4,069.68	1,300.00	2,769.68	68.06
+ GST 7.00/7.00% (S\$)	284.88	91.00	193.88	68.06
Nett Amount (S\$)	4,354.56	1,391.00	2,963.56	68.06
+ Car Rental (2.0 x S\$100.00/day + 7.00% GST) (S\$)		214.00		
Nett Liability (S\$)		1,605.00		

INSPECTION

Date of Assignment: 27/07/2021

Date Inspected: 27/07/2021

Estimated Period of Repair: 2.0 days

Inspected At:

Tan Lim Motor Pte Ltd (Defu)
1 Defu Lane 6
Singapore 539365

Adjuster: MARCUS CHUA**Manager:** Jaslin Kok Chin Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILGATE LID LOCK TOP	Not Necessary	242.30 FL	*- FL
2	1		*TAILGATE LID WEATHERSTRIP	Not Necessary	129.20 FL	*- FL
3	1		*TAILGATE LID FIT BADGE	Not Necessary	29.10 FL	*- FL
4	1		*REAR BUMPER (SPORT)	Distorted	936.70 FL	*936.70 FL
5	1		*REAR BUMPER TOW HOOK COVER	Not Necessary	28.80 FL	*- FL
6	1		*REAR BUMPER SIDE RETAINER O/S	Cracked	16.20 FL	*16.20 FL
7	8		*REAR BUMPER FASTENER CLIPS	Necessary	36.00 FL	*36.00 FL
8	2		*REAR BUMPER TOP BRACKET	Not Necessary	19.60 FL	*- FL
9	2		*REAR BUMPER END SPLASHIELD COVER	Not Necessary	51.60 FL	*- FL
10	1		*REAR END PANEL	Repair	480.00 FL	*- FL
11	1		*REAR END PANEL INNER TRIM	Not Necessary	183.90 FL	*- FL
12	4		*REAR END PANEL INNER TRIM CLIPS	Not Necessary	18.00 FL	*- FL
13	1		*REAR LAMP O/S	Not Necessary	390.70 FL	*- FL
14	1		*REAR LAMP PANEL O/S	Repair	125.00 FL	*- FL
15	1		*SET REAR BUMPER PARKING SENSOR	Not Necessary	280.00 FS	*- FS
F=Franchise part. S=SpcNett. L=ListItemDisc.						
Sub Total (\$\$)					2,967.10	988.90
- List Item Discount on L Items 20.00/20.00% (\$\$)					537.42	197.78
Total Parts (\$\$)					2,429.68	791.12

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO CHECK ELECTRICAL LIGHTING CONCERNED	New	50.00	20.00
2	TO RUST-PROOFING OF THE AFFECTED AREAS	New	60.00	0.00
3	TO REINSTALL OF REAR BUMPER PARKING SENSOR	New	80.00	40.00
4	PANEL BEATING ,KNOCKING AND STRAIGHTEN THE NECESSARY PORTION ,REMOVE AND RENEWAL OF PARTS ,ADJUST AND REALIGN THE SAME	New	700.00	300.00
5	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	New	750.00	500.00
Gross Labour Cost (\$)			1,640.00	860.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >