

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CS3/AIG21007961/VUF3E2

**Date:** 02/08/2021

### REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2070017408  
**Claimant Vehicle No :** SMJ631Y **Insured Vehicle No :** SMS3016G  
Date of Loss: 26/07/2021 Nature of Claim: TP Claim No: 1445153367SG

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SMJ631Y**  
Make & Model: TOYOTA SIENTA, 1.5 (A) Engine No: 2NRX426972  
Reg. Date: 21/02/2019 (Man. Year: 2019) Chassis No: MHFZ28H3000062288  
Colour: Silver Odometer: 147670 km  
Engine Capacity: 1496 cc  
Market Value/New Car Price: N/A  
Sum Insured (S\$): **Market Value/New Car Price**

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size: 185/60 R15 Rear Tyre Size: 185/60 R15  
Front Left Side: Dunlop 6 mm Rear Left Side: Dunlop 6 mm  
Front Right Side: Dunlop 6 mm Rear Right Side: Dunlop 6 mm

*The above values represent the remaining tyre treads depth*

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Nett Amount (S\$)</b>	<b>0.00</b>	<b>0.00</b>	<b>0.00</b>	

### INSPECTION

Date of Assignment: 27/07/2021  
Date Inspected: 27/07/2021 Inspected At: Garage 13 Pte Ltd (HQ)  
8 Kaki Bukit Ave 4, Premier @ Kaki Bukit, #03-46  
Singapore 415875  
Estimated Period of Repair: 5.0 days

**Adjuster:** Thevan Thomas Karthikesavan

**Manager:** Tan Hui Zhen

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

MARKET VALUE: \$69,000.00 (EST)

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Dented	0.00 F	*- F
2	2		*REAR BUMPER UPPER	Distorted	0.00 F	*- F
3	1		*REAR BUMPER CLIPS	Necessary	0.00 F	*- F
4	1		*REAR BUMPER BRACKET	Necessary	0.00 F	*- F
5	1		*REAR BUMPER SIDE RETAINER	Distorted	0.00 F	*- F
6	1		*REAR BUMPER REFLECTOR	Cracked	0.00 F	*- F
7	1		*REVERSE SENSOR	Cut	0.00 F	*- F
8	1		*REAR END PANEL	Repair	0.00 F	*- F
9	1		*TAILGATE	Dented	0.00 F	*- F
10	3		*TAILGATE EMBLEM	Necessary	0.00 F	*- F
11	1		*TAILGATE GARNISH	Scratched	0.00 F	*- F
12	1		*TAILGATE LAMP LH	Cracked	0.00 F	*- F
13	1		*TAILGATE GLASS SEALANT	Necessary	0.00 F	*- F
14	1		*TAILGATE LOCK	Bent	0.00 F	*- F
15	1		*TAILGATE RUBBER	Cut	0.00 F	*- F
16	1		*BUMPER CENTRE REFLECTOR	Cracked	0.00 F	*- F
17	1		*REFLECTOR COVER	Scratched	0.00 F	*- F
F=Franchise part.						
					<b>Total Parts (S\$)</b>	<b>0.00 0.00</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.
-----------------------------------------------

< END OF ESTIMATES >