

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CC4/GRB21007962/R1ES3Q2  
**Date:** 18/11/2021REFERENCE

Handling Insurer:	India International Insurance Pte Ltd	Policy No:	D21MFL0000447
<b>Claimant Vehicle No :</b>	SKK6335G	<b>Insured Vehicle No :</b>	SLM4404G
Date of Loss:	24/07/2021	Nature of Claim:	TP
		Claim No:	MFL2021D0003194

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>SKK6335G</b>		
Make & Model:	MERCEDES-BENZ S450L, 3.0 (A)	Engine No:	25693030309060
Reg. Date:	16/06/2021 (Man. Year: 2021)	Chassis No:	W1K2231612A037215
Colour:	Black	Odometer:	3864 km
Engine Capacity:	2999 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	285/45 R19	Rear Tyre Size:	285/45 R19
Front Left Side:	Pirelli 6 mm	Rear Left Side:	Pirelli 6 mm
Front Right Side:	Pirelli 6 mm	Rear Right Side:	Pirelli 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	5,522.56	3,289.88	2,232.68	40.43
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,760.00	2,160.00	600.00	21.74
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>8,282.56</b>	<b>5,449.88</b>	<b>2,832.68</b>	<b>34.20</b>
<b>+ GST 7.00/7.00% (S\$)</b>	<b>579.78</b>	<b>381.49</b>	<b>198.29</b>	<b>34.20</b>

<b>Nett Amount (S\$)</b>	<b>8,862.34</b>	<b>5,831.37</b>	<b>3,030.97</b>	<b>34.20</b>
<b>+ Car Rental (3.0 x S\$180.00/day) (S\$)</b>		540.00		
<b>Nett Liability (S\$)</b>		<b>6,371.37</b>		

INSPECTION

Date of Assignment: 27/07/2021

Date Inspected: 11/08/2021

Estimated Period of Repair: 3.0 days

Inspected At:

188 PANDAN LOOP

Repairer: Cycle &amp; Carriage Automotive Pte Ltd (Pandan Gardens)

**Adjuster:** MOHD RASUL**Manager:** Asher Sng Rong Yi

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 02 Nov 2021)
<b>Parts:</b>	143	MERCEDES-BENZ S450L 3.0 (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SKK6335G)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	2,083.13 FS	*2,083.13 FS
2	1		*REAR BOTTOM PANEL	Serviceable	684.67 FS	*- FS
3	1		*RH/R BOTTOM PANEL CHROME	Serviceable	213.36 FS	*- FS
4	1		*LH/R BOTTOM PANEL CHROME	Serviceable	213.36 FS	*- FS
5	1		*CT/R BOTTOM PANEL TRIM	Serviceable	250.81 FS	*- FS
6	1		*CT/R BOTTOM PANEL CHROME	Serviceable	481.11 FS	*- FS
7	1		*RH/R BASIC MOUNTING FOR BUMPER	Cracked	144.63 FS	*144.63 FS
8	1		*RH/R BUMPER GARNISH	Necessary	112.27 FS	*112.27 FS
9	1		*LH/R BUMPER GARNISH	Necessary	112.27 FS	*112.27 FS
10	1		*RH/R EXHAUST TAIL PIPE TRIM	Serviceable	325.10 FS	*- FS
11	1		*RH/R EXHAUST TAIL PIPE BRACKET	Serviceable	64.27 FS	*- FS
12	1		*RH/R TAIL LAMP	Scratched	796.62 FS	*796.62 FS
13	1		*RH/R BOTTOM EXHAUST SHIELDING	Bent	40.96 FS	*40.96 FS
F=Franchise part. S=SpcNett.						
					<b>Total Parts (\$\$)</b>	<b>5,522.56</b>
						<b>3,289.88</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	USE XENTRY TO CHECK CONTROL UNITS & RESET MEMORY TO STANDARD SETTINGS	New	480.00	480.00
2	CHECK REAR LIGHTING SYSTEM AND CONDUCT WATER TEST FOR ANY LEAKAGE	New	120.00	120.00
3	REMOVE & REPLACE REAR BUMPER & REMOVE REAR SUPPORT ASSY COMPONENTS & REFINISH	New	1,440.00	960.00
4	RESPRAY REAR BUMPER	New	720.00	600.00
<b>Gross Labour Cost (\$\$)</b>			<b>2,760.00</b>	<b>2,160.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >