

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/AIG21007963/UGS3Q2
Date: 15/10/2021

REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2000001627-01
Claimant Vehicle No :	SKV2124S	Insured Vehicle No :	YQ196H
Date of Loss:	26/07/2021	Nature of Claim:	TP
		Claim No:	6349185163SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKV2124S		
Make & Model:	TOYOTA COROLLA ALTIS, 1.6 CVT (A)	Engine No:	3ZZ4892053
Reg. Date:	21/05/2009 (Man. Year: 2009)	Chassis No:	MR053ZEE106146160
Colour:	Grey	Odometer:	300913 km
Engine Capacity:	1598 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	185/65 R15	Rear Tyre Size:	185/65 R15
Front Left Side:	Dunlop 7 mm	Rear Left Side:	Dunlop 7 mm
Front Right Side:	Dunlop 7 mm	Rear Right Side:	Dunlop 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	981.32	423.82	557.50	56.81
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,250.00	750.00	500.00	40.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	2,231.32	1,173.82	1,057.50	47.39
Approved Total (Overridden) (S\$)		800.00		

(S\$)	2,231.32	800.00	1,431.32	64.15
+ GST 7.00/7.00% (S\$)	156.19	56.00	100.19	64.15
Nett Amount (S\$)	2,387.51	856.00	1,531.51	64.15
+ Car Rental (3.0 x S\$100.00/day) (S\$)		300.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		1,158.00		

INSPECTION

Date of Assignment: 11/08/2021

Date Inspected: 11/08/2021

Estimated Period of Repair: 2.0 days

Inspected At:

Hock Wah Motor Workshop Pte Ltd (Bedok)
 Blk 3011, Bedok Industrial Park E., #01-2008/2010/2012
 Singapore 489977

Adjuster: MARCUS CHUA**Manager:** Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

Recommended Parts

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	LABOUR TO REMOVE & REFIT NECESSARY PARTS	New	500.00	300.00
2	SPRAY PAINT ON THE AFFECTED AREAS	New	500.00	400.00
3	ANTI-RUST COATING	New	100.00	0.00
4	TO REMOVE & REFIT REVERSE SENSOR	New	150.00	50.00
Gross Labour Cost (S\$)			1,250.00	750.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >