

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CC4/AIG21007969/TGA3Q2**Date:** 18/04/2022REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1900125465
<b>Claimant Vehicle No :</b>	SHC3122B	<b>Insured Vehicle No :</b>	GBJ7009D
Date of Loss:	26/07/2021	Nature of Claim:	TP
		Claim No:	6828386379SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>SHC3122B</b>	Engine No:	G4LEJU192201
Make & Model:	HYUNDAI AE IONIQ HEV DCT, 1.6 (A)	Chassis No:	KMHC851CVKU141515
Reg. Date:	12/03/2019 (Man. Year: 2018)	Odometer:	171589 km
Colour:	Blue		
Engine Capacity:	1580 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	West Lake 6 mm	Rear Left Side:	West Lake 6 mm
Front Right Side:	West Lake 6 mm	Rear Right Side:	West Lake 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	2,110.64	557.12	1,553.52	73.60
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,630.00	1,025.00	605.00	37.12
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>3,740.64</b>	<b>1,582.12</b>	<b>2,158.52</b>	<b>57.70</b>
<b>+ GST 7.00/7.00% (S\$)</b>	261.84	110.75	151.09	57.70
<b>Nett Amount (S\$)</b>	<b>4,002.48</b>	<b>1,692.87</b>	<b>2,309.61</b>	<b>57.70</b>
<b>+ Loss of Use (3.0 x S\$50.00/day) (S\$)</b>		150.00		
<b>+ Car Rental (3.0 x S\$125.19/day) (S\$)</b>		375.57		
<b>+ Doc/Search Fee (S\$)</b>		2.00		
<b>Nett Liability (S\$)</b>		<b>2,220.44</b>		

INSPECTION

Date of Assignment:	27/07/2021	
Date Inspected:	27/07/2021	Inspected At: ComfortDelGro Engineering Pte Ltd (Loyang) 59 Loyang Drive Singapore 508969
Estimated Period of Repair:	3.0 days	

**Adjuster:** MOHD TAUFIKH BIN HAMID**Manager:** Chong Pui Lin

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR RH FENDER	Repair	1,768.30 FL	*- FL
2	1		*REAR FENDER SHIELD RH	Not Necessary	173.60 FL	*- FL
3	1		*WHEEL CAP RH	Cut	346.40 FL	*346.40 FL
4	1		*REAR DOOR ADVERTISEMENT	Cut	100.00 FS	*100.00 FS
5	1		*REAR FENDER ADVERTISEMENT	Cut	100.00 FS	*100.00 FS
6	1		*REAR DOOR COMFORT APP	Necessary	80.00 FS	*80.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	2,568.30	626.40
- List Item Discount on L Items 20.00/20.00% (\$)	457.66	69.28
Total Parts (\$)	2,110.64	557.12

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	PANEL BEATING	New	850.00	525.00
2	SPRAY PAINTING CHARGE	New	600.00	500.00
3	TUFF COAT	New	90.00	0.00
4	REMOVE/REFIX REAR UPHOLSTERY	New	90.00	0.00
<b>Gross Labour Cost (\$\$)</b>			<b>1,630.00</b>	<b>1,025.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >