

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLL 8977Z

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	SUNDRIES (SN)	NECESSARY	60.00	30.00
1	HEADLAMP ASSY, RH (SN)	NOT NECESSARY	613.50	-
1	HEADLAMP ASSY, LH (SN)	CRACKED	613.50	613.50
1	WHEEL, DISC (SN)	SCRATCHED	1,962.40	1,962.40
1	ORNAMENT SUB-ASSY, W (SN)	NOT NECESSARY	39.80	-
1	GRILLE, RADIATOR, LW (SN)	NOT NECESSARY	290.20	-
1	COVER, FR BUMPER, L (SN)	DEFORMED	500.80	500.80
1	RETAINER, FR BUMPER (SN)	NOT NECESSARY	69.40	-
1	RETAINER, FR BUMPER (SN)	NECESSARY	69.40	69.40
1	REINFORCEMENT SUB-AS (SN)	NOT NECESSARY	403.70	-
1	GRILLE SUB-ASSY, RAD (SN)	NOT NECESSARY	206.30	-
1	EMBLEM, SYMBOL (SN)	NOT NECESSARY	58.90	-
1	PANEL, FR FENDER, LH (SN)	BENT	712.10	712.10
1	LINER, FR FENDER, LH (SN)	CUT	306.40	306.40
1	HINGE ASSY, HOOD, RH (SN)	NOT NECESSARY	59.40	-
1	HINGE ASSY, HOOD, LH (SN)	NOT NECESSARY	59.40	-
1	INLET, AIR CLEANER (SN)	NOT NECESSARY	70.50	-
			6,095.70	4,194.60
	<u>LABOUR</u>			
	TO RESET AND REPROGRAMME.		180.00	180.00
	TO CONDUCT WHEEL ALIGNMENT CHECK.		180.00	180.00
	TO TRANSFER TYRE TO NEW SPORT-RIM AND BALANCE.		72.00	72.00
	TO CHECK WIRING AND LIGHTING. TO FOCUS HEADLAMP.		122.40	122.40
	TO REPLACE FRONT LH SIDE ACCIDENT DAMAGE PARTS. STRAIGHTEN / REALIGN ALL OTHER AFFECTED AREAS.		2,160.00	1,800.00
	TO SPRAY PAINT ON FRONT ACCIDENT AFFECTED AREA.		2,950.00	2,360.00
			5,664.40	4,714.40
	GRAND TOTAL		11,760.10	8,909.00

Report Ref No. CS/SMR21007971/R1uf3e2



Page No.:2 of 2

RECOMMENDED COST OF REPAIRS 8,909.00

Report Ref No. CS/SMR21007971/R1uf3e2

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

7

ANG BRYAN TANI

Automotive Assessor / Investigator