

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI21007972/VTCE2

Date: 25/08/2021

REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMB1SNW00006552102
Claimant Vehicle No : SMW174G **Insured Vehicle No :** CB7182R
Date of Loss: 21/07/2021 Nature of Claim: TP Claim No: SNM21D204045/C2/IRENE

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SMW174G**
Make & Model: MAZDA 2, 1.5 (A) Engine No: P520605135
Reg. Date: 29/10/2020 (Man. Year: 2019) Chassis No: JM6DJ2HAA01300532
Colour: Red Odometer: 4905 km
Engine Capacity: 1496 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 185/65 R15 Rear Tyre Size: 185/65 R15
Front Left Side: Bridgestone 6 mm Rear Left Side: Bridgestone 6 mm
Front Right Side: Bridgestone 6 mm Rear Right Side: Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,500.50	2,358.00	1,142.50	32.64
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,660.00	3,710.00	1,950.00	34.45
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	9,160.50	6,068.00	3,092.50	33.76
+ GST 7.00/7.00% (S\$)	641.24	424.76	216.48	33.76
Nett Amount (S\$)	9,801.74	6,492.76	3,308.98	33.76

INSPECTION

Date of Assignment: 27/07/2021
Date Inspected: 28/07/2021 Inspected At: Trans Eurokars Pte Ltd
Singapore 408605
Estimated Period of Repair: 5.0 days

Adjuster: Thevan Thomas Karthikesavan

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 25 Aug 2021)
Parts:	143	MAZDA 2 1.5 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMW174G)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Distorted	893.40 F	*893.40 F
2	1		*BRACKET CENTER RR BUMPER	Repair	5.40 F	*- F
3	2		*STAY RR BUMPER	Repair	22.80 F	*- F
4	1		*RETAINER LH	Distorted	27.20 F	*27.20 F
5	1		*RETAINER RH	Distorted	27.20 F	*27.20 F
6	7		*FASTENER	Distorted	21.00 F	*21.00 F
7	1		*SPLASH SHIELD RR RH	Repair	62.30 F	*- F
8	1		*SPLASH SHIELD RR LH	Repair	62.30 F	*- F
9	4		*GROMMET, SCREW	Necessary	10.80 F	*10.80 F
10	1		*BODY, LIFT GATE	Dented	956.70 F	*956.70 F
11	1		*WTHSTP PARTING SEAL	Necessary	58.10 F	*58.10 F
12	1		*TRIM, LIFTGATE-LOWER	Cut	93.50 F	*93.50 F
13	9		*FASTENER	Necessary	27.00 F	*27.00 F
14	1		*RECESS, LIFT GATE	Repair	15.00 F	*- F
15	2		*CLIP, TRIM	Necessary	6.00 F	*6.00 F
16	2		*COVER, HOLE TRUNK LID	Repair	5.00 F	*- F
17	2		*VALVE, ONEWAY	Repair	24.00 F	*- F
18	1		*SWITCH, OPEN	Repair	89.70 F	*- F
19	2		*HINGE, LIFT GATE	Repair	68.20 F	*- F
20	1		*MASCOT, REAR	Repair	61.20 F	*- F
21	1		*ORNAMENT, MAZDA 2	Necessary	58.30 F	*58.30 F
22	1		*ORNAMENT SKYACTIV	Necessary	68.00 F	*68.00 F
23	4		*CLIP, GARNISH	Necessary	20.80 F	*20.80 F
24	1		*SPOILER LHR SIDE	Repair	178.80 F	*- F
25	1		*WIPER MTR REAR	Repair	333.00 F	*- F
26	4		*SPACER	Repair	51.20 F	*- F
27	2		*FASTENER	Repair	16.40 F	*- F
28	2		*FASTENER	Repair	5.60 F	*- F
29	2		*LAMP, LICENSE	Repair	111.60 F	*- F
30	1		*SUNDRIES	Necessary	50.00 FS	*20.00 FS
31	1		*NUMBER PLATE	Necessary	70.00 FS	*70.00 FS
					Total Parts (S\$)	3,500.50
						2,358.00

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	REPLACE REAR BUMPER, TAILGATE. 167320	New	1,980.00	1,320.00
2	SPRAY REAR BUMPER, TAILGATE	New	1,890.00	1,260.00
3	TO REMOVE & REFIT THE WINDSCREEN GLASS AND CONDUCT WATER LEAK TEST	New	560.00	560.00
4	TO SUPPLY SEALER ON THE WINDSCREEN GLASS	New	120.00	120.00
5	TO TRANSFER REVERSE SENSORS	New	660.00	150.00
6	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING	New	200.00	120.00
7	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS	New	250.00	180.00
Gross Labour Cost (\$)			5,660.00	3,710.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >