

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG21007976/TGS3Q2**Date:** 14/02/2022REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1800079121-03
Claimant Vehicle No :	YN7104T	Insured Vehicle No :	GBF2072Z
Date of Loss:	23/07/2021	Nature of Claim:	TP
		Claim No:	5537998709SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	YN7104T		
Make & Model:	mitsubishi canter, 3.0 D FE83 (M)	Engine No:	4P10B38151
Reg. Date:	18/12/2014 (Man. Year: 2014)	Chassis No:	FEB21EA01051
Colour:	White	Odometer:	362616 km
Engine Capacity:	2998 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/85 R15	Rear Tyre Size:	195/85 R15 (D)
Front Left Side:	Kenda 6 mm	Rear Left Side:	Kenda 6/6 mm
Front Right Side:	Kenda 6 mm	Rear Right Side:	Kenda 6/6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	12,471.50	8,731.50	3,740.00	29.99
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,300.00	1,660.00	640.00	27.83
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	14,771.50	10,391.50	4,380.00	29.65
Approved Total (Overridden) (S\$)		8,300.00		
(S\$)	14,771.50	8,300.00	6,471.50	43.81
+ GST 7.00/7.00% (S\$)	1,034.01	581.00	453.01	43.81
Nett Amount (S\$)	15,805.51	8,881.00	6,924.51	43.81
+ Loss of Use (9.0 x S\$60.00/day) (S\$)		540.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		9,428.45		
Global Sum Settlement (S\$)		9,400.00		

INSPECTION

Date of Assignment:	27/07/2021	
Date Inspected:	28/07/2021	Inspected At: Em-1 Auto Pte Ltd (HQ) Blk 8 Sin Ming Industrial Estate Sector C, #01-68 Singapore 575643
Estimated Period of Repair:	7.0 days	

Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR NUMBER PLATE LAMP	Cracked	92.00 FL	*92.00 FL
2	2		*TAILLAMP ASSY	Cracked	586.00 FL	*586.00 FL
3	1		*TAILLAMP ASSY BASE LH	Cracked	152.00 FL	*152.00 FL
4	1		*SPARE TYRE CARRIER	Missing	352.00 FL	*352.00 FL
5	1		*TAILGATE DOOR ASSY FIBER	N/S Cracked / O/SNot Necessary	3,600.00 FS	*1,800.00 FS
6	1		*TAILGATE DOOR HINGES BOTTOM (STAINLESS)	N/S Bent / O/SNot Necessary	360.00 FS	*180.00 FS
7	2		*TAILGATE DOOR OPENER BAR (STAINLESS)	Bent	1,000.00 FS	*700.00 FS
8	2		*TAILGATE DOOR OPENER BAR HINGE (STAINLESS)	Not Necessary	300.00 FS	*- FS
9	1		*TAILGATE DOOR OPENER BAR CATCH	N/S Bent / O/S Not Necessary	300.00 FS	*150.00 FS
10	1		*TAILGATE DOOR SAFE LOCK CAR LH	Bent	320.00 FS	*320.00 FS
11	1		*REAR STEP CROSS MEMBER	Bent	380.00 FS	*380.00 FS
12	4		*REAR PROTECTOR BIG STOPPER	Torn	600.00 FS	*600.00 FS
13	1		*REAR NUMBWER PLATE	Not Necessary	30.00 FS	*- FS
14	1		*REAR BUMPER	Bent	1,000.00 FS	*1,000.00 FS
15	2		*REAR BUMPER BRACKET	Bent	500.00 FS	*500.00 FS
16	1		*REAR TYRE	Not Necessary	380.00 FS	*- FS
17	2		*REAR DOOR STICKER WITH COMPANY LOGO	Necessary	1,000.00 FS	*800.00 FS
18	1		*60KM STICKER	Necessary	15.00 FS	*15.00 FS
19	1		*REAR REFRIGERATOR SURROUND FRAME (STAINLESS)	Bent	1,800.00 FS	*1,400.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	12,767.00	9,027.00
- List Item Discount on L Items 25.00/25.00% (\$)	295.50	295.50
Total Parts (\$)	12,471.50	8,731.50

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING	New	1,200.00	800.00
2	SPRAY PAINTING CHARGE	New	1,000.00	800.00
3	ANTI RUST	New	60.00	30.00
4	CHECK WIRING	New	40.00	30.00
Gross Labour Cost (\$\$)			2,300.00	1,660.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >