

Note: This document has not been finalised.**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Adeline Chng Pei Wen

Date: 10 Aug 2021

Preliminary Advice

Insured Vehicle No	: YN6990H	Accident Date	: 26/07/2021
TP Vehicle No	: SDB8381P	Assignment Date	: 27/07/2021
Make	: BMW 318i	Est. Duration of Repair	: 3
Date of Inspection	: 29/07/2021		
Inspection At	: TICK HAI MOTOR & WELDING SERVICES - KAKI BUKIT (HQ) BLK 1 KAKI BUKIT AVE 6, #01-54 AUTOBAY @ KAKI BUKIT SINGAPORE 417883		

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	7,541.32
Revised Amount	:S\$	2,406.79
Check Items (Estimated)	:S\$	0.00
Total	:S\$	2,406.79
 Lump Sum Repair	 :S\$	 1,900.00

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

- () The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- () Other comments :