

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/AIG21007992/APA3Q2**Date:** 14/02/2022REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2070114351
Claimant Vehicle No :	SKX9035J	Insured Vehicle No :	SJZ6727S
Date of Loss:	22/07/2021	Nature of Claim:	TP
		Claim No:	6582315683SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKX9035J	Engine No:	PE20712384
Make & Model:	MAZDA 6, 2.0 4-DOOR SEDAN 2.0L SP.6EAT (A)	Chassis No:	JM6GJ1072G0224443
Reg. Date:	31/12/2015 (Man. Year: 2015)	Odometer:	77174 km
Colour:	White		
Engine Capacity:	1998 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/45 R18	Rear Tyre Size:	225/45 R18
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	17,516.20	1,990.80	15,525.40	88.63
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,630.00	920.00	3,710.00	80.13
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	22,146.20	2,910.80	19,235.40	86.86
Approved Total (Overridden) (S\$)		2,300.00		
(S\$)	22,146.20	2,300.00	19,846.20	89.61
+ GST 7.00/7.00% (S\$)	1,550.23	161.00	1,389.23	89.61
Nett Amount (S\$)	23,696.43	2,461.00	21,235.43	89.61
+ Car Rental (4.0 x S\$140.00/day) (S\$)		560.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		3,028.45		
Global Sum Settlement (S\$)		3,000.00		

INSPECTION

Date of Assignment:	27/07/2021		
Date Inspected:	27/07/2021	Inspected At:	Xin Hua Workshop Pte Ltd (HQ) 23 Kaki Bukit Ave 4 #04-01 Singapore 415933
Estimated Period of Repair:	4.0 days		

Adjuster: ADRIAN LING**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BOOT LID	Repair	1,165.30 F	*- FL
2	1		*BOOT LID BADGE	Necessary	95.60 F	*95.60 FL
3	1		*BOOT LID EMBLEM MAZDA	Necessary	58.00 F	*58.00 FL
4	1		*BOOT LID OUTER CHROME MOULDING	Not Necessary	312.60 F	*- FL
5	2		*BOOT LID SIDE CHROME MOULDING	Not Necessary	290.00 F	*- FL
6	1		*BOOT LID NO.PLATE LAMP GARNISH	Not Necessary	142.50 F	*- FL
7	2		*BOOT LID LAMPS	Not Necessary	1,464.00 F	*- FL
8	2		*BOOT LID LAMPS INNER SEALER	Not Necessary	76.00 F	*- FL
9	2		*SET BOOT LID LAMP CLIPS	Not Necessary	60.00 F	*- FL
10	1		*BOOT LID INNER LOCK	Not Necessary	245.60 F	*- FL
11	1		*BOOT LID LOCK CATCH	Not Necessary	48.00 F	*- FL
12	1		*BOOT LID WEATHERSTRIP	Cut	198.70 F	*198.70 FL
13	1		*BOOT LID POCKET HANDLE	Not Necessary	85.60 F	*- FL
14	1		*BOOT LID INSULATOR	Not Necessary	385.00 F	*- FL
15	1		*SET BOOT LID INSULATOR CLIP	Not Necessary	40.00 F	*- FL
16	2		*BOOT LID HINGE	Not Necessary	417.00 F	*- FL
17	1		*REAR BUMPER	Deformed	1,245.60 F	*1,245.60 FL
18	2		*REAR BUMPER SIDE RETAINERS	Necessary	170.40 F	*170.40 FL
19	1		*SET REAR BUMPER CLIPS	Necessary	50.00 F	*30.00 FL
20	1		*REAR BUMPER REINFORCEMENT	Not Necessary	548.90 F	*- FL
21	2		*REAR BUMPER REFLECTORS	Not Necessary	151.20 F	*- FL
22	2		*REAR BUMPER TOW COVER	Missing	131.60 F	*131.60 FL
23	2		*TAILLAMPS	Not Necessary	3,032.00 F	*- FL
24	2		*TAILLAMPS INNER SEALER	Not Necessary	76.00 F	*- FL
25	2		*SET TAILLAMPS CLIPS	Not Necessary	50.00 F	*- FL
26	1		*END PANEL	Repair	667.00 F	*- FL
27	1		*END PANEL TOP TRIM	Deformed	198.60 F	*198.60 FL
28	1		*SET END PANEL TOP TRIM CLIPS	Necessary	30.00 F	*10.00 FL
29	1		*REAR KEY ANTENNA SENSOR	Not Necessary	198.00 F	*- FL
30	1		*SPARE TYRE PANEL TOP BOARD W/CLOTH	Not Necessary	487.00 F	*- FL
31	1		*SPARE TYRE PANEL TOP SIDE SPONGE LH	Not Necessary	292.00 F	*- FL
32	1		*SPARE TYRE PANEL TOP SIDE SPONGE RH	Not Necessary	204.00 F	*- FL
33	2		*SPARE TYRE PANEL TOP SIDE TRAY	Not Necessary	578.00 F	*- FL
34	2		*REAR FENDER INNER TRIM	Not Necessary	852.00 F	*- FL
35	2		*SET REAR FENDER INNER TRIM CLIPS	Not Necessary	60.00 F	*- FL
36	1		*REAR EXHAUST SILENCER	Not Necessary	1,745.00 F	*- FL
37	2		*REAR EXHAUST MOUNTINGS	Not Necessary	78.00 F	*- FL
38	1		*REAR EXHAUST GASKET	Not Necessary	46.00 F	*- FL
39	1		*REAR HEAT PLATE	Not Necessary	91.00 F	*- FL
40	1		*REAR NUMBER PLATE WITH COVER	Not Necessary	70.00 FS	*- FS
41	1		*SET REVERSE SENSORS (4 PCS)	Damaged	450.00 FS	*280.00 FS
42	4		*REVERSE CAMERA	Not Necessary	450.00 FS	*- FS
43	1		*SET BODY PANEL JOINT SEALANT	Not Necessary	120.00 FS	*- FS
44	2		*REAR EXHAUST CHROME PIPE	Not Necessary	360.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	17,516.20	2,418.50
- List Item Discount on L Items 0.00/20.00% (\$\$)	0.00	427.70
Total Parts (\$\$)	17,516.20	1,990.80

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING	New	2,000.00	400.00
2	SPRAY PAINTING	New	2,000.00	400.00
3	CHECK WIRING ON TAILAMP	New	120.00	30.00
4	ANTI RUST	New	180.00	40.00
5	REMOVE AND INSTALL INTERIOR UPHOLSTERY	New	120.00	0.00
6	REMOVE AND INSTALL REVERSE SENSOR	New	90.00	50.00
7	REMOVE AND INSTALL REAR EXHAUST SILENCER	New	120.00	0.00
Gross Labour Cost (\$\$)			4,630.00	920.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >