

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI21007993/EUCN2**Date:** 22/09/2021**REFERENCE**

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSNW00061662102		
Claimant Vehicle No :	GBJ235M	Insured Vehicle No :	GBH4601Z		
Date of Loss:	27/07/2021	Nature of Claim:	TP	Claim No:	SNM21D204141/C02/TANCHC

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GBJ235M		
Make & Model:	NISSAN NV350, 2.5 PANEL VAN 5MT 5DR (M)	Engine No:	YD25000231B
Reg. Date:	30/11/2018 (Man. Year: 2017)	Chassis No:	JN1MC2E26Z0009487
Colour:	Silver	Odometer:	82890 km
Engine Capacity:	2488 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195R15C	Rear Tyre Size:	195R15C
Front Left Side:	Dunlop 4 mm	Rear Left Side:	Dunlop 4 mm
Front Right Side:	Dunlop 4 mm	Rear Right Side:	Dunlop 4 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,862.58	1,286.91	2,575.67	66.68
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,280.00	760.00	1,520.00	66.67
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (\$\$)	6,142.58	2,046.91	4,095.67	66.68
+ GST 7.00/7.00% (\$\$)	429.98	143.28	286.70	66.68
Nett Amount (\$\$)	6,572.56	2,190.19	4,382.37	66.68

INSPECTION

Date of Assignment:	12/08/2021	
Date Inspected:	12/08/2021 Inspected At:	Efficient Motor & Engineering Works Pte Ltd (HQ) 56 Loyang Way #06-07, Loyang Enterprise Building Singapore 508775
Estimated Period of Repair:	3.0 days	

Adjuster: CHEN TSUE YEE**Manager:** Tan Hui Zhen*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 22 Sep 2021)	
Parts:	N/A	NISSAN NV350 2.5 PANEL VAN 5MT 5DR (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBJ235M)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Broken	571.90 FL	*571.90 FL
2	1		*FRONT BUMPER SIDE RETAINER	O/s Broken	294.00 FL	*147.00 FL
3	1		*FRONT BUMPER STAY (BKT)	Not Necessary	104.70 FL	*- FL
4	1		*FRONT FOG LAMP GARNISH	Not Necessary	130.10 FL	*- FL
5	1		*FRONT FOG LAMP	Not Necessary	323.70 FL	*- FL
6	1		*FRONT BUMPER BEAM	Not Necessary	235.00 FL	*- FL
7	1		*FRONT FOG LAMP BRACKET	Not Necessary	87.10 FL	*- FL
8	1		*HEADLAMP ASSY	Broken	403.00 FL	*403.00 FL
9	1		*FRONT GRILLE	Not Necessary	455.00 FL	*- FL
10	1		*FRONT GRILLE LOGO	Not Necessary	79.90 FL	*- FL
11	1		*FRONT STEP PANEL GARNISH	Broken	108.00 FL	*108.00 FL
12	1		*FRONT WHEELHOUSE SPLASH GUARD	Not Necessary	151.10 FL	*- FL
13	1		*OIL COOLER	Not Necessary	700.30 FL	*- FL
14	1		*OIL COOLER COWLING WITH BRACKET	Not Necessary	155.30 FL	*- FL
15	1		*AIR GUIDE LOWER	Not Necessary	137.10 FL	*- FL
16	1		*SET FRONT BUMPER CLIPS	Necessary	50.00 FS	*30.00 FS
17	1		*COMPANY REGISTRATION STICKER	Necessary	30.00 FS	*30.00 FS
18	1		*FRONT GRILLE CLIPS	Not Necessary	30.00 FS	*- FS
19	1		*WHEELHOUSE UNDERSHIELD CLIPS	Not Necessary	30.00 FS	*- FS
20	1		*BIZSAFE STICKER & DOOR STICKER	Necessary	180.00 FS	*120.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	4,256.20	1,409.90
- List Item Discount on L Items 10.00/10.00% (\$)	393.62	122.99
Total Parts (\$)	3,862.58	1,286.91

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CUT,WELD & REPAIR DAMAGED FRONT PORTION AND FRONT DOOR	New	1,000.00	200.00
2	TO APPLY ANTI RUST COAT AND TUFF KOTE AFFECTED AREAS	New	80.00	30.00
3	TO CONDUCT FRONT WHEEL ALIGNMENT	New	120.00	0.00
4	TO CHECK AND RECTIFY LIGHTING & WIRING HARNESS	New	80.00	30.00
5	TO SPRAY PAINTING FRONT BUMPER & FRONT LEFT DOOR & AFFECTED PARTS	New	1,000.00	500.00
Gross Labour Cost (\$)			2,280.00	760.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >