

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG21007997/ETF3E2

Date: 26/08/2021

REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	29147838ATM
Claimant Vehicle No :	CB7802K	Insured Vehicle No :	SMG5817L
Date of Loss:	26/07/2021	Nature of Claim:	TP
		Claim No:	637218

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	CB7802K	Engine No:	1KD2617265
Make & Model:	TOYOTA HIACE, 3.0 COMMUTER GL (A)	Chassis No:	KDH2230028366
Reg. Date:	02/09/2016 (Man. Year: 2016)	Odometer:	209533 km
Colour:	Silver		
Engine Capacity:	2982 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195 R15C	Rear Tyre Size:	195 R15C
Front Left Side:	DURATURN 5 mm	Rear Left Side:	DURATURN 5 mm
Front Right Side:	DURATURN 5 mm	Rear Right Side:	DURATURN 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,488.00	0.00	1,488.00	100.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,750.00	920.00	830.00	47.43
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	3,238.00	920.00	2,318.00	71.59
+ GST 7.00/7.00% (S\$)	226.66	64.40	162.26	71.59
Nett Amount (S\$)	3,464.66	984.40	2,480.26	71.59

INSPECTION

Date of Assignment:	28/07/2021		
Date Inspected:	29/07/2021	Inspected At:	Connect3 (woodlands) (HQ) 566 Woodlands Road Singapore 728697
Estimated Period of Repair:	3.0 days		

Adjuster: CHEN TSUE YEE

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 17 Aug 2021)	
Parts:	N/A	TOYOTA HIACE 3.0 COMMUTER GL (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for CB7802K)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*RH REAR FENDER PANEL	Repair	1,408.00 F	*- F
2	2		*SEALANT	Not Necessary	80.00 F	*- F
F=Franchise part.						
					Total Parts (\$\$)	1,488.00 0.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR TO REMOVE RH SIDE GLASS TO ASSIST REPAIR	New	150.00	0.00
2	LABOUR TO REMOVE RH TRIMS, SEATS, UPHOLSTERY TO ASSIST REPAIR	New	300.00	120.00
3	LABOUR CHARGES	New	600.00	400.00
4	SPRAY PAINTING	New	700.00	400.00
Gross Labour Cost (\$\$)			1,750.00	920.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >