

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/AIG21007998/UTF3N2**Date:** 13/10/2021REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1900154970
Claimant Vehicle No :	SKT6242T	Insured Vehicle No :	SMP8228U
Date of Loss:	20/07/2021	Nature of Claim:	TP
		Claim No:	2534842586SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKT6242T	Engine No:	BKL002085
Make & Model:	VOLKSWAGEN PHAETON, 3.2 (A)	Chassis No:	WVWZZZ3DZ68002309
Reg. Date:	11/07/2006 (Man. Year: 2005)	Odometer:	185323 km
Colour:	Black		
Engine Capacity:	3189 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	245/45ZR18	Rear Tyre Size:	245/45ZR18
Front Left Side:	West Lake 6 mm	Rear Left Side:	West Lake 6 mm
Front Right Side:	West Lake 6 mm	Rear Right Side:	West Lake 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,690.60	4,188.46	3,502.14	45.54
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,560.00	820.00	740.00	47.44
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	9,250.60	5,008.46	4,242.14	45.86
Approved Total (Overridden) (S\$)		4,000.00		
(S\$)	9,250.60	4,000.00	5,250.60	56.76
+ GST 7.00/7.00% (S\$)	647.54	280.00	367.54	56.76
Nett Amount (S\$)	9,898.14	4,280.00	5,618.14	56.76

INSPECTION

Date of Assignment:	28/07/2021	
Date Inspected:	28/07/2021	Inspected At: Fastech Auto Pte Ltd (HQ) 1 Kaki Bukit Ave 6, #01-46/48/50 Autobay Singapore 417883
Estimated Period of Repair:	3.0 days	

Adjuster: MARCUS CHUA**Manager:** DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Dented/Cracked	3,357.60 F	*2,650.00 FL
2	1		*REAR BUMPER LOWER	Cracked	730.40 F	*730.40 FL
3	1		*REAR BUMPER BEAM	Repair	800.20 F	*- FL
4	1		*REAR BUMPER CHROME MOULDING	Cracked	1,100.20 F	*980.00 FL
5	1		*SET REAR BUMPER CLIPS	Necessary	50.00 F	*50.00 FL
6	2		*REAR BUMPER SIDE RETAINERS	Not Necessary	210.00 F	*- FL
7	1		*REAR BUMPER TOP RETAINER	Serviceable	188.20 F	*- FL
8	1		*REAR ANTENNA SENSOR	Cracked	199.00 F	*199.00 FL
9	1		*REAR PDC SENSOR	Serviceable	185.00 F	*- FL
10	1		*REAR END PANEL	Repair	820.00 F	*- FL
11	1		*REAR LICENCE PLATE	Cracked	50.00 FS	*40.00 FS
					Sub Total (\$\$)	7,690.60 4,649.40
					- List Item Discount on L Items 0.00/10.00% (\$\$)	0.00 460.94
					Total Parts (\$\$)	7,690.60 4,188.46

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK WIRING	New	50.00	20.00
2	TO DISMANTLE & REPLACED REAR PDC SENSOR	New	80.00	50.00
3	TO DISMANTLE & REFIX CUSHION UPHOLSTERY	New	100.00	0.00
4	TO SPRAY RUST PROOFING	New	50.00	0.00
5	LABOUR FOR PANEL BEATING & REPLACED PARTS	New	600.00	300.00
6	TO PUTTY & SPRAY PAINTING	New	680.00	450.00
Gross Labour Cost (\$)			1,560.00	820.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >