

MS First Capital Insurance Ltd
36 Robinson Road
#16-01 City House
Singapore 068877



VICOM LTD
385 Sin Ming Drive Singapore 575718

Mainline (65) 6458 4555
Facsimile (65) 6458 1040

DAMAGE ASSESSMENT REPORT

www.vicom.com.sg
Company Registration No: 198160320R

GENERAL INFORMATION			
VAC Ref. No.	: 548153	Claim No.	: D19005106MFSH
Accident Date	: 05/08/2019	Claim Type	: THIRD PARTY
Assignment Date	: 22/08/2019	Policy No.	:
Survey Date	: 23/08/2019		
Report Date	: 23/08/2019	Insured Veh.	: SHC656Y
VEHICLE PARTICULARS			
Vehicle No.	: FBH6966H	Chassis No.	: ZAPMA330000008073
Registration Date	: 27/07/2018	Engine No.	: MA33M1008224
Make	: PIAGGIO	Engine Cap.	: 278CC
Model	: VESPA GTS SUPER/SUP	Transmission	: MANUAL
		Colour	: GREY
CONDITION OF VEHICLE DURING SURVEY (VISUAL and STATIC TEST ONLY)			
Foot Brake	: SERVICEABLE	Steering	: SERVICEABLE
Hand Brake	: SERVICEABLE	Modification	: NONE
Mileage	: NO READING		
TYRES	SIZE	MAKE	BALANCE (mm)
FRONT	120/70-17	MICHELIN	7
REAR	130/70-17	MICHELIN	7
SURVEY CONDUCTED AT			
UNITED CYCLES LLP 25 K BT RD 4 #01-25 SYNERGY @ KB SP 417800 MR LEE: 63459060			
REMARKS			
[1]Workshop did not give repair estimate.			
[2]We have not authorised repairs. This survey was carried out on without prejudice basis.			

DAMAGE ASSESSMENT REPORT**Annex A: List of damaged parts**

#	Qty	Vehicle Parts Description	Condition
1	1	Front Fender	Cut/Replace
2	1	Front Brake Disc Rotor	Intact
3	1	Front Fork Assembly	Intact
4	1	Front Tyre Rim	Intact
5	1	Front Brake Assembly	Intact
6	1	Front Center Fairing	Bent/Replace
7	1	Front Center Fairing Chrome Moulding (Lh)	Dislodge/Bent/Replace
8	1	Front Center Fairing Side Lamp (Lh)	Intact/No Visible Damaged
9	1	Front Lh Handle Lever	Cut/Replace
10	1	Front Lh Handle Balancer	Cut/Replace
11	1	Front Lh Handle Bar	Bent/Replace
12	1	Front Lh Side Mirror	Intact
13	1	Front Center Fairing Inner Garnish (Lh)	Cut/Replace
14	1	Side Center Fairing (Lh)	Bent/Replace
15	1	Side Center Fairing Outer Chrome Moulding (Lh)	Bent/Replace
16	1	Center Lower Garnish	Dislodge/Replace
17	1	Rear Lh Lower Garnish	Dislodge/Replace
18	1	Rear Lh Pillion Footrest	Bent/Cut/Replace
19	1	Rear Lh Pillion Footrest Bracket	Bent/Replace
20	1	Mainstand	Cut/Bent/Replace
21	1	Engine Cover	No Visible Damaged
22	1	Lh Side Fairing	Repair
23	3	Lh Side Fairing Stickers	Necessary/Replace
24	1	Lh Fairing Emblem 'Vespa'	Necessary/Replace
25	1	Lh Side Fairing Outer Protector	Cut/Replace
26	1	Lh Side Signal Lamp	Intact/No Visible Damaged
27	1	Rear Number Plate	No Visible Damaged
28	1	Rear Box Assembly	No Visible Damaged
29	1	Rear Box Bracket	Intact
30	1	Rear Taillamp	No Visible Damaged
31	1	Rh Side Portion	No Visible Damaged

DAMAGE ASSESSMENT REPORT**Annex B: Comments****ASSESSOR'S REPORT**

At the place of inspection, we saw this motor cycle sustained lh side portion damage.

The damages seen during our survey were front fender, front center fairing/outer moulding chrome(lh), lh side lower fairing/outer moulding, rear pillion footrest/bracket(lh), front handle lever(lh), front handle bar/balancer(lh), rear fairing outer protector(lh), main stand and surrounding areas. A fuller detailed description of the damages is in Annex A of this damage assessment report.

We enclose photographs of this vehicle taken during our attendance.

The repair estimate was not available during our survey attendance.

This Vehicle has :

a) estimated pre-accident value = S\$11,888.00

b) estimated salvage value = S\$4,952.00

c) economical repair value = S\$6,936.00

Although this vehicle was registered on 27/07/2018, a relatively brand new vehicle, we explore repairs on lump-sum basis with the workshop.



Jason Lau Zhe Hao
for VICOM Ltd































