

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CC3/AIG21008000/AVCN2**Date:** 13/10/2021**REFERENCE**

Insured/Claimant:	ONG MUN WAI EUGENE	Policy No:	2100401461-06	
Date of Loss:	14/07/2021	Nature of Claim:	OD	Claim No: 0282383866SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKR3500D		
Make & Model:	AUDI A6, 2.0 TFSI MU (A)	Engine No:	CDN408232
Reg. Date:	30/01/2015 (Man. Year: 2014)	Chassis No:	WAUZZZ4G1EN137822
Colour:	Grey	Odometer:	68578 km
Engine Capacity:	1984 cc		
Market Value/New Car Price:	S\$73,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/55R17	Rear Tyre Size:	225/55R17
Front Left Side:	Pirelli 6 mm	Rear Left Side:	Pirelli 6 mm
Front Right Side:	Pirelli 6 mm	Rear Right Side:	Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	17,459.00	11,229.28	6,229.72	35.68
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,872.00	3,022.00	3,850.00	56.02
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	24,331.00	14,251.28	10,079.72	41.43
+ GST 7.00/7.00% (S\$)	1,703.17	997.59	705.58	41.43
Nett Amount (S\$)	26,034.17	15,248.87	10,785.30	41.43

INSPECTION

Date of Assignment:	28/07/2021		
Date Inspected:	27/07/2021	Inspected At:	Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1 Singapore 408699
Estimated Period of Repair:	4.0 days		

Adjuster: ADRIAN LING**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	2,832.00 FS	*2,265.60 FS
2	1		*FRONT BUMPER FIXING PARTS	Not Necessary	276.00 FS	*- FS
3	1		*FRONT BUMPER SECURING STRIP	Not Necessary	14.00 FS	*- FS
4	1		*FRONT BUMPER CLOSING ELEMENT	Not Necessary	190.00 FS	*- FS
5	1		*FRONT BUMPER COVER TRIM-CENTER	Not Necessary	99.00 FS	*- FS
6	1		*FRONT BUMPER END CAP	Not Necessary	143.00 FS	*- FS
7	1		*FRONT BUMPER GRILLE-RH	Not Necessary	153.00 FS	*- FS
8	1		*RADIATOR GRILLE	Cracked	1,332.00 FS	*1,065.60 FS
9	1		*RADIATOR GRILLE STRIKER PLATE	Not Necessary	36.00 FS	*- FS
10	1		*FOAM FILLER PIECE	Not Necessary	99.00 FS	*- FS
11	1		*FRONT REINFORCEMENT BEAM	Dented	872.00 FS	*697.20 FS
12	1		*FRONT BUMPER TOP COVER	Cracked	123.00 FS	*98.00 FS
13	1		*FRONT BUMPER GUIDE PIECE-RH	Not Necessary	38.00 FS	*- FS
14	1		*FRONT BUMPER BRACE-RH	Not Necessary	30.00 FS	*- FS
15	1		*CAUTION STICKER	Necessary	14.00 FS	*10.88 FS
16	1		*A/C STICKER	Necessary	30.00 FS	*24.00 FS
17	1		*HORN-RH	Not Necessary	286.00 FS	*- FS
18	1		*FRONT PARKING AID SENSOR	Not Necessary	0.00 FS	*- FS
			NPA			
19	1		*FRONT PARKING AID SEAL RING	Not Necessary	6.00 FS	*- FS
20	1		*BONNET	Dented	5,436.00 FS	*4,348.80 FS
21	1		*BONNET ATTACHMENT PARTS	Not Necessary	144.00 FS	*- FS
22	2		*BONNET HINGE-LH/RH	Not Necessary	161.00 FS	*- FS
23	1		*BONNET CATCH HOOK	Not Necessary	140.00 FS	*- FS
24	2		*BONNET LOCK BAR	Not Necessary	100.00 FS	*- FS
25	2		*BONNET LOCK WITH MICRO SWITCH	Not Necessary	427.00 FS	*- FS
26	1		*BONNET BOWDEN CABLE	Not Necessary	58.00 FS	*- FS
27	2		*HEADLIGHT MOUNTING-LH/RH	Not Necessary	118.00 FS	*- FS
28	1		*HEADLIGHT RH	Cracked	3,321.00 FS	*2,656.80 FS
29	1		*HEADLIGHT LIFT CYLINDER-RH	Not Necessary	236.00 FS	*- FS
30	1		*HEADLIGHT HOSE-RH	Not Necessary	191.00 FS	*- FS
31	1		*HEADLIGHT WASHER CAP-RH	Not Necessary	58.00 FS	*- FS
32	2		*RADIATOR AIR GUIDE-LH/RH	Not Necessary	64.00 FS	*- FS
33	1		*RADIATOR COVER-UPPER CENTRE	Not Necessary	29.00 FS	*- FS
34	1		*FRONT NO PLATE	Dented	60.00 FS	*60.00 FS
35	1		*SUNDRIES	Necessary	300.00 FS	*2.40 FS
36	1		*HORN BRACKET-RH	Not Necessary	43.00 FS	*- FS

F=Franchise part. S=SpcNett.

Total Parts (\$\$)	17,459.00	11,229.28
---------------------------	------------------	------------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE,CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS,HORNS,OUTSIDE TEMPERATURE SENSOR,HEADLIGHT WASHER ASSY AND FRONT PARKING AID	New	480.00	480.00
2	TO REMOVE AND TRANSFER RHS HEADLIGHTS CONTROL UNIT AND POWER MODULE	New	400.00	250.00
3	TO DISMANTLE AND RENEW FRONT BUMPER,BONNET AND RHS HEADLIGHT.RE-ORGANIZE CRASH MANAGEMENT COMPONENTS.REINSTALL ALL PARTS REMOVED	New	2,800.00	1,000.00
4	TO RESPRAY FRONT BUMPER,RHS FRONT FENDER AND BONNET	New	3,000.00	1,100.00
5	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
Gross Labour Cost (\$\$)			6,872.00	3,022.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >