

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL: (065) 62563561 FAX: (065) 62564315

Your Ref: 21.28892 Date: 24th Dec 2021

Our Ref: CS3/ASM20013835/R1qy3e2-1

## M/s Axa Insurance Pte Ltd

C/o: Seah Ong & Partners LLP 36 Robinson Road #12-03 City House Singapore 068877 (The Motor Claims Department)

Dear Sir / Madam,

## EVALUATION REPORT (PAPER SURVEY) OF ACCIDENT VEHICLE NO: SLC 2637S INSURED VEHICLE: SMM 3465A

**ACCIDENT DATE: 08/12/2020** 

We thank you for your instruction on 28/07/2021.

We acknowledge receipt of the following documents:-

- a) Automobile Inspection Report of SLC 2637S from M/s WG Appraisal Services.
- b) Singapore Accident Statement and Police Report of Vehicle SLC 2637S.
- c) Final Repair Bill of SLC 2637S from M/s 1ST Motor Pro Pte Ltd.
- d) Colour damaged vehicle photographs of SLC 2637S.

Pre-Repair Inspection Date: 15/12/2020 at M/s 1ST Motor Pro Pte Ltd, 48 Toh Guan Road East, #05-139, Enterprise Hub, Singapore 608586.

Based on the documents received from you, we have evaluated the damages of the vehicle and have the following comments:-

1. Information Recorded: -

Registration Number : SLC 2637S

Make & Model : Hyundai LF Sonata 2.0 GLS A/T

Year of Registration : 2016

Chassis Number : KMHE341CMGA239703

Engine Capacity : 1999 cc

- 2. We recommend that the repairs of the entire damage require about \_\_\_\_\_\_ 5 (Five) \_\_\_\_\_ working days to complete.
- 3. We hereby provide our recommendations on the cost of repair to the damaged vehicle as stated in the following page.