

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

OPINION ON REPAIR COST FOR VEHICLE NO. SG 5320G

Qty	Description of Parts	Condition	Recommended (\$)
	REPLACEMENT OF PARTS		
1	BOSTICK SEALANT 7008	NECESSARY	15.00
1	REAR ENGINE COMPARTMENT DOOR	BENT	3,104.00
1	PLATE;2MX1M;SOUND ABSORBER	BENT	463.00
			3,582.00
	<u>LABOUR</u>		
	(2) WORKSHOP LABOUR.		184.00
	CONTRACTOR'S REPAIR CHARGES.		300.00
			484.00
	GRAND TOTAL		4,066.00

RECOMMENDED COST OF REPAIRS 4,066.0

Report Ref No. CS1/LPC21008002/Tvy3m4

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

ANG BRYAN TANI

Automotive Assessor / Investigator

Automotive Assessor