

Your Ref: TP/IP/26771/2021
Our Ref : CI/TPD21008003/N

5 August 2021

General Investigation Team

Traffic Police Department
Singapore Police Force
10 Ubi Avenue 3
Singapore 408865

MECHANICAL INSPECTION REPORT OF MOTORCYCLE JQR 8144

1. We refer to your request on 30 June 2021 to conduct a physical inspection of a motorcycle bearing registration number JQR 8144 (herein referred to as “**Motorcycle**”), which was involved in a non- fatal road traffic accident on 1 June 2021.
2. The objective of the inspection is to determine if there was any possible mechanical failure to the Motorcycle that may have contributed to the accident.
3. Following the request, we had carried out a physical inspection of the Motorcycle on 2 August 2021 at the premises of Traffic Police vehicle pound, 517 Airport Road Singapore 539942. We now set out below our observations and comments with respect to this inspection.


General Condition

4. The mileage of the Motorcycle at the time of our inspection was 2, 910km.
5. The Motorcycle had sustained damages all around. Body parts that were found to have been damaged include its headlight assembly, front cowling, front fork assembly, front mudguard, front basket, side cowlings, front brake lever, rear side covers, rear brake pedal, right front footrest, gear shift pedal, exhaust muffler and exhaust muffler heat shield, amongst others.

Tyres and Wheel Rims

6. The front tyre of the Motorcycle was observed to be in serviceable condition. We did not observe any tear, burst mark(s) and/or punctured hole(s) on the sidewalls as well as across the tread of the 2 tyres. Both tyres were observed to be sufficiently inflated for vehicular operation.

7. However the rear tyre was observed to be bald. The tyre brand, tyre size and remaining tread depth of the 2 tyres of the Motorcycle were recorded as follows:-



Pirelli 80/90 R17 (0mm)

Pirelli 70/90 R17 (3mm)

8. The 2 tyres were wrapped around alloy wheel rims. At the time of our inspection, we did not observe any visible damage on the front and rear wheel rim of the Motorcycle. See photos 1 – 18 below.



Photo 1 shows the speedometer gauge of the Motorcycle where the mileage recorded at the time of our inspection was 2, 910km (circled).



Photo 2 shows a general view of the frontal portion of the Motorcycle at the time of our inspection. The Motorcycle had sustained damages all around.



Photo 3 shows a general view of the left body of the Motorcycle at the time of our inspection. The Motorcycle had sustained damages all around.



Photo 4 shows a general view of the right body of the Motorcycle at the time of our inspection. The Motorcycle had sustained damages all around. Body parts that were found to have been damaged include its headlight assembly, front cowling, front fork assembly, front mudguard, front basket, side cowlings, front brake lever, rear side covers, rear brake pedal, right front footrest, gear shift pedal, exhaust muffler and exhaust muffler heat shield, amongst others.



Photo 5 shows a closer view of the grazed headlight assembly of the Motorcycle as a result of the accident (arrowed).



Photo 6 shows a closer view of the front brake lever and left handlebar end of the Motorcycle (arrowed). These parts were amongst the body parts of the Motorcycle which were damaged as a result of the accident.



Photo 7 shows a closer view of the front mudguard, which was amongst the body parts of the Motorcycle that had sustained damage as a result of the accident.



Photo 8 shows a closer view of the front cowling which was amongst the body parts at the front body of the Motorcycle that had sustained damages as a result of the accident.



Photo 9 shows a closer view of the right cowling which was amongst the body parts at the front body of the Motorcycle that had sustained damages as a result of the accident.



Photo 10 shows a closer view of the grazed left cowling which was amongst the body parts at the front body of the Motorcycle that had sustained damages as a result of the accident (arrowed).



Photo 11 shows a closer view of the right rear side cover which was amongst the body parts of the Motorcycle that had sustained damages of grazing nature as a result of the accident (circled).



Photo 12 shows a closer view of the grazed exhaust muffer (circled) and dented exhaust muffer heat shield (arrowed) which were amongst the body parts of the Motorcycle that had sustained damage as a result of the accident.



Photo 13 shows a closer view of the rear brake pedal (circled) and right front footrest (arrowed) which were amongst the body parts of the Motorcycle that had sustained damage as a result of the accident.



Photo 14 shows the broken front basket of the Motorcycle at the time of our inspection.



Photo 15 shows a closer view of the left rear side cover which was amongst the body parts of the Motorcycle that had sustained damages of grazing nature as a result of the accident (arrowed).



Photo 16 shows a closer view of the bent gear shift pedal of the Motorcycle as a result of the accident (arrowed).



Photo 17 shows the front tyre of the Motorcycle at the time of our inspection. The front tyre was observed to be in serviceable condition with remaining tread depth of approximately 3mm. The pattern of the tread was also clearly visible. There was no tear, burst mark(s) and/or punctured hole(s) on the sidewalls as well as across the tread of the front tyre.



Photo 18 shows the condition of the Motorcycle's rear tyre. The rear tyre was observed to be bald. The tyre was also observed to be sufficiently inflated for vehicular operation. We did not observe any tear, burst mark(s) and/or punctured hole(s) on the sidewalls as well as across the tread of the rear tyre.

Engine & Drive Train

9. Upon examination of the Motorcycle's engine area, we had observed that the various engine related parts and components were intact with no visible damage. There was also no sign(s) or indication(s) of fluid leak observed around the engine area of the Motorcycle.
10. The gear chain of the Motorcycle was found to be intact without any misalignment. It was also adequately lubricated for operating purposes. See photos 19 – 22 below.



Photo 19 shows the left side of the engine of the Motorcycle at the time of our inspection. The various engine related parts and components were found to be intact with no visible damage. There was also no sign(s) or indication(s) of fluid leak observed around the left engine area of the Motorcycle.



Photo 20 shows the right side of the engine of the Motorcycle at the time of our inspection. The various engine related parts and components were found to be intact with no visible damage. There was also no sign(s) or indication(s) of fluid leak observed around the right engine area of the Motorcycle.



Photo 21 shows the gear chain (arrowed) of the Motorcycle, which was observed to be intact with no misalignment. It was also adequately lubricated for operating purposes. The gear chain rotates the rear wheel of the Motorcycle.




Photo 22 shows the closer view of the gear chain (arrowed) of the Motorcycle, which was observed to be intact with no misalignment. It was also adequately lubricated for operating purposes.

Steering System & Braking System

11. For this case, we were not able to conduct any test(s) on the steering system of the Motorcycle due to the damage of its front forks. The front forks were found to be bent as a result of the accident.
12. The brake system of the Motorcycle was of a semi-hydraulic type, where hydraulic (brake fluid) pressure controls the brake for the front wheel while the brake for the rear wheel is controlled by mechanical means (cables and springs). Our visual examination of the various components in the brake system, like the brake disc, brake caliper, drum, brake lever and brake foot pedal, revealed all to be intact and without damage. There was also no leakage of brake fluid observed along the front brake hose. This was from the respective front brake fluid reservoir to the front brake caliper of the Motorcycle. The brake fluid for the front brake was found to be without contamination and of sufficient level for operating purposes. There was also no visible tear or cut observed on the connecting hoses and cables.
13. Static brake tests conducted on the Motorcycle had appear to indicate that the braking system of the Motorcycle was in serviceable condition. There was some resistance felt (spongy like feel) upon pressing the brake lever and upon stepping the brake pedal. This would indicate that there was no leakage of pressure/vacuum in the braking system.
14. For this case, we were not able to carry out any operational tests to the steering system and front braking system of the Motorcycle due to the damage of its front forks, which had rendered the Motorcycle immobile for the operational tests. We were not able to push the Motorcycle manually forward and backward, simulating movement of the Motorcycle, for the operational tests. See photos 23 – 27 below.



Photo 23 shows the front forks of the Motorcycle. The front forks (arrowed) were observed to be bent as a result of the accident. We were hence not able to conduct any tests on the steering system of the Motorcycle.



Photo 24 shows a close up view of the front brake caliper, front brake disc and front brake hose (arrowed) of the Motorcycle, which are all part of the components in the hydraulic front brake system of the Motorcycle. Our visual checks of these various components had revealed all to be intact with no visible damage. No leakage of brake fluid was also observed.



Photo 25 shows the brake fluid reservoir for the front brake of the Motorcycle. The brake fluid was observed to be of sufficient level (arrowed) and without contamination for operational purposes.



Photo 26 shows the front brake lever being depressed. There was some resistance felt (spongy like feel) upon pressing the front brake lever (arrowed). This would indicate that there is no leakage of pressure/vacuum in the brake system.



Photo 27 shows the rear wheel of the Motorcycle. The type of brake system for the rear wheel was of a mechanical type, controlled by the brake foot pedal of the Motorcycle. Our checks of the cable (arrowed), spring and drum which are all part of the components in the rear brake system of the Motorcycle reveal all to be intact and without damage.

Conclusion

15. For this particular case, we were unable to determine whether there was any possible mechanical failure to the Motorcycle that may have contributed to the accident. This was mainly due to the extent of damage that it had sustained. Its steering system was damaged as a result of the accident. The braking system of the Motorcycle was observed to be in serviceable condition.

16. The front tyre of the Motorcycle was found to be in serviceable condition. There was no tear, cut or burst mark(s) on the outer and the inner sidewalls as well as across the tread of the 2 tyres. The 2 tyres were sufficiently inflated for vehicular operation. The front tyre had remaining tread depth of approximately 3mm. The rear tyre of the Motorcycle was observed to be bald.

**Muhd Nazril***Senior Technical Investigator***Ang Bryan Tani***AMSOE, AMIRTE, AFF SAE, M.MATAI, AFF.Inst.AEA
Senior Technical Investigator
Technical Investigation & Reconstructionist (SAE-A)*

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability or responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.