

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/AIG21008012/UGA3Q2**Date:** 28/03/2022REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	7210038152
Claimant Vehicle No :	SML2943Z	Insured Vehicle No :	SMZ2693X
Date of Loss:	23/07/2021	Nature of Claim:	TP
		Claim No:	6942375357SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SML2943Z	Engine No:	CAV387822
Make & Model:	VOLKSWAGEN SCIROCCO, 1.4 TSI (A)	Chassis No:	WVWZZZ13ZCV027589
Reg. Date:	18/04/2012 (Man. Year: 2012)	Odometer:	140056 km
Colour:	White		
Engine Capacity:	1390 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/40Z R18	Rear Tyre Size:	225/40Z R18
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,592.88	2,053.72	1,539.16	42.84
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,560.00	1,060.00	500.00	32.05
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	5,152.88	3,113.72	2,039.16	39.57
Approved Total (Overridden) (S\$)		2,500.00		
(S\$)	5,152.88	2,500.00	2,652.88	51.48
+ GST 7.00/7.00% (S\$)	360.70	175.00	185.70	51.48
Nett Amount (S\$)	5,513.58	2,675.00	2,838.58	51.48
+ Loss of Use (3.0 x S\$60.00/day) (S\$)		180.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		2,857.00		
Global Sum Settlement (S\$)		2,850.00		

INSPECTION

Date of Assignment:	28/07/2021		
Date Inspected:	28/07/2021	Inspected At:	Tan Lim Motor Pte Ltd (Defu) 1 Defu Lane 6 Singapore 539365
Estimated Period of Repair:	3.0 days		

Adjuster: MARCUS CHUA**Manager:** Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Cut / Torn	1,563.18 FL	*1,232.15 FL
2	1		*REAR BUMPER SIDE RETAINER O/S	Not Necessary	65.00 FL	*- FL
3	1		*O/S REAR LAMP	Not Necessary	473.35 FL	*- FL
4	1		*O/S REAR WHEEL RIM	Cut / Warped	1,100.00 FL	*1,100.00 FL
5	1		*O/S REAR FENDER PROTECTOR	Scratched	235.00 FL	*235.00 FL
6	1		*O/S REAR WHEEL TYRE	Serviceable	500.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	3,936.53	2,567.15
- List Item Discount on L Items 10.00/20.00% (S\$)	343.65	513.43
Total Parts (S\$)	3,592.88	2,053.72

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO RUST-PROOFING OF THE AFFECTED AREAS	New	50.00	0.00
2	TO TRANSFER OF TYRE ,RIM AND ON WHEEL BALANCING	New	50.00	0.00
3	TO REINSTALL OF REAR BUMPER PARKING SENSOR	New	60.00	40.00
4	TO CHECK ELECTRICAL LIGHTING CONCERNED	New	50.00	20.00
5	PANEL BEATING ,KNOCKING AND STRAIGHTEN THE NECESSARY PORTION ,REMOVE AND RENEWAL OF PARTS ,ADJUST AND REALIGN THE SAME	New	650.00	400.00
6	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	New	700.00	600.00
Gross Labour Cost (\$\$)			1,560.00	1,060.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >