



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLS 9119R

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	FRONT RH FENDER (N)	TO REPAIR SEE LABOUR	631.50	-
1	FRONT RH DOOR (N)	BENT	1,232.90	1,232.90
1	REAR RH DOOR (N)	TO REPAIR SEE LABOUR	1,116.50	-
1	FRONT BUMPER (N)	TO REPAIR SEE LABOUR	456.30	-
1	DOOR MOULDING (N)	NECESSARY	149.00	95.10
1	DOOR MOULDING (N)	NECESSARY	149.00	95.10
1	RH SIDE MIRROR (N)	JAMMED	323.90	323.90
1	ROCKER PANEL GARNISH RH (N)	DENTED / CUT	850.30	375.00
	LESS 10% DISCOUNT		-	-212.20
			4,909.40	1,909.80
	<u>LABOUR</u>			
	LABOUR CHARGE. CHANGE FRT BUMPER, FENDER, TWO DOOR AND ROCKER PANEL. INCLUSIVE OF THE REPAIR OF FRONT RH FENDER, REAR RH DOOR AND FRONT BUMPER.		800.00	500.00
	CHANGE DOOR COMPONENT.		100.00	60.00
	SPRAY PAINTING.		1,000.00	900.00
			1,900.00	1,460.00
	GRAND TOTAL		6,809.40	3,369.80
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			2,700.00

Report Ref No. CS/SMR21008013/Kuf3e2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.