

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG21008016/T1RA3Q2
Date: 20/09/2021**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1800137537	
Claimant Vehicle No :	SH8308T	Insured Vehicle No :	SMF7829U	
Date of Loss:	26/07/2021	Nature of Claim:	TP	Claim No: 2330292839SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SH8308T		
Make & Model:	TOYOTA PRIUS, 1.8 HYBRID CVT (A)	Engine No:	2ZRS044126
Reg. Date:	30/05/2017 (Man. Year: 2017)	Chassis No:	JTDKB3FU803557283
Colour:	Blue	Odometer:	795674 km
Engine Capacity:	1798 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	West Lake 6 mm	Rear Left Side:	West Lake 6 mm
Front Right Side:	West Lake 6 mm	Rear Right Side:	West Lake 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,308.20	1,330.00	1,978.20	59.80
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,500.00	1,085.00	415.00	27.67
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	4,808.20	2,415.00	2,393.20	49.77
Approved Total (Overridden) (S\$)		1,950.00		

(S\$)	4,808.20	1,950.00	2,858.20	59.44
+ GST 7.00/7.00% (S\$)	336.57	136.50	200.07	59.44
Nett Amount (S\$)	5,144.77	2,086.50	3,058.27	59.44
+ Loss of Use (2.0 x S\$50.00/day) (S\$)		100.00		
+ Car Rental (2.0 x S\$125.40/day) (S\$)		250.80		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		2,439.30		

INSPECTION

Date of Assignment: 28/07/2021

Date Inspected: 28/07/2021

Estimated Period of Repair: 2.0 days

Inspected At:

ComfortDelGro Engineering Pte Ltd (Loyang)
 59 Loyang Drive
 Singapore 508969

Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** Jaslin Kok Chin Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*COVER FRONT BUMPER	Deformed	499.90 FL	*499.90 FL
2	1		*FENDER SUB-ASSY FRONT LH	Bent	945.30 FL	*945.30 FL
3	1		*EMBLEM SIDE PANEL (HYBRID)	Necessary	86.50 FL	*86.50 FL
4	1		*UNIT ASSY HEADLAMP LH	Not Necessary	2,637.60 FL	*- FL
5	10		*BUMPER PIECE	Necessary	22.00 FL	*22.00 FL
6	1		*SUPPORT FRONT BUMPER SIDE	Cracked	86.30 FL	*86.30 FL
7	1		*ADVERTISEMENT STICKER -FENDER	Necessary	100.00 FS	*100.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	4,377.60	1,740.00
- List Item Discount on L Items 25.00/25.00% (\$)	1,069.40	410.00
Total Parts (\$)	3,308.20	1,330.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PANEL BEATING	New	800.00	525.00
2	SPRAYPAINT CHARGE	New	600.00	500.00
3	CHECK ALL LIGHTING	New	50.00	30.00
4	TUFF COAT ON AFFECTED PARTS	New	50.00	30.00
Gross Labour Cost (\$\$)			1,500.00	1,085.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >