

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CS3/III21005232/GVF3E2-1

**Date:** 11/08/2021

### REFERENCE

Handling Insurer: India International Insurance Pte Ltd Policy No: D21MPC0000770  
**Claimant Vehicle No :** SKS7108Y **Insured Vehicle No :** SJR9548P  
Date of Loss: 25/04/2021 Nature of Claim: TP Claim No: MPC2021D0001939

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SKS7108Y**  
Make & Model: MERCEDES-BENZ C180, 1.6 Avantgarde (R17 LED) (A) Engine No: 27491030359847  
Reg. Date: 30/04/2015 (Man. Year: 2015) Chassis No: WDD2050402R056982  
Colour: Blue Odometer: 78583 km  
Engine Capacity: 1595 cc  
Market Value/New Car Price: N/A  
Sum Insured (\$\$): **Market Value/New Car Price**

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size: 225/50 R17 Rear Tyre Size: 225/50 R17  
Front Left Side: Pirelli 6 mm Rear Left Side: Pirelli 6 mm  
Front Right Side: Pirelli 6 mm Rear Right Side: Pirelli 6 mm

*The above values represent the remaining tyre treads depth*

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	19,923.00	5,123.93	14,799.07	74.28
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,680.00	1,750.00	2,930.00	62.61
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (\$\$)</b>	<b>24,603.00</b>	<b>6,873.93</b>	<b>17,729.07</b>	<b>72.06</b>
<b>Approved Total (Overridden) (\$\$)</b>		<b>5,500.00</b>		
<b>(\$\$)</b>	24,603.00	5,500.00	19,103.00	77.65
<b>+ GST 7.00/7.00% (\$\$)</b>	1,722.21	385.00	1,337.21	77.65
<b>Nett Amount (\$\$)</b>	<b>26,325.21</b>	<b>5,885.00</b>	<b>20,440.21</b>	<b>77.65</b>

### INSPECTION

Date of Assignment: 28/07/2021  
Date Inspected: 28/04/2021 Inspected At: Sin Hock Lee Motor Repair (HQ)  
51 Ubi Ave 1, #01-09 Paya Ubi Industrial Park  
Singapore 408933  
Estimated Period of Repair: 6.0 days

**Adjuster:** XING GUO QIANG

**Manager:** VERON CHEN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

**Part Source:** MRM-SG Version: 1.0 (Last Synchronised: 11 Aug 2021)

**Parts:** 143 MERCEDES-BENZ C180 1.6 Avantgarde (R17 LED) (A) (Catalogue:Merimen Singapore 1.0)

**Labour:** Repairer's (Price-denominated Standard List)

**Print Code:** (Unsubmitted, no print-code for SKS7108Y)

**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk \*.

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Fractured	1,882.00 F	*1,312.32 FL
2	1		*REAR BUMPER CHROME MOULDING LH	Abraded	102.00 F	*102.00 FL
3	1		*REAR BUMPER CHROME MOULDING RH	Necessary	102.00 F	*102.00 FL
4	1		*REAR BUMPER PARKING SENSOR LH	Serviceable	306.00 F	*- FL
5	6		*REAR BUMPER PARKING SENSOR SEAL	Serviceable	48.00 F	*- FL
6	1		*REAR BUMPER PARKING SENSOR WIRE HARNESS	Serviceable	397.00 F	*- FL
7	1		*REAR BUMPER RETAINER LH	Serviceable	65.00 F	*- FL
8	1		*REAR BUMPER SIDE RETAINER LH	Bent	56.00 F	*56.00 FL
9	1		*REAR WINDSCREEN GLASS REPAIR KIT	Serviceable	205.00 F	*- FL
10	1		*REAR FENDER LH	Repair	2,399.00 F	*- FL
11	1		*REAR SPORT RIM LH	Abraded	1,322.00 F	*1,322.00 FL
12	1		*REAR SHOCK ABSORBER LH	Serviceable	690.00 F	*- FL
13	1		*REAR TIE ROD LH	Serviceable	250.00 F	*- FL
14	1		*REAR STRUT ARM LH	Serviceable	215.00 F	*- FL
15	1		*REAR CONTROL ARM TOP LH	Serviceable	259.00 F	*- FL
16	1		*REAR TORSION BAR LINK LH	Serviceable	83.00 F	*- FL
17	1		*REAR CAMBER ARM LH	Serviceable	119.00 F	*- FL
18	1		*REAR KNUCKLE ARM LH	Serviceable	1,921.00 F	*- FL
19	1		*REAR DOOR LH	Buckled	2,205.00 F	*1,296.80 FL
20	1		*REAR DOOR GLASS OUTER CHROME MOULDING LH	Serviceable	125.00 F	*- FL
21	1		*REAR DOOR WEATHERSTRIP LH	Necessary	310.00 F	*310.00 FL
22	1		*REAR DOOR INNER TRIM BOARD LH	Deformed	1,950.00 F	*755.80 FL
23	1		*REAR DOOR INNER LOCK LH	Serviceable	549.00 F	*- FL
24	1		*REAR DOOR WINDOW REGULATOR LH	Serviceable	650.00 F	*- FL
25	1		*REAR DOOR WINDOW REGULATOR MOTOR LH	Serviceable	590.00 F	*- FL
26	1		*FRONT DOOR LH	Repair	1,798.00 F	*- FL
27	1		*FRONT DOOR GLASS OUTER MOULDING LH	Serviceable	146.00 F	*- FL
28	1		*FRONT DOOR WEATHERSTRIP LH	Serviceable	202.00 F	*- FL
29	1		*REAR WINDSCREEN GLASS SEALANT	Serviceable	70.00 FS	*- FS
30	1		*REAR TYRE LH	Abraded	550.00 FS	*120.00 FS
31	1		*REAR KNUCKLE ARM BEARING LH	Dislodged	357.00 F	*303.00 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>19,923.00</b>	<b>5,679.92</b>
<b>- List Item Discount on L Items 0.00/10.00% (\$\$)</b>	0.00	555.99

<b>Total Parts (\$\$)</b>	<b>19,923.00</b>	<b>5,123.93</b>
---------------------------	------------------	-----------------

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO STRAIGHTEN AND PANEL BEATING REAR LH FRAME MEMBER. TO CUT / WELD REAR LH FENDER. TO REMOVE AND REFIT ABOVE PARTS	New	1,400.00	600.00
2	TO PUTTY, RE-SPRAY PAINTING AND POLISH AFFECTED AREAS	New	1,800.00	800.00
3	TO CHECK AND RECTIFY WIRING SYSTEM	New	80.00	30.00
4	TO RUST PROOF AFFECTED AREAS	New	120.00	60.00
5	TO REMOVE AND REFIT REAR WINDSCREEN GLASS	New	150.00	0.00
6	TO REMOVE AND REFIT LINING, UPHOLSTERY, CUSHION SEATS, GARNISH, FITTINGS, ETC. TO ASSIST REPAIR	New	200.00	60.00
7	TO REMOVE, REFIT REAR LH SPORT RIM / TYRE AND BALANCING	New	50.00	30.00
8	TO REMOVE AND REFIT REAR SUSPENSION SYSTEM	New	400.00	50.00
9	TO CONDUCT ELECTRONIC WHEEL ALIGNMENT TEST	New	180.00	60.00
10	TO REMOVE, TRANSFER AND REFIT LH REAR DOOR COMPONENTS	New	300.00	60.00

<b>Gross Labour Cost (\$\$)</b>	<b>4,680.00</b>	<b>1,750.00</b>
---------------------------------	-----------------	-----------------

Report was unsubmitted during this print-out.

< END OF ESTIMATES >