

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG21008017/T1PA3Q2
Date: 06/09/2021**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1900110006
Claimant Vehicle No :	SBS15J	Insured Vehicle No :	SMM8546S
Date of Loss:	24/07/2021	Nature of Claim:	TP
		Claim No:	1061019910SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SBS15J		
Make & Model:	VOLVO B9TL, 9.4 D AUTO TURBO ABS (A)	Engine No:	D9194774
Reg. Date:	30/12/2015 (Man. Year: 2015)	Chassis No:	YV3S4P923GA175469
Colour:	Green	Odometer:	370740 km
Engine Capacity:	9364 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	275/70 R22.5	Rear Tyre Size:	275/70 R22.5 (D)
Front Left Side:	Firenza 8 mm	Rear Left Side:	Firenza 8/8 mm
Front Right Side:	Firenza 8 mm	Rear Right Side:	Firenza 8/8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,022.76	194.24	3,828.52	95.17
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,640.00	1,880.00	1,760.00	48.35
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	7,662.76	2,074.24	5,588.52	72.93
+ GST 7.00/7.00% (S\$)	536.39	145.20	391.19	72.93

Nett Amount (S\$)	8,199.15	2,219.44	5,979.71	72.93
+ Loss of Use (3.0 x S\$300.00/day) (S\$)		900.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		3,121.44		
Global Sum Settlement (S\$)		3,120.00		

INSPECTION

Date of Assignment: 28/07/2021

Date Inspected: 30/07/2021

Estimated Period of Repair: 3.0 days

Inspected At:

Lexbuild International Pte Ltd - Loyang Way (HQ)
 LOYANG BUS DEPOT, 2 LOYANG WAY
 Singapore 508776

Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR LHS WHEELARC PANEL	Repair	1,161.18 F	*- FL
2	1		*REAR LHS 2nd LAST PANEL	Bent	215.82 F	*215.82 FL
3	1		*REAR LHS LAST PANEL	Repair	1,333.22 F	*- FL
4	1		*REAR LHS CORNER BUMPER	Repair	1,312.54 F	*- FL

F=Franchise part. L=ListItemDisc.

Sub Total (\$)	4,022.76	215.82
- List Item Discount on L Items 0.00/10.00% (\$)	0.00	21.58
Total Parts (\$)	4,022.76	194.24

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	SUPPLY SKILLED LABOUR TO:REPLACE REAR LHS WHEELARC PANEL, REPLACE REAR LHS 2nd LAST PANEL,REPLACE REAR LHS LAST PANEL ,REPLACE REAR LHS CORNER BUMPER	New	2,640.00	880.00
2	SUPPLY SKILLED PAINTER & PAINT MATERIAL TO PUTTY ,GRINDING & SPRAYPAINT:REAR LHS WHEELARC PANEL,REAR LHS 2nd LAST PANEL,REAR LHS LAST PANEL ,REAR LHS CORNER BUMPER	New	1,000.00	1,000.00
Gross Labour Cost (S\$)			3,640.00	1,880.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >