



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SG 5831Z

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	LAMP.REVERSE.(BULB)	CRACKED	98.00	98.00
1	LAMP ASSY.LED.STOP	CRACKED	330.00	330.00
1	LAMP HSG W/OUT BULB.FOG.RR	CRACKED	40.00	40.00
2	LED.SIGNAL LAMP.RR.LH/RH	CRACKED	150.00	150.00
1	OUT-MCD3300 OUTDOOR CAMERA WITH LENS	CRACKED	450.00	450.00
			1,068.00	1,068.00
	<u>LABOUR</u>			
	TERM CONTRACTOR LABOUR COST.		180.00	180.00
	CONTRACTOR LABOUR COST. (BODYWORK)		850.00	850.00
	WORKSHOP LABOUR COST.	NOT NECESSARY	184.00	-
			1,214.00	1,030.00
	GRAND TOTAL		2,282.00	2,098.00
RECOMMENDED COST OF REPAIRS				2,098.00

Report Ref No. CS/FCI21008018/T1uf3e2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.