

Re: E/3231/2021 - SG5831Z with TTS bus svc 66 SBS6338M

Yao Tianhao <yaoth@sbstransit.com.sg>

Wed 7/28/2021 1:59 PM

Estimate for

Stock Code	Description	Quantity	Total Material cost(S\$)
30400257	LAMP.REVERSE.(BULB) cra√	1	\$98.00
30400255	LAMP ASSY.LED.STOP cra ✓	1	\$330.00
30400213	LAMP HSG W/OUT BULB.FOG.RR cra ✓	1	\$40.00
30541771	LED.SIGNAL LAMP.RR.LH/RH cra√	1	\$150.00
OUT- MCD3	OUT-MCD3300 Outdoor camera with lens	1	\$450.00
		Sub Total S\$:	450.00
(A)		Total for Parts S\$:	1068.00

V-7	
Parts cost: \$ 1068 ✓ Term Contractor Labour cost (CCTV): \$ 180 Contractor Labour cost (BODYWORK): \$ 850 Workshop Labour cost: \$ 184 Xnn Advertisement Cost: \$ 0 Repair period: 2 days ✓	+gst \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \
Tow Cost: \$ 0 Loss of use: \$ not required by lkk Overheads: \$ 684.60 Xnn	"WP" 29/07/21 @3 Resurvey new par 2 DAYS taufikh@lkkauto,co COR not finalised

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

3pm ts

with workshop