

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/AIG21008022/BQF3E2

Date: 29/10/2021

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2070119328
Claimant Vehicle No : CB6997M Insured Vehicle No : GBJ8155H
Date of Loss: 27/07/2021 Nature of Claim: TP Claim No: 7601624388SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **CB6997M**
Make & Model: TOYOTA HIACE, 3.0 (A) Engine No: 5L5304017
Reg. Date: 22/03/2003 (Man. Year: 2003) Chassis No: LH1726112720
Colour: Silver Odometer: 823778 km
Engine Capacity: 2985 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195 R15 Rear Tyre Size: 195 R15
Front Left Side: OHTSU 5 mm Rear Left Side: Yokohama 5 mm
Front Right Side: OHTSU 5 mm Rear Right Side: Yokohama 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 28/07/2021
Date Inspected: 18/08/2021 Inspected At: Ann Joo Motor Pte Ltd (HQ)
Singapore 575721
Estimated Period of Repair: 3.0 days

Adjuster: Lim Teow Guan

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

MARKET VALUE: \$30,000.00 (EST)

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount	
1	1		*REAR LH TAILLAMP	Broken	0.00 F	*- F	
2	1		*REAR RH TAILLAMP	Broken	0.00 F	*- F	
3	1		*TAILGATE	Dented	0.00 F	*- F	
4	1		*TAILGATE EMBLEM	Necessary	0.00 F	*- F	
5	1		*TAILGATE LOCK	Jammed	0.00 F	*- F	
6	1		*TAILGATE LOCK COVER	Broken	0.00 F	*- F	
7	1		*STICKER 60KM/H	Necessary	0.00 F	*- F	
					Total Parts (\$)	0.00	0.00

F=Franchise part.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >