

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT CS3/ASM21008023/R1tce2 AXA INSURANCE PTE LTD Ref: 8 SHENTON WAY #24-01 AXA TOWER Date: 13/08/2021 SINGAPORE 068811 ATTN: PAY DANIEL Code: ASM 1. Policy Particulars :- (THIRD PARTY CLAIM) Insured Veh. SHB 2293C XD 3964T Veh. Inspected Policy No. VFX/P2419140 Coverage (\$) 0.00 Claim No. S1M03EE4 Excess (\$) 0.00 **PAY DANIEL Assign Date** 28/07/2021 Assign From **Vehicle Particulars & Condition** 2. SCANIA P380CA4X2MSZ 11705 Make & Model C.C HIDDEN 2010 Engine No. Year of Reg. XLEP4X20005234857 YELLOW Chassis No. Colour 785274 KM Odometer Steering **IN ORDER IN ORDER** NIL **Brakes** Modification **FAIR** General 3. **Conditions of Tyres** Size Make **Balance** R/H Front Tyre 295/80 R22.5 **GOODYEAR** 8 mm 295/80 R22.5 L/H Front Tyre **GOODYEAR** 8 mm 295/80 R22.5 (D) GOODYEAR R/H Rear Tyre 8/8 mm 295/80 R22.5 (D) GOODYEAR L/H Rear Tyre 8/8 mm 4. **Description of Damages** THE VEHICLE SUSTAINED DAMAGES AT THE O/S FRONT PORTION. 5. **General Information** 23/07/2021 05/08/2021 (01:49 PM) **Accident Date** Inspect Date / Time 7 SOON LEE STREET #01-39 iSPACE S627608 Survey held at Repairer LYS ENGINEERING 5a. Remarks A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$5,000-\$6,000 5b. **Estimate Days of Repair ESTIMATED NORMAL PERIOD FOR REPAIR:** 7 Working Days

Report Ref No. CS3/ASM21008023/R1tce2

Inspected By

Automotive Assessor

MOHAMMED RASUL BIN MOHD YUNUS

K.K.LAU CPT(RET)

SEOD Anta Organizations OAE Linear Administra

BEng(Hons), B.Bus, MBA, PEng, PE, MInstAEA, MASME, MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser