

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/GRB21008024/AUF3N2**Date:** 07/09/2021REFERENCE

Handling Insurer: India International Insurance Pte Ltd

Policy No:

Claimant Vehicle No : SFZ21G**Insured Vehicle No :** SLR8284H

Date of Loss: 30/06/2021

Nature of Claim: TP Claim No: N/A

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **SFZ21G**

Make & Model: HONDA ACCORD, 1.6 (M)

Engine No: K24W31201287

Reg. Date: 18/09/2015 (Man. Year: 2014)

Chassis No: MRHCR2630EP000075

Colour: Silver

Odometer: 167224 km

Engine Capacity: 2356 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 235/45R18

Rear Tyre Size: 235/45R18

Front Left Side: Pirelli 6 mm

Rear Left Side: Pirelli 6 mm

Front Right Side: Pirelli 6 mm

Rear Right Side: Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,462.56	3,581.12	2,881.44	44.59
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,730.00	860.00	870.00	50.29
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	8,192.56	4,441.12	3,751.44	45.79
Approved Total (Overridden) (S\$)		3,500.00		
Nett Amount (S\$)	8,192.56	3,500.00	4,692.56	57.28

INSPECTION

Date of Assignment: 28/07/2021

Date Inspected: 30/07/2021 Inspected At:

Centre Line Car Spray Painting (HQ)
2 KAKI BUKIT AVENUE 2, #02-23 KAKI BUKIT
AUTOHUB
Singapore 417921

Estimated Period of Repair: 4.0 days

Adjuster: ADRIAN LING**Manager:** Tan Hui Zhen

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 06 Sep 2021)
Parts:	143	HONDA ACCORD 1.6 (M) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SFZ21G)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	708.60 FL	*708.60 FL
2	1		*FRONT BUMPER PDC SENSOR-RH	Damaged	281.90 FL	*185.00 FL
3	1		*FRONT BUMPER FOG LAMP-RH	Cracked	441.50 FL	*285.00 FL
4	1		*FRONT BUMPER FOG LAMP COVER	Not Necessary	86.90 FL	*- FL
5	1		*FRONT BUMPER SPONGE	Not Necessary	120.30 FL	*- FL
6	1		*FRONT BUMPER REINFORCEMENT	Not Necessary	441.20 FL	*- FL
7	1		*FRONT BUMPER SIDE RETAINERS-L/R	O/s Necessary	65.40 FL	*32.70 FL
8	1		*FRONT BONNET	Repair	891.90 FL	*- FL
9	1		*FRONT FENDER-RH	Repair	541.80 FL	*- FL
10	1		*FRONT FENDER INNER SHIELD-RH	Not Necessary	154.60 FL	*- FL
11	1		*FRONT GRILLE ASSY	Cracked	481.90 FL	*385.00 FL
12	1		*FRONT HEADLAMP ASSY-L.E.D	Cracked	2,955.60 FL	*2,753.00 FL
13	1		*FRONT HEADLAMP LOWER BRACKET	Cracked	89.60 FL	*89.60 FL
14	1		*FRONT SUPPORT PANEL	Repair	561.90 FL	*- FL
15	1		*FRONT WIPER TANK	Not Necessary	142.60 FL	*- FL
16	1		*SET FRONT BUMPER CLIP	Necessary	45.00 FS	*30.00 FS
17	1		*SET FRONT FENDER INNER SHIELD CLIP	Not Necessary	45.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	8,055.70	4,468.90
- List Item Discount on L Items 20.00/20.00% (\$\$)	1,593.14	887.78
Total Parts (\$\$)	6,462.56	3,581.12

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK FRONT ELECTRICAL WIRING	New	50.00	30.00
2	TO RESPRAY UNDERCOATING	New	80.00	30.00
3	TO RESPRAY PAINTING AND ETC	New	800.00	400.00
4	PANEL BEATING,CUT,WELD REMOVE & REPLACING ABOVE PARTS	New	800.00	400.00
Gross Labour Cost (\$\$)			1,730.00	860.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >