

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC3/AIG21008025/AEA3Q2**Date:** 31/03/2022REFERENCE

| | | | |
|------------------------------|--------------------------------------|-----------------------------|---------------|
| Handling Insurer: | AIG Asia Pacific Insurance Pte. Ltd. | Policy No: | 2100383718-07 |
| Claimant Vehicle No : | SCQ9780Y | Insured Vehicle No : | SFN911B |
| Date of Loss: | 18/07/2021 | Nature of Claim: | TP |
| | | Claim No: | 8864661433SG |

DESCRIPTION & IDENTIFICATION OF VEHICLE

| | | | |
|-----------------------------|--|-------------|-------------------|
| Reg No: | SCQ9780Y | | |
| Make & Model: | AUDI A5, 2.0 SB TFSI S TRONIC (DESIGN) (A) | Engine No: | DEM024936 |
| Reg. Date: | 14/09/2020 (Man. Year: 2020) | Chassis No: | WAUZZZF56LA021158 |
| Colour: | White | Odometer: | 8658 km |
| Engine Capacity: | 1984 cc | | |
| Market Value/New Car Price: | N/A | | |
| Sum Insured (\$\$): | Market Value/New Car Price | | |

CONDITION OF VEHICLE AT THE TIME OF SURVEY

| | | | | |
|--------------------------|-------------------------|----------------------|--------------------------|-------------------------|
| General Condition: | Steering (Serviceable): | Yes | Footbrake (Serviceable): | Yes |
| Handbrake (Serviceable): | Yes | Engine Modification: | No | Pre-accident Condition: |

CONDITION OF TYRES

| | | | |
|-------------------|---------------|------------------|---------------|
| Front Tyre Size: | 255/35 R19 | Rear Tyre Size: | 255/35 R19 |
| Front Left Side: | Michelin 6 mm | Rear Left Side: | Michelin 6 mm |
| Front Right Side: | Michelin 6 mm | Rear Right Side: | Michelin 6 mm |

The above values represent the remaining tyre treads depth

| COST OF CLAIMS | Repairer's | Adjuster's | Difference | Diff % |
|--|-------------------|-------------------|-------------------|---------------|
| Parts | 3,287.00 | 0.00 | 3,287.00 | 100.00 |
| Miscellaneous Items | 0.00 | 0.00 | 0.00 | |
| Labour | 3,002.00 | 1,852.00 | 1,150.00 | 38.31 |
| Paintwork Labour | 0.00 | 0.00 | 0.00 | |
| Towing | 0.00 | 0.00 | 0.00 | |
| Gross Total (\$\$) | 6,289.00 | 1,852.00 | 4,437.00 | 70.55 |
| + GST 7.00/7.00% (\$\$) | 440.23 | 129.64 | 310.59 | 70.55 |
| Nett Amount (\$\$) | 6,729.23 | 1,981.64 | 4,747.59 | 70.55 |
| + Car Rental (3.0 x S\$150.00/day) (\$\$) | | 450.00 | | |
| + Doc/Search Fee (\$\$) | | 2.00 | | |
| Nett Liability (\$\$) | | 2,433.64 | | |

INSPECTION

| | | | |
|-----------------------------|------------|---------------|--|
| Date of Assignment: | 03/08/2021 | | |
| Date Inspected: | 03/08/2021 | Inspected At: | Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1 Singapore 408699 |
| Estimated Period of Repair: | 3.0 days | | |

Adjuster: ADRIAN LING**Manager:** Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

| No. | Qty | Part No. | Particulars | Condition | Repairer's | Amount |
|------------------------------|-----|----------|--|---------------|-------------|--------|
| 1 | 1 | | *FRONT BUMPER | Repair | 2,342.00 FS | *- FS |
| 2 | 1 | | *FRONT BUMPER CLOSING ELEMENT LOWER CENTRE | Not Necessary | 262.00 FS | *- FS |
| 3 | 1 | | *FRONT BUMPER CLOSING ELEMENT | Not Necessary | 262.00 FS | *- FS |
| 4 | 2 | | *FRONT BUMPER SECURING STRIP | Not Necessary | 71.00 FS | *- FS |
| 5 | 1 | | *SUNDRIES | Not Necessary | 350.00 FS | *- FS |
| F=Franchise part. S=SpcNett. | | | | | | |
| Total Parts (S\$) | | | | | 3,287.00 | 0.00 |

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

| No | Particulars | Lab.Type | Repairer's | Amount |
|---------------------------------|---|----------|-----------------|-----------------|
| Labour Items | | | | |
| 1 | TO REMOVE CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHT HORNS ,OUTSIDE TEMPERATURE SENSOR HEADLIGHT WASHER ASSY AND FRONT PARKING AID | New | 480.00 | 480.00 |
| 2 | TO DISMANTLE AND RENEW FRONT BUMPER .REORGANISE CRASH MANAGEMENT COMPONENTS REINSTALL ALL PARTS REMOVED | New | 1,200.00 | 500.00 |
| 3 | TO RESPRAY FRONT BUMPER | New | 1,000.00 | 550.00 |
| 4 | TO REAPPLY PAINT COATING ON AFFECTED AREA (BY OWNER) | New | 130.00 | 130.00 |
| 5 | TO CARRY OUT DIAGNOSTIC CHECK | New | 192.00 | 192.00 |
| Gross Labour Cost (\$\$) | | | 3,002.00 | 1,852.00 |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >