

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:**

CC6/III21008030/APS3Q2

Date:

10/12/2021

REFERENCE

Handling Insurer: India International Insurance Pte Ltd

Policy No:

D20MFL0000326_01

Claimant Vehicle No : SMW8566G**Insured Vehicle No :**

SMJ1734C

Date of Loss: 23/07/2021

Nature of Claim:

TP

Claim No:

MFL2021D0003268

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **SMW8566G**

Make & Model: SSANGYONG TIVOLI, 1.6 (A)

Engine No:

67391002094925

Reg. Date: 15/12/2020 (Man. Year: 2020)

Chassis No:

KPT30A1USLP318110

Colour: Black

Odometer:

19816 km

Engine Capacity: 1597 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price****CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:

Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Yes

Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/65 R16

Rear Tyre Size:

205/65 R16

Front Left Side: Kumho 6 mm

Rear Left Side:

Kumho 6 mm

Front Right Side: Kumho 6 mm

Rear Right Side:

Kumho 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	8,589.86	6,175.07	2,414.79	28.11
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,210.00	2,000.00	1,210.00	37.69
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	11,799.86	8,175.07	3,624.79	30.72
Approved Total (Overridden) (S\$)		6,500.00		

(S\$)	11,799.86	6,500.00	5,299.86	44.91
+ GST 7.00/7.00% (S\$)	825.99	455.00	370.99	44.91
Nett Amount (S\$)	12,625.85	6,955.00	5,670.85	44.91
+ Loss of Use (6.0 x S\$60.00/day) (S\$)		360.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		7,322.45		

INSPECTION

Date of Assignment:	26/07/2021		
Date Inspected:	26/07/2021	Inspected At:	MG Solution Pte Ltd (HQ) 23 Kaki Bukit Avenue 4 #02-03B, VICOM Inspection Centre Singapore 415933
Estimated Period of Repair:	6.0 days		

Adjuster: ADRIAN LING

Manager: CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 24 Nov 2021)
Parts:	M1-SUV	SSANGYONG TIVOLI 1.6 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMW8566G)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILGATE	Dented	1,890.40 FL	*1,450.00 FL
2	1		*TAILGATE LOGO	Necessary	150.00 FL	*150.00 FL
3	1		*TAILGATE EMBLEM TIVOLI	Necessary	90.00 FL	*90.00 FL
4	1		*TAILGATE EMBLEM SSANGYONG	Necessary	110.00 FL	*110.00 FL
5	1		*TAILGATE LOCK	Damaged	322.50 FL	*322.50 FL
6	1		*TAILGATE INNER TRIM	Cracked	510.20 FL	*510.20 FL
7	1		*TAILGATE WEATHERSTRIP	Not Necessary	210.00 FL	*- FL
8	1		*TAILGATE WINDSCREEN MOULDING	Necessary	190.00 FL	*190.00 FL
9	1		*TAILGATE KEYLESS SENSOR	Not Necessary	280.20 FL	*- FL
10	1		*TAILGATE NUMBER PLATE GARNISH	Not Necessary	160.00 FL	*- FL
11	1		*REAR BUMPER UPPER	Deformed	1,245.80 FL	*855.00 FL
12	1		*REAR BUMPER LOWER	Deformed	650.20 FL	*394.00 FL
13	2		*REAR BUMPER SIDE RETAINER	Necessary	128.40 FL	*128.40 FL
14	2		*REAR BUMPER REFLECTOR	Not Necessary	280.00 FL	*- FL
15	1		*REAR BUMPER REINFORCEMENT	Cracked	455.50 FL	*455.50 FL
16	1		*REAR BUMPER REINFORCEMENT BRACKET	Damaged	180.20 FL	*180.20 FL
17	4		*REAR BUMPER REINFORCEMENT INNER HOLDER	Damaged	320.00 FL	*180.00 FL
18	1		*REAR BUMPER BRAKE LIGHT	Cracked	250.00 FL	*250.00 FL
19	1		*REAR END PANEL	Dented	820.50 FL	*595.00 FL
20	1		*REAR END PANEL TOP GARNISH	Deformed	211.50 FL	*211.50 FL
21	1		*REAR STICKERE	Necessary	500.00 FS	*300.00 FS
22	1		*REAR NUMBER PLATE	Deformed	20.00 FS	*20.00 FS
23	1		*SET TAILGATE INNER TRIM CLIPS	Necessary	20.00 FS	*20.00 FS
24	1		*TAILGATE WINDSCREEN MOULDING	Necessary	80.00 FS	*80.00 FS
25	1		*SET REAR BUMPER CLIPS	Necessary	20.00 FS	*20.00 FS
26	1		*REAR END PANEL SEALANT	Necessary	100.00 FS	*60.00 FS
27	1		*SET REAR END PANEL TOP GARNISH CLIPS	Necessary	20.00 FS	*10.00 FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
28	1		*REVERSE SENSOR	Damaged	220.00 FS	*200.00 FS
F=Franchise part. S=SpcNett. L=ListItemDisc.						
					Sub Total (\$\$)	9,435.40
					- List Item Discount on L Items 10.00/10.00% (\$\$)	845.54
					Total Parts (\$\$)	8,589.86

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PANEL BEATINGM ,REMOVAL AND REPLACING PARTS	New	1,200.00	800.00
2	TO SPRAY PAINT AFFECTED AREA	New	1,200.00	800.00
3	TUFF COAT	New	250.00	60.00
4	WIRING CHECK	New	100.00	30.00
5	REMOVE AND REFIX UPHOLSTRY AND ROOF LINNING TO FACILITATE REPAIR	New	180.00	60.00
6	REMOVE AND REFIX REVERSE SENSOR AND DISTACE SETTING	New	80.00	50.00
7	TRANFER TAILGATE MECHANISM	New	80.00	80.00
8	TRANFER TAILGATE WINDSCREEN	New	120.00	120.00
Gross Labour Cost (S\$)			3,210.00	2,000.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >