

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/AIG21008031/APA3Q2**Date:** 20/01/2022**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1800019409
Claimant Vehicle No :	SMD9649U	Insured Vehicle No :	SLW7122Y
Date of Loss:	26/07/2021	Nature of Claim:	TP
		Claim No:	6958089268SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMD9649U	Engine No:	LEB6560234
Make & Model:	HONDA SHUTTLE HYBRID, 1.5 (A)	Chassis No:	GP71216645
Reg. Date:	13/09/2018 (Man. Year: 2018)	Odometer:	37996 km
Colour:	Silver		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	185/60 R15	Rear Tyre Size:	185/60 R15
Front Left Side:	Yokohama 6 mm	Rear Left Side:	Yokohama 6 mm
Front Right Side:	Yokohama 6 mm	Rear Right Side:	Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	10,606.70	3,768.96	6,837.74	64.47
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,190.00	1,560.00	630.00	28.77
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	12,796.70	5,328.96	7,467.74	58.36
Approved Total (Overridden) (S\$)		4,200.00		
(S\$)	12,796.70	4,200.00	8,596.70	67.18
+ GST 7.00/7.00% (S\$)	895.77	294.00	601.77	67.18
Nett Amount (S\$)	13,692.47	4,494.00	9,198.47	67.18
+ Loss of Use (5.0 x S\$60.00/day) (S\$)		300.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		4,801.45		
Global Sum Settlement (S\$)		4,800.00		

INSPECTION

Date of Assignment:	27/07/2021	Green Forest Automobile Pte Ltd (Kaki Bukit)
Date Inspected:	27/07/2021 Inspected At:	8 Kaki Bukit Avenue 4, #05-25,, Premier@Kaki Bukit
Estimated Period of Repair:	5.0 days	Singapore 415875

Adjuster: ADRIAN LING**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BOOT LID	Distorted	1,250.00 F	*1,180.00 FL
2	2		*REAR BOOT LID HINGES	Not Necessary	310.00 F	*- FL
3	1		*REAR BOOT LID RUBBER	Not Necessary	205.00 F	*- FL
4	1		*REAR BOOT LID INNER TRIM	Cracked	680.00 F	*366.00 FL
5	1		*BOOT LID INNER LOCK	Damaged	203.10 F	*203.10 FL
6	2		*REAR BOOT LID SHOCK ABSORBER	Not Necessary	420.00 F	*- FL
7	1		*REAR BOOT LID WINDSCREEN INNER SEAL	Necessary	128.00 F	*128.00 FL
8	8		*REAR BOOT LID CENTER GARNISH CLIPS	Necessary	44.00 F	*20.00 FL
9	1		*REAR BOOT LID CENTRE GARNISH	Cracked	285.10 F	*285.10 FL
10	1		*REAR BOOT LID EMBLE LOGO	Necessary	60.00 F	*60.00 FL
11	1		*REAR BOOT LID SHUTTLE LOGO	Necessary	40.00 F	*40.00 FL
12	1		*REAR BOOT LID HYBRID LOGO	Necessary	48.00 F	*48.00 FL
13	1		*BOOT LID CENTRE MOULDING	Not Necessary	385.20 F	*- FL
14	1		*BOOT LID CENTRE MOULDING CLIPS	Not Necessary	80.00 F	*- FL
15	1		*REAR BOOT LID SIDE REFLECTOR	N/S Cracked	750.00 F	*375.00 FL
16	1		*REAR TAIL LAMP	N/S Cut	1,116.00 F	*558.00 FL
17	2		*REAR NUMBER PLATE LAMP	Not Necessary	116.00 F	*- FL
18	1		*REAR NUMBER PLATE	Not Necessary	50.00 F	*- FL
19	2		*REAR BUMPER SIDE REFLECTOR	Not Necessary	170.00 F	*- FL
20	1		*REAR BUMPER REINFORCEMENT	Not Necessary	425.10 F	*- FL
21	1		*REAR BUMPER	Deformed	1,080.00 F	*1,080.00 FL
22	2		*REAR BUMPER SIDE BRACKET	Necessary	224.00 F	*78.00 FL
23	8		*REAR BUMPER CLIPS	Necessary	40.00 F	*40.00 FL
24	1		*REAR BUMPER SPONGE	Not Necessary	168.20 F	*- FL
25	1		*REAR BUMPER REVERSE SENSOR	Damaged	350.00 FS	*200.00 FS
26	1		*REAR END PANEL	Repair	740.00 F	*- FL
27	1		*REAR END PANEL TOP GARNISH	Not Necessary	384.00 F	*- FL
28	1		*SPARE TYRE PANEL TOP COVER	Not Necessary	415.00 F	*- FL
29	1		*REAR SPARE TYRE PANEL SEALANT	Not Necessary	280.00 F	*- FL
30	1		*REAR EXHAUST CHROME PIPE	Not Necessary	160.00 F	*- FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	10,606.70	4,661.20
- List Item Discount on L Items 0.00/20.00% (\$)	0.00	892.24
Total Parts (\$)	10,606.70	3,768.96

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	REMOVE/REFIX REAR WINDSCREEN	New	120.00	120.00
2	GUM	New	50.00	50.00
3	REMOVE/REFIX REAR CUSHION	New	120.00	60.00
4	REMOVE/REFIX REAR REVERSE SENSOR	New	120.00	50.00
5	TUFF KOTE	New	120.00	50.00
6	TO CHECK WIRING SYSTEM	New	60.00	30.00
7	PANEL BEATING	New	800.00	600.00
8	SPRAY PAINTING CHARGES	New	800.00	600.00
Gross Labour Cost (\$\$)			2,190.00	1,560.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >