

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CC6/AIG21008032/APA3Q2**Date:** 18/05/2022REFERENCE

|                              |                                      |                             |              |
|------------------------------|--------------------------------------|-----------------------------|--------------|
| Handling Insurer:            | AIG Asia Pacific Insurance Pte. Ltd. | Policy No:                  | 1800049642   |
| <b>Claimant Vehicle No :</b> | SMH8205C                             | <b>Insured Vehicle No :</b> | SFV9099U     |
| Date of Loss:                | 26/07/2021                           | Nature of Claim:            | TP           |
|                              |                                      | Claim No:                   | 1334132115SG |

DESCRIPTION & IDENTIFICATION OF VEHICLE

|                             |                                   |             |                   |
|-----------------------------|-----------------------------------|-------------|-------------------|
| Reg No:                     | <b>SMH8205C</b>                   | Engine No:  | 3A92UHN8897       |
| Make & Model:               | MITSUBISHI ATTRAGE, 1.2 CVT (A)   | Chassis No: | MMBSTA13AKH001101 |
| Reg. Date:                  | 11/02/2019 (Man. Year: 2018)      | Odometer:   | 34073 km          |
| Colour:                     | Silver                            |             |                   |
| Engine Capacity:            | 1193 cc                           |             |                   |
| Market Value/New Car Price: | N/A                               |             |                   |
| Sum Insured (S\$):          | <b>Market Value/New Car Price</b> |             |                   |

CONDITION OF VEHICLE AT THE TIME OF SURVEY

|                          |                         |                      |                          |                         |
|--------------------------|-------------------------|----------------------|--------------------------|-------------------------|
| General Condition:       | Steering (Serviceable): | Yes                  | Footbrake (Serviceable): | Yes                     |
| Handbrake (Serviceable): | Yes                     | Engine Modification: | No                       | Pre-accident Condition: |

CONDITION OF TYRES

|                   |                  |                  |                  |
|-------------------|------------------|------------------|------------------|
| Front Tyre Size:  | 185/55 R15       | Rear Tyre Size:  | 185/55 R15       |
| Front Left Side:  | Bridgestone 6 mm | Rear Left Side:  | Bridgestone 6 mm |
| Front Right Side: | Bridgestone 6 mm | Rear Right Side: | Bridgestone 6 mm |

*The above values represent the remaining tyre treads depth*

| <b>COST OF CLAIMS</b>                           | <b>Repairer's</b> | <b>Adjuster's</b> | <b>Difference</b> | <b>Diff %</b> |
|-------------------------------------------------|-------------------|-------------------|-------------------|---------------|
| Parts                                           | 13,228.96         | 6,260.00          | 6,968.96          | 52.68         |
| Miscellaneous Items                             | 0.00              | 0.00              | 0.00              |               |
| Labour                                          | 5,420.00          | 2,890.00          | 2,530.00          | 46.68         |
| Paintwork Labour                                | 0.00              | 0.00              | 0.00              |               |
| Towing                                          | 0.00              | 0.00              | 0.00              |               |
| <b>Calculated Gross Total (S\$)</b>             | <b>18,648.96</b>  | <b>9,150.00</b>   | <b>9,498.96</b>   | <b>50.94</b>  |
| <b>Approved Total (Overridden) (S\$)</b>        |                   | <b>7,200.00</b>   |                   |               |
| <b>(S\$)</b>                                    | 18,648.96         | 7,200.00          | 11,448.96         | 61.39         |
| <b>+ GST 7.00/7.00% (S\$)</b>                   | 1,305.43          | 504.00            | 801.43            | 61.39         |
| <b>Nett Amount (S\$)</b>                        | <b>19,954.39</b>  | <b>7,704.00</b>   | <b>12,250.39</b>  | <b>61.39</b>  |
| <b>+ Car Rental (9.0 x S\$100.00/day) (S\$)</b> |                   | 900.00            |                   |               |
| <b>+ Doc/Search Fee (S\$)</b>                   |                   | 7.45              |                   |               |
| <b>Nett Liability (S\$)</b>                     |                   | <b>8,611.45</b>   |                   |               |
| <b>Global Sum Settlement (S\$)</b>              |                   | <b>8,600.00</b>   |                   |               |

INSPECTION

|                             |            |               |                                                                                 |
|-----------------------------|------------|---------------|---------------------------------------------------------------------------------|
| Date of Assignment:         | 27/07/2021 |               |                                                                                 |
| Date Inspected:             | 27/07/2021 | Inspected At: | Xin Hua Workshop Pte Ltd (HQ)<br>23 Kaki Bukit Ave 4 #04-01<br>Singapore 415933 |
| Estimated Period of Repair: | 8.0 days   |               |                                                                                 |

**Adjuster:** ADRIAN LING**Manager:** CHEW HSIAO TONG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

**SPECIAL REMARKS**

(FOR MANDATE ONLY)

## REPAIR DETAILS

### Recommended Parts

| No. | Qty | Part No. | Particulars                          | Condition     | Repairer's  | Amount     |
|-----|-----|----------|--------------------------------------|---------------|-------------|------------|
| 1   | 1   |          | *BOOTLID                             | Dented        | 923.50 FL   | *828.00 FL |
| 2   | 2   |          | *BOOTLID HINGES                      | Not Necessary | 197.40 FL   | *- FL      |
| 3   | 1   |          | *BOOTLID ATTRAGE EMBLEM              | Necessary     | 89.50 FL    | *89.50 FL  |
| 4   | 1   |          | *BOOTLID MIVEC EMBLEM                | Necessary     | 87.20 FL    | *87.20 FL  |
| 5   | 1   |          | *BOOTLID CC EMBLEM                   | Necessary     | 87.50 FL    | *87.50 FL  |
| 6   | 1   |          | *BOOTLID LOGO                        | Necessary     | 95.60 FL    | *95.60 FL  |
| 7   | 2   |          | *BOOTLID STOPPER                     | Not Necessary | 60.00 FL    | *- FL      |
| 8   | 1   |          | *BOOTLID CHROME MOULDING             | Cracked       | 385.90 FL   | *385.90 FL |
| 9   | 1   |          | *BOOTLID NUMBER PLATE LAMPS          | Not Necessary | 78.50 FL    | *- FL      |
| 10  | 1   |          | *BOOTLID INNER LOCK                  | Damaged       | 245.80 FL   | *165.00 FL |
| 11  | 1   |          | *BOOTLID LOCK CATCH                  | Not Necessary | 46.80 FL    | *- FL      |
| 12  | 1   |          | *BOOTLID INNER TRIM                  | Not Necessary | 298.70 FL   | *- FL      |
| 13  | 1   |          | *BOOTLID WEATHERSTRIP                | Cut           | 185.60 FL   | *185.60 FL |
| 14  | 1   |          | *BOOTLID OUTER LOCK SWITCH           | Not Necessary | 195.60 FL   | *- FL      |
| 15  | 1   |          | *REAR BUMPER                         | Deformed      | 698.60 FL   | *698.60 FL |
| 16  | 2   |          | *REAR BUMPER RETAINER                | Necessary     | 171.40 FL   | *171.40 FL |
| 17  | 2   |          | *REAR BUMPER REFLECTORS              | Not Necessary | 125.00 FL   | *- FL      |
| 18  | 2   |          | *TAILAMPS                            | Cracked       | 779.40 FL   | *670.00 FL |
| 19  | 2   |          | *TAILAMPS INNER SEAL                 | Not Necessary | 70.00 FL    | *- FL      |
| 20  | 1   |          | *TAILAMPS PANELS                     | N/S Dented    | 397.40 FL   | *198.70 FL |
| 21  | 1   |          | *END PANEL                           | Dented        | 598.30 FL   | *598.30 FL |
| 22  | 1   |          | *END PANEL TOP GARNISH               | Deformed      | 178.90 FL   | *178.90 FL |
| 23  | 1   |          | *SPARE TYRE PANEL                    | Repair        | 986.30 FL   | *- FL      |
| 24  | 1   |          | *SPARE TYRE TOP BOARD                | Torn          | 258.90 FL   | *207.00 FL |
| 25  | 1   |          | *SPARE TYRE WHEEL NUT                | Not Necessary | 68.20 FL    | *- FL      |
| 26  | 1   |          | *REAR AIR VENT                       | Not Necessary | 65.80 FL    | *- FL      |
| 27  | 1   |          | *REAR AIR VENT OUTER GARNISH         | Not Necessary | 65.20 FL    | *- FL      |
| 28  | 1   |          | *REAR ALARM SPEAKER                  | Damaged       | 116.30 FL   | *116.30 FL |
| 29  | 1   |          | *REAR FENDER                         | N/S Buckled   | 1,975.00 FL | *798.00 FL |
| 30  | 2   |          | *REAR FENDER INNER TRIM              | Not Necessary | 596.60 FL   | *- FL      |
| 31  | 2   |          | *REAR FENDER INNER COWLINGS          | Not Necessary | 312.40 FL   | *- FL      |
| 32  | 1   |          | *REAR SILENCER BOX                   | Not Necessary | 756.80 FL   | *- FL      |
| 33  | 2   |          | *REAR SILENCER BOX MOUNTING          | Not Necessary | 137.80 FL   | *- FL      |
| 34  | 1   |          | *REAR WINDSCREEN MOULDING            | Necessary     | 138.50 FL   | *138.50 FL |
| 35  | 2   |          | *REAR WINDSCREEN INNER SEAL          | Not Necessary | 80.00 FL    | *- FL      |
| 36  | 1   |          | *SET REAR BUMPER CLIPS               | Necessary     | 30.00 FS    | *30.00 FS  |
| 37  | 2   |          | *SET REAR TAILAMPS CLIPS             | Necessary     | 60.00 FS    | *20.00 FS  |
| 38  | 1   |          | *SET REAR BUMPER LOWER SKIRT         | Cracked       | 950.00 FS   | *750.00 FS |
| 39  | 1   |          | *SET REAR BOOTLID SPOILER            | Not Necessary | 650.00 FS   | *- FS      |
| 40  | 2   |          | *SET REAR FENDER INNER COWLING CLIPS | Not Necessary | 60.00 FS    | *- FS      |
| 41  | 2   |          | *SET REAR FENDER INNER TRIM CLIPS    | Not Necessary | 60.00 FS    | *- FS      |
| 42  | 2   |          | *END PANEL SEALANT                   | Necessary     | 80.00 FS    | *60.00 FS  |
| 43  | 1   |          | *SET END PANEL TOP GARNISH CLIPS     | Necessary     | 30.00 FS    | *10.00 FS  |
| 44  | 1   |          | *SET SPARE TYRE FLOOR INSULATOR PADS | Not Necessary | 150.00 FS   | *- FS      |
| 45  | 1   |          | *SET WINDSCREEN SEALANT              | Necessary     | 80.00 FS    | *60.00 FS  |
| 46  | 1   |          | *SET REVERSE SENSORS                 | Damaged       | 250.00 FS   | *200.00 FS |
| 47  | 1   |          | *SET REVERSE CAMERA                  | Not Necessary | 380.00 FS   | *- FS      |
| 48  | 1   |          | *SET REAR NUMBER PLATE WITH CASING   | Not Necessary | 50.00 FS    | *- FS      |

F=Franchise part. S=SpcNett. L=ListItemDisc.

|                                                          |                  |                 |
|----------------------------------------------------------|------------------|-----------------|
| <b>Sub Total (\$)</b>                                    | <b>14,384.40</b> | <b>6,830.00</b> |
| <b>- List Item Discount on L Items 10.00/10.00% (\$)</b> | 1,155.44         | 570.00          |
| <b>Total Parts (\$)</b>                                  | <b>13,228.96</b> | <b>6,260.00</b> |

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

| No                              | Particulars                                                              | Lab.Type | Repairer's      | Amount          |
|---------------------------------|--------------------------------------------------------------------------|----------|-----------------|-----------------|
| <b>Labour Items</b>             |                                                                          |          |                 |                 |
| 1                               | TO RENEW DAMAGED PARTS ,REPLACE BEAT ,WELD ,REALIGN AND ALIGNE ALL PARTS | New      | 1,800.00        | 1,200.00        |
| 2                               | TO RESPRAY AFFECTED AREAS                                                | New      | 1,800.00        | 1,200.00        |
| 3                               | TO TUFFCOAT AFFECTED AREA                                                | New      | 200.00          | 60.00           |
| 4                               | TO REMOVE/REFIT /REPLACE REAR BOOTLID MECHANISM                          | New      | 120.00          | 60.00           |
| 5                               | TO REMOVE /REFIT REAR INTERIOR UPHOLSTERY                                | New      | 150.00          | 60.00           |
| 6                               | TO CONDUCT CHECK ON TAILAMPS WIRING                                      | New      | 120.00          | 30.00           |
| 7                               | TO REMOVE/REFIT REAR SENSOR AND DISTANCE SETTLING                        | New      | 150.00          | 50.00           |
| 8                               | TO REMOVE/REFIT REAR CAMERA AND SETTING                                  | New      | 150.00          | 50.00           |
| 9                               | TO REMOVE/REFIT /REPLACE REAR WINDSCREEN FOR FENDER REPLACEMENT          | New      | 120.00          | 120.00          |
| 10                              | TO REMOVE/REFIT REAR FUEL TANK FOR FENDER REPLACEMENT                    | New      | 280.00          | 0.00            |
| 11                              | TO REPAIR AND REALIGN REAR CHASSIS MEMBER                                | New      | 350.00          | 0.00            |
| 12                              | LABOUR TO APPLY SEALANT ON THE AFFECTED AREA                             | New      | 180.00          | 60.00           |
| <b>Gross Labour Cost (\$\$)</b> |                                                                          |          | <b>5,420.00</b> | <b>2,890.00</b> |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >