

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/ICS21008035/ATF3N2**Date:** 03/11/2021REFERENCE

Handling Insurer: ECICS Limited Policy No:

Claimant Vehicle No : SJW3554J **Insured Vehicle No :** SLZ7033E

Date of Loss: 27/07/2021 Nature of Claim: TP Claim No: DMPC2100244H/02/CT

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SJW3554J**

Make & Model: TOYOTA COROLLA ALTIS, 1.6 (A) Engine No: 3ZZ4976893

Reg. Date: 18/03/2010 (Man. Year: 2010) Chassis No: MR053ZEE106167965

Colour: Blue Odometer: 133063 km

Engine Capacity: 1598 cc

Market Value/New Car Price: N/A

Sum Insured (\$\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/65R15 Rear Tyre Size: 195/65R15

Front Left Side: Yokohama 6 mm Rear Left Side: Yokohama 6 mm

Front Right Side: Yokohama 6 mm Rear Right Side: Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	12,265.77	6,308.47	5,957.30	48.57
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,060.00	3,440.00	2,620.00	43.23
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	18,325.77	9,748.47	8,577.30	46.80
Approved Total (Overridden) (\$\$)		7,800.00		
(\$\$)	18,325.77	7,800.00	10,525.77	57.44
+ GST 7.00/7.00% (\$\$)	1,282.80	546.00	736.80	57.44
Nett Amount (\$\$)	19,608.57	8,346.00	11,262.57	57.44

INSPECTION

Date of Assignment: 29/07/2021

Date Inspected: 30/07/2021 Inspected At:

MG Solution Pte Ltd (HQ)
23 Kaki Bukit Avenue 4 #02-03B, VICOM
Inspection Centre
Singapore 415933

Estimated Period of Repair: 11.0 days

Adjuster: ADRIAN LING**Manager:** DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 03 Nov 2021)
Parts:	143	TOYOTA COROLLA ALTIS 1.6 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SJW3554J)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	2		*REAR DOOR	Repair	2,590.00 FL	*- FL
2	1		*BOOTLID	Distorted	769.60 FL	*769.60 FL
3	1		*BOOTLID LOGO	Necessary	80.00 FL	*80.00 FL
4	1		*BOOTLID EMBLEM COROLLA	Necessary	62.40 FL	*62.40 FL
5	1		*BOOTLID EMBLEM ALTIS	Necessary	55.30 FL	*55.30 FL
6	1		*BOOTLID EMBLEM 1.6	Necessary	55.00 FL	*55.00 FL
7	2		*BOOTLID HINGE	Bent	181.60 FL	*181.60 FL
8	1		*BOOTLID TOP LOCK	Damaged	162.20 FL	*162.20 FL
9	1		*BOOTLID LOWER LOCK	Damaged	60.00 FL	*60.00 FL
10	1		*BOOTLID INNER TRIM	Torn	160.20 FL	*160.20 FL
11	1		*BOOTLID WEATHERSTRIP	Cut	222.30 FL	*222.30 FL
12	2		*BOOTLID REFLECTOR	Cracked	381.40 FL	*381.40 FL
13	1		*REAR BUMPER	Distorted	588.70 FL	*588.70 FL
14	2		*REAR BUMPER SIDE RETAINER FRONT	Not Necessary	124.80 FL	*- FL
15	2		*REAR BUMPER SIDE RETAINER REAR	Necessary	110.40 FL	*110.40 FL
16	1		*REAR BUMPER REFLECTOR	O/s Cracked	180.00 FL	*90.00 FL
17	2		*REAR BUMPER BRACKET	Dented	260.00 FL	*260.00 FL
18	1		*REAR BUMPER SPONGE WITH PROTECTOR BAR	Damaged	166.80 FL	*166.80 FL
19	1		*NUMBER PLATE CHROME	Cracked	280.00 FL	*280.00 FL
20	1		*SET NUMBER PLATE LAMP	Not Necessary	120.50 FL	*- FL
21	2		*TAILLAMP	Cracked	750.00 FL	*750.00 FL
22	1		*TAILLAMP PANEL	O/s Dented	510.60 FL	*255.30 FL
23	2		*TAILLAMP LOWER BRACKET	Cracked	120.80 FL	*120.80 FL
24	1		*REAR FENDER	O/s Buckled	1,844.60 FL	*922.30 FL
25	2		*REAR FENDER INNER COWLING	Not Necessary	140.00 FL	*- FL
26	2		*REAR FENDER INNER TRIM	Torn	777.80 FL	*570.00 FL
27	1		*REAR FENDER AIR VENT	Cracked	112.50 FL	*112.50 FL
28	1		*REAR FENDER INNER PANEL RH	Repair	587.00 FL	*- FL
29	1		*REAR WINDSCREEN MOULDING	Necessary	169.00 FL	*169.00 FL
30	1		*REAR END PANEL	Distorted	708.00 FL	*708.00 FL
31	1		*REAR END PANEL TOP GARNISH	Deformed	126.00 FL	*126.00 FL
32	1		*REAR FLOOR PANEL	Repair	899.00 FL	*- FL
33	1		*REAR FLOOR PANEL TOP BOARD	Deformed	311.50 FL	*311.50 FL
34	1		*REAR FLOOR COTTON CROSS MEMBER	Not Necessary	533.40 FL	*- FL
35	1		*REAR EXHAUST PIPE	Repair	855.90 FL	*- FL
36	2		*REAR EXHAUST MOUNTING	Not Necessary	110.40 FL	*- FL
37	1		*REAR NUMBER PLATE	Deformed	50.00 FS	*50.00 FS
38	1		*SET REAR BOOTLID INNER TRIM CLIPS	Not Necessary	20.00 FS	*- FS
39	1		*SET REAR BUMPER CLIPS	Necessary	20.00 FS	*20.00 FS
40	1		*SET TAILLAMP CLIPS	Necessary	30.00 FS	*30.00 FS
41	1		*TAILLAMP PANEL SEALANT	Not Necessary	120.00 FS	*- FS
42	1		*REAR FENDER SEALANT	Necessary	120.00 FS	*50.00 FS
43	1		*SET REAR FENDER COWLING CLIPS	Not Necessary	20.00 FS	*- FS
44	1		*SET REAR FENDER INNER TRIM CLIP	Necessary	20.00 FS	*20.00 FS
45	1		*REAR END PANEL TOP GARNISH CLIPS	Necessary	20.00 FS	*20.00 FS
46	1		*REAR END PANEL INSULATION SEAL	Necessary	150.00 FS	*60.00 FS

Report was unsubmitted during this print-out.

11/3/21, 11:12 AM

Adjuster Report

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
47	1		*REAR WINDSCREEN SEALANT	Necessary	100.00 FS	*60.00 FS
48	1		*REVERSE SENSOR	Damaged	220.00 FS	*200.00 FS
F=Franchise part. S=SpcNett. L=ListItemDisc.						
Sub Total (\$)					16,057.70	8,241.30
- List Item Discount on L Items 25.00/25.00% (\$)					3,791.93	1,932.83
Total Parts (\$)					12,265.77	6,308.47
Report was unsubmitted during this print-out.						

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING,REMOVAL AND REPLACING PARTS	New	2,400.00	1,600.00
2	TO SPRAY PAINT AFFECTED AREA	New	2,400.00	1,400.00
3	TUFF COAT	New	250.00	100.00
4	WIRING CHECK	New	100.00	30.00
5	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING	New	80.00	50.00
6	TRANFER BOOTLID MECHANISM	New	120.00	60.00
7	CONDUCT WATER LEAKAGE TEST	New	80.00	0.00
8	REMOVE AND REFIX REAR WINDSCREEN	New	120.00	120.00
9	REMOVE AND REFIX REAR EXHAUST PIPE	New	180.00	0.00
10	TRANFER REAR DOOR MECHANISM	New	80.00	0.00
11	REMOVE AND REFIX CUSHION SEAT /UPHOLSTERY & ROOF LINING TO FACILITATE REPAIR	New	250.00	80.00
Gross Labour Cost (\$\$)			6,060.00	3,440.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >