

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG21008038/GGS3Q2**Date:** 21/01/2022REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2070162309
Claimant Vehicle No :	SMX64K	Insured Vehicle No :	GBH9738E
Date of Loss:	26/07/2021	Nature of Claim:	TP
		Claim No:	0431790384SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMX64K	Engine No:	8ARW236906
Make & Model:	LEXUS RX200T, 2.0 (A)	Chassis No:	JTJBAMCA802003621
Reg. Date:	28/03/2016 (Man. Year: 2016)	Odometer:	85737 km
Colour:	Grey		
Engine Capacity:	1998 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	265/40 R22	Rear Tyre Size:	265/40 R22
Front Left Side:	Michelin 8 mm	Rear Left Side:	Michelin 8 mm
Front Right Side:	Michelin 8 mm	Rear Right Side:	Michelin 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,607.00	1,037.97	4,569.03	81.49
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,662.00	1,830.00	1,832.00	50.03
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	9,269.00	2,867.97	6,401.03	69.06
Approved Total (Overridden) (S\$)		2,300.00		
(S\$)	9,269.00	2,300.00	6,969.00	75.19
+ GST 7.00/7.00% (S\$)	648.83	161.00	487.83	75.19
Nett Amount (S\$)	9,917.83	2,461.00	7,456.83	75.19
Global Sum Settlement (S\$)		0.00		

INSPECTION

Date of Assignment:	29/07/2021	Juzz Performance Pte Ltd (HQ)
Date Inspected:	29/07/2021 Inspected At:	8 Kaki Bukit Avenue 4 #03-51/52 PREMIER @Kaki Bukit
Estimated Period of Repair:	4.0 days	Singapore 415875

Adjuster: XING GUO QIANG**Manager:** Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*LH FRONT DOOR	Torn	2,950.00 F	*1,069.30 FL
2	1		*LH FRONT DOOR INNER LOCK	Not Necessary	728.00 F	*- FL
3	1		*LH FRONT DOOR OUTER HANDLE	Not Necessary	740.00 F	*- FL
4	1		*LH FRONT DOOR REGULATOR COMPLETE WITH MOTOR	Not Necessary	1,025.00 F	*- FL
5	1		*FRONT DOOR SEALANT	Not Necessary	80.00 F	*- FL
6	12		*FRONT DOOR GARNISH CLIP	Necessary	84.00 F	*84.00 FL
					Sub Total (S\$)	5,607.00 1,153.30
					- List Item Discount on L Items 0.00/10.00% (S\$)	0.00 115.33
					Total Parts (S\$)	5,607.00 1,037.97

F=Franchise part. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO INSTALL SOUND INSULATION FOR LH FRONT DOOR	New	1,250.00	950.00
2	AUTO MOULDING	New	212.00	0.00
3	TO REMOVE & INSTALL LH FRONT DOOR }	New	350.00	380.00
4	TO TRANSFER FRONT DOOR MECHANISM }	New	250.00	0.00
5	TO PANEL BEAT}	New	400.00	0.00
6	TO SPRAY PAINT INTERIOR & EXTERIOR DOOR	New	600.00	280.00
7	CERAMIC COATING	New	500.00	200.00
8	WIRING CHECK	New	100.00	20.00
Gross Labour Cost (\$)			3,662.00	1,830.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >