

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT						
	AXA INSURANCE	PTE LTD	Re	ef:	CS3/ASM21008039/Gtce2	
	8 SHENTON WAY SINGAPORE 0688	#24-01 AXA TOWER 11	Da	ate:	03/08/2021	
	ATTN: CHAN KIAN	CHUAN	Co	ode:	ASM	
1.	Policy Particulars :- (THIRD PARTY CLAIM)					
	Insured Veh.	SHC 3042Z	Veh. Inspected		FBD 5513J	
	Policy No.	VFX/P2419138	Coverage (\$)		0.00	
	Claim No.	S1M0375A	Excess (\$)		0.00	
	Assign From	CHAN KIAN CHUAN	Assign Date		29/07/2021	
2.	. Vehicle Particulars & Condition					
	Make & Model	YAMAHA YBR125	c.c		124	
	Engine No.	HIDDEN	Year of Reg.		2009	
	Chassis No.	LBPKE128490020451	Colour		RED	
	Odometer	50631 KM	Steering		IN ORDER	
	Brakes	IN ORDER	Modification		NIL	
	General	GOOD				
3.	3. Conditions of Tyres					
		Size	Make		Balance	
	R/H Front Tyre	80/90-18	GOLDEN BOY		4 mm	
	L/H Front Tyre				mm	
	R/H Rear Tyre	90/90-18	MICHELIN		4 mm	
	L/H Rear Tyre				mm	
4.	Description of Damages					
	THE VEHICLE SUS BODY.	STAINED DAMAGES AT THE FRO	O/S			
5.	General Information					
	Accident Date	02/04/2021	Inspect Date / Tim	ne	29/07/2021 (11:00 AM)	
	Survey held at	25 KAKI BUKIT ROAD 4 #06-28	SYNERGY			
	Repairer	Repairer TOH MOTOR ENTERPRISE				
5a.		Remarks				
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$1,500-\$2,000					
5b.	Estimate Days of Repair					
	ESTIMATED NORMAL PERIOD FOR REPAIR: 3 Working Days					

Report Ref No. CS3/ASM21008039/Gtce2

Inspected By

XING GUO QIANG

K.K.LAU CPT(RET)

M.MATAI, AMSAE-A

 $BEng(Hons), B. Bus, MBA, PEng, PE, \, MInstAEA, MASME, MIRTE$

REGD Auto Consultant-SAE, Licensed Appraiser

Automotive Assessor