

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT**

AIG Asia Pacific Insurance Pte. Ltd.  
AIG Building, 78 Shenton Way #07-16  
Singapore 079120

**Our File No:** CS/AIG21008040/EQF3N2**Date:** 29/10/2021**REFERENCE**

Insured/Claimant: REDDIPALLI ASHOK RAMAMURTHY  
Date of Loss: 28/07/2021

Policy No: 1800134321  
Nature of Claim: OD Claim No: 5055957510SG

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No: **SJU7937Y**  
Make & Model: MITSUBISHI ECLIPSE CROSS, 1.5 (A) Engine No: 4B40DR9185  
Reg. Date: 19/11/2018 (Man. Year: 2018) Chassis No: JMAXTGK1WJZ002846  
Colour: Brown Odometer: 63249 km  
Engine Capacity: 1499 cc  
Market Value/New Car Price: S\$93,000.00  
Sum Insured (S\$): **Market Value/New Car Price**

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

**CONDITION OF TYRES**

Front Tyre Size: 225/55R18 Rear Tyre Size: 225/55R18  
Front Left Side: Yokohama 5 mm Rear Left Side: Yokohama 5 mm  
Front Right Side: Yokohama 5 mm Rear Right Side: Yokohama 5 mm

*The above values represent the remaining tyre tread depth*

| <b>COST OF CLAIMS</b>               | <b>Repairer's</b> | <b>Adjuster's</b> | <b>Difference</b> | <b>Diff %</b> |
|-------------------------------------|-------------------|-------------------|-------------------|---------------|
| Parts                               | 17,004.05         | 11,894.37         | 5,109.68          | 30.05         |
| Miscellaneous Items                 | 0.00              | 0.00              | 0.00              |               |
| Labour                              | 15,570.00         | 9,615.00          | 5,955.00          | 38.25         |
| Paintwork Labour                    | 0.00              | 0.00              | 0.00              |               |
| Towing                              | 0.00              | 0.00              | 0.00              |               |
| <b>Calculated Gross Total (S\$)</b> | <b>32,574.05</b>  | <b>21,509.37</b>  | <b>11,064.68</b>  | <b>33.97</b>  |
| <b>- Excess (S\$)</b>               | 800.00            | 800.00            | 0.00              | 0.00          |
| <b>(S\$)</b>                        | 31,774.05         | 20,709.37         | 11,064.68         | 34.82         |
| <b>+ GST 7.00/7.00% (S\$)</b>       | 2,224.18          | 1,449.66          | 774.52            | 34.82         |
| <b>Nett Amount (S\$)</b>            | <b>33,998.23</b>  | <b>22,159.03</b>  | <b>11,839.20</b>  | <b>34.82</b>  |

**INSPECTION**

Date of Assignment: 29/07/2021

Date Inspected: 29/07/2021 Inspected At:

Cycle & Carriage Automotive Pte Ltd (Pandan Gardens)  
209 Pandan Gardens  
Singapore 609339

Estimated Period of Repair: 22.0 days

**Adjuster:** CHEN TSUE YEE**Manager:** SHIAU CHAN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Recommended Parts

| No. | Qty | Part No. | Particulars                 | Condition     | Repairer's | Amount     |
|-----|-----|----------|-----------------------------|---------------|------------|------------|
| 1   | 1   |          | *FACE,RR BUMPER             | Dented        | 556.00 FL  | *556.00 FL |
| 2   | 1   |          | *EXTENSION,RR BUMPER        | Broken        | 152.00 FL  | *152.00 FL |
| 3   | 1   |          | *COVER,RR BUMPER,LH         | Not Necessary | 117.00 FL  | *- FL      |
| 4   | 1   |          | *COVER,RR BUMPER,RH         | Not Necessary | 117.00 FL  | *- FL      |
| 5   | 1   |          | *BRKT,R/BMPR FACE SIDE,LH   | Not Necessary | 25.00 FL   | *- FL      |
| 6   | 1   |          | *BRKT,R/BMPR FACE SIDE,RH   | Broken        | 25.00 FL   | *25.00 FL  |
| 7   | 8   |          | *CLIP,FR BUMPER             | Necessary     | 32.00 FL   | *32.00 FL  |
| 8   | 2   |          | *BRACKET,RR BUMPER          | Not Necessary | 32.00 FL   | *- FL      |
| 9   | 1   |          | *CORE,RR BUMPER             | Not Necessary | 34.00 FL   | *- FL      |
| 10  | 1   |          | *BRACKET,RR BUMPER SIDE,LWR | Not Necessary | 12.00 FL   | *- FL      |
| 11  | 1   |          | *PANEL,QTR,OTR RH           | Dented        | 866.00 FL  | *866.00 FL |
| 12  | 1   |          | *EXTENSION,QTR PANEL,OTR RH | Not Necessary | 110.00 FL  | *- FL      |
| 13  | 1   |          | *EXTN,QTR PANEL,RR LWR RH   | Dented        | 97.00 FL   | *97.00 FL  |
| 14  | 1   |          | *REINF,GATE PILLAR,RH       | Not Necessary | 150.00 FL  | *- FL      |
| 15  | 1   |          | *GARNISH,SIDE SILL,RH       | Cut           | 91.00 FL   | *91.00 FL  |
| 16  | 1   |          | *GARNISH,FR DOOR,RH         | Cut           | 241.00 FL  | *241.00 FL |
| 17  | 1   |          | *GARNISH,RR DOOR,RH         | Cut           | 160.00 FL  | *160.00 FL |
| 18  | 1   |          | *MOULDING,R/DOOR PROTECT,RH | Cut           | 105.00 FL  | *105.00 FL |
| 19  | 1   |          | *GARNISH,QTR PANEL RH       | Cut           | 181.00 FL  | *181.00 FL |
| 20  | 1   |          | *GARNISH,RR DOOR SASH,RR RH | Not Necessary | 49.00 FL   | *- FL      |
| 21  | 1   |          | *GARNISH,RR DOOR SASH,FR RH | Not Necessary | 108.00 FL  | *- FL      |
| 22  | 1   |          | *GARNISH,FR DOOR SASH,RH    | Not Necessary | 66.00 FL   | *- FL      |
| 23  | 1   |          | *GARN,FR DOOR DELTA,OTR RH  | Not Necessary | 175.00 FL  | *- FL      |
| 24  | 1   |          | *GARNISH,FR PILLAR,RH       | Not Necessary | 123.00 FL  | *- FL      |
| 25  | 1   |          | *MOULDING,FR WHEEL ARCH,RH  | Cut           | 151.00 FL  | *151.00 FL |
| 26  | 1   |          | *MOULDING,RR WHEEL ARCH,RH  | Cut           | 159.00 FL  | *159.00 FL |
| 27  | 1   |          | *SHIELD,RR WHEEL,FR RH      | Not Necessary | 126.00 FL  | *- FL      |
| 28  | 1   |          | *SHIELD,RR WHEEL,RR RH      | Torn          | 38.00 FL   | *38.00 FL  |
| 29  | 1   |          | *PANEL ASSY,RR DOOR,RH      | Dented        | 942.00 FL  | *942.00 FL |
| 30  | 1   |          | *HINGE,RR DOOR,UPR RHR      | Not Necessary | 38.00 FL   | *- FL      |
| 31  | 1   |          | *HINGE,RR DOOR LWR RHR      | Not Necessary | 38.00 FL   | *- FL      |
| 32  | 1   |          | *MLDG,R/DR WDO BELT LINE,RH | Not Necessary | 120.00 FL  | *- FL      |
| 33  | 1   |          | *MOULDING,R/DR SASH,UPR RH  | Necessary     | 114.00 FL  | *114.00 FL |
| 34  | 1   |          | *SASH,RR DOOR WINDOW,CTR RH | Not Necessary | 60.00 FL   | *- FL      |
| 35  | 1   |          | *REGULATOR,R/DR WINDOW,RH   | Not Necessary | 77.00 FL   | *- FL      |
| 36  | 1   |          | *GASKET,F/DR OUTSIDE HANDLE | Not Necessary | 6.00 FL    | *- FL      |
| 37  | 1   |          | *HANDLE,FR DOOR OUTSIDE,RH  | Not Necessary | 86.00 FL   | *- FL      |
| 38  | 1   |          | *COVER,F/DR OUTS HANDLE,RH  | Not Necessary | 20.00 FL   | *- FL      |
| 39  | 1   |          | *GASKET,F/DR OUTSIDE HANDLE | Not Necessary | 4.00 FL    | *- FL      |
| 40  | 1   |          | *BASE,F/DR OUTSIDE HOLE,RH  | Not Necessary | 47.00 FL   | *- FL      |
| 41  | 1   |          | *LATCH,RR DOOR,RH           | Not Necessary | 321.00 FL  | *- FL      |
| 42  | 1   |          | *SHIM,FR DOOR LATCH STRIKER | Not Necessary | 6.00 FL    | *- FL      |
| 43  | 1   |          | *STRIKER,FR DOOR LATCH      | Not Necessary | 20.00 FL   | *- FL      |
| 44  | 1   |          | *PANEL ASSY,FR DOOR,RH      | Dented        | 954.00 FL  | *954.00 FL |
| 45  | 1   |          | *MLDR,F/DR WDO BELT LINE,RH | Not Necessary | 89.00 FL   | *- FL      |
| 46  | 1   |          | *MOULDING,F/DR SASH,UPR RH  | Necessary     | 119.00 FL  | *119.00 FL |
| 47  | 1   |          | *HINGE,FR DOOR,UPR RH       | Not Necessary | 54.00 FL   | *- FL      |
| 48  | 1   |          | *HINGE,FR DOOR,LWR RH       | Not Necessary | 54.00 FL   | *- FL      |
| 49  | 1   |          | *MOTOR,F/DR POWER WDO REG,R | Not Necessary | 439.00 FL  | *- FL      |
| 50  | 1   |          | *REGULATOR,FR DOOR WDO,RH   | Not Necessary | 104.00 FL  | *- FL      |
| 51  | 1   |          | *GASKET,F/DR OUTSIDE HANDLE | Not Necessary | 6.00 FL    | *- FL      |
| 52  | 1   |          | *HANDLE,FR DOOR OUTSIDE,RH  | Not Necessary | 298.00 FL  | *- FL      |
| 53  | 1   |          | *COVER,F/DR OUTS HANDLE,RH  | Not Necessary | 20.00 FL   | *- FL      |
| 54  | 1   |          | *GASKET,F/DR OUTSIDE HANDLE | Not Necessary | 4.00 FL    | *- FL      |
| 55  | 1   |          | *BASE,F/DR OUTSIDE HDLE,RH  | Not Necessary | 47.00 FL   | *- FL      |

Report was unsubmitted during this print-out.

| No. | Qty | Part No. | Particulars                                    | Condition     | Repairer's  | Amount       |
|-----|-----|----------|------------------------------------------------|---------------|-------------|--------------|
| 56  | 1   |          | *SHIM,FR DOOR LATCH STRIKER                    | Not Necessary | 6.00 FL     | *- FL        |
| 57  | 1   |          | *STRIKER,FR DOOR LATCH                         | Not Necessary | 20.00 FL    | *- FL        |
| 58  | 1   |          | *LATCH,FR DOOR,RH                              | Not Necessary | 322.00 FL   | *- FL        |
| 59  | 1   |          | *CHECK,FR DOOR                                 | Not Necessary | 32.00 FL    | *- FL        |
| 60  | 1   |          | *MIRROR ASSY,DOOR,RH                           | Cut           | 824.00 FL   | *824.00 FL   |
| 61  | 1   |          | *COVER,DOOR MIRROR,OTR RH                      | Not Necessary | 101.00 FL   | *- FL        |
| 62  | 1   |          | *FENDER,FR RH                                  | Dented        | 541.00 FL   | *541.00 FL   |
| 63  | 1   |          | *FACE,FR BUMPER                                | Dented        | 718.00 FL   | *718.00 FL   |
| 64  | 1   |          | *GARNISH,FR BUMPER SIDE                        | Not Necessary | 214.00 FL   | *- FL        |
| 65  | 1   |          | *GARNISH,FR BUMPER SIDE                        | Not Necessary | 77.00 FL    | *- FL        |
| 66  | 1   |          | *HEADLAMP ASSY,RH                              | Cut           | 1,986.00 FL | *1,986.00 FL |
| 67  | 1   |          | *LAMP A,T/SIG & FOG,FR RH                      | Not Necessary | 506.00 FL   | *- FL        |
| 68  | 1   |          | *LAMP ASSY,COMB,RR RH                          | Broken        | 693.00 FL   | *693.00 FL   |
| 69  | 1   |          | *LAMP ASSY,FOG,RR RH                           | Not Necessary | 132.00 FL   | *- FL        |
| 70  | 1   |          | *WHEEL,DISC RHR                                | Cut           | 1,102.00 FL | *1,102.00 FL |
| 71  | 1   |          | *HUB ASSY,RHR WHEEL                            | Necessary     | 434.00 FL   | *434.00 FL   |
| 72  | 1   |          | *CROSSMEMBER,RR SUSP                           | Not Necessary | 1,198.00 FL | *- FL        |
| 73  | 1   |          | *ARM ASSY,RR SUSP,UPR                          | Bent          | 131.00 FL   | *131.00 FL   |
| 74  | 1   |          | *LINK RR SUSP ASSIST                           | Bent          | 79.00 FL    | *79.00 FL    |
| 75  | 1   |          | *ARM ASSY,RR SUSP TRAIL,RH                     | Bent          | 504.00 FL   | *504.00 FL   |
| 76  | 1   |          | *ARM ASSY,RR SUSP,LWR                          | Not Necessary | 174.00 FL   | *- FL        |
| 77  | 1   |          | *BAR,RR SUSP STABILIZER                        | Not Necessary | 285.00 FL   | *- FL        |
| 78  | 1   |          | *SHOCK ABSORBER RR SUSP                        | Bent          | 296.00 FL   | *296.00 FL   |
| 79  | 1   |          | *SENSOR,RR ABS,RH                              | Not Necessary | 315.00 FL   | *- FL        |
| 80  | 1   |          | *SUNDRIES                                      | Necessary     | 30.00 FS    | *30.00 FS    |
| 81  | 1   |          | *C&C BADGE                                     | Not Necessary | 40.00 FS    | *- FS        |
| 82  | 1   |          | *BODY PNL SEALANT                              | Necessary     | 80.00 FS    | *80.00 FS    |
| 83  | 1   |          | *RHR TYRE-YOKOHAMA BLUEARTH XT 225/55R18       | Torn          | 480.00 FS   | *480.00 FS   |
| 84  | 1   |          | *SIDE SILL,FR FLOOR,OTR RH<br>(Supplementary)  | Dented        | 792.00 FL   | *792.00 FL   |
| 85  | 1   |          | *DUCT,RR VENTILATOR<br>(Supplementary)         | Broken        | 39.00 FL    | *39.00 FL    |
| 86  | 1   |          | *SIDE EXTENSTION<br>(Supplementary)            | Dented        | 436.00 FL   | *436.00 FL   |
| 87  | 1   |          | *BRACE,RR PILLAR,RH<br>(Supplementary)         | Dented        | 57.00 FL    | *57.00 FL    |
| 88  | 1   |          | *REINF,RR PILLAR,RH<br>(Supplementary)         | Dented        | 477.00 FL   | *477.00 FL   |
| 89  | 1   |          | *REINF,RR PILLAR,LWR RH<br>(Supplementary)     | Dented        | 74.00 FL    | *74.00 FL    |
| 90  | 1   |          | *PANEL,QTR,LWR INR RH<br>(Supplementary)       | Dented        | 286.00 FL   | *286.00 FL   |
| 91  | 1   |          | *EXTENSION,QTR PANEL,INR RH<br>(Supplementary) | Dented        | 189.00 FL   | *189.00 FL   |
| 92  | 1   |          | *VALVE,TIRE<br>(Supplementary)                 | Necessary     | 40.00 FL    | *40.00 FL    |

F=Franchise part. S=SpcNett. L=ListItemDisc.

|                                                            |                  |                  |
|------------------------------------------------------------|------------------|------------------|
| <b>Sub Total (\$\$)</b>                                    | <b>21,895.00</b> | <b>15,271.00</b> |
| <b>- List Item Discount on L Items 23.00/23.00% (\$\$)</b> | 4,890.95         | 3,376.63         |
| <b>Total Parts (\$\$)</b>                                  | <b>17,004.05</b> | <b>11,894.37</b> |

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

| No                              | Particulars                                                                                                                                                                                         | Lab.Type | Repairer's       | Amount          |
|---------------------------------|-----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|----------|------------------|-----------------|
| <b>Labour Items</b>             |                                                                                                                                                                                                     |          |                  |                 |
| 1                               | RENEW RR BUMPER,RHR FENDER,RHR DOOR,RHF DOOR,RHF FENDER & FR BUMPER,REPAIR RH ROCKER PNL,RHR WHEELHOUSE,RH C PILLAR & ROOF TOP                                                                      | New      | 5,400.00         | 3,375.00        |
| 2                               | RESPRAY FR BUMPER,BONNET,ROOF TOP,TAILGATE,RR BUMPER,LHF FENDER,LHF DOOR,LHR DOOR,LHR FENDER,LH ROCKER PNL,RHF FENDER,RHF DOOR,RHR DOOR,RHR FENDER,RHR WHEELHOUSE PNL,RH ROCKER PNL & RH WINGMIRROR | New      | 5,950.00         | 2,100.00        |
| 3                               | REMOVE & REFIT RHR DOOR COMPONENT                                                                                                                                                                   | New      | 120.00           | 120.00          |
| 4                               | REMOVE & REFIT RHF DOOR COMPONENT                                                                                                                                                                   | New      | 120.00           | 120.00          |
| 5                               | RENEW RHR SPORT RIM                                                                                                                                                                                 | New      | 30.00            | 30.00           |
| 6                               | REMOVE & REFIT ALL RR SEAT,TRIM,CARPET & RR FLR BOARD                                                                                                                                               | New      | 450.00           | 450.00          |
| 7                               | REMOVE & REFIT ROOF LINING TO FACILITATE REPAIR                                                                                                                                                     | New      | 450.00           | 450.00          |
| 8                               | CHECK WIRING ELECTRICAL SYSTEM                                                                                                                                                                      | New      | 30.00            | 30.00           |
| 9                               | TO CARRY OUT DIAGNOSTIC CHECK ON ELECTRONIC CONTROL SYSTEM                                                                                                                                          | New      | 120.00           | 120.00          |
| 10                              | TO CONDUCT COMPUTERIZE FULL WHEEL ALIGNMENT                                                                                                                                                         | New      | 120.00           | 120.00          |
| 11                              | TO RENEW REAR U/CARRIAGE RH                                                                                                                                                                         | New      | 450.00           | 450.00          |
| 12                              | REMOVE & REFIT FR PARKING ASSIST SENSOR                                                                                                                                                             | New      | 80.00            | 80.00           |
| 13                              | REMOVE & REFIT REVERSE SENSOR                                                                                                                                                                       | New      | 80.00            | 80.00           |
| 14                              | APPLY ANTI CORROSION ON AFFECTED AREAS                                                                                                                                                              | New      | 120.00           | 40.00           |
| 15                              | REPLACE RH ROCKER PANEL & RH REAR INNER QUARTER PANEL<br>(Supplementary)                                                                                                                            | New      | 1,350.00         | 1,350.00        |
| 16                              | RESPRAY RH ROCKER PANEL & RH REAR INNER QUARTER PANEL<br>(Supplementary)                                                                                                                            | New      | 700.00           | 700.00          |
| <b>Gross Labour Cost (\$\$)</b> |                                                                                                                                                                                                     |          | <b>15,570.00</b> | <b>9,615.00</b> |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >