

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/AIG21008041/AVF3N2**Date:** 14/10/2021REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1900162308
Claimant Vehicle No :	SMQ5428Z	Insured Vehicle No :	SMP2455U
Date of Loss:	27/07/2021	Nature of Claim:	TP
		Claim No:	5589249198SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMQ5428Z	Engine No:	2ZRA678125
Make & Model:	TOYOTA WISH, 1.8 CVT (A)	Chassis No:	JTDGG20W305001673
Reg. Date:	14/02/2011 (Man. Year: 2011)	Odometer:	144370 km
Colour:	Grey		
Engine Capacity:	1798 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/65R15	Rear Tyre Size:	195/65R15
Front Left Side:	Nexen 6 mm	Rear Left Side:	Nexen 6 mm
Front Right Side:	Nexen 6 mm	Rear Right Side:	Nexen 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,559.25	2,994.00	4,565.25	60.39
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,320.00	1,550.00	1,770.00	53.31
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	10,879.25	4,544.00	6,335.25	58.23
Approved Total (Overridden) (S\$)		3,600.00		
Nett Amount (S\$)	10,879.25	3,600.00	7,279.25	66.91

INSPECTION

Date of Assignment:	29/07/2021	Jd Motorsports Pte Ltd (HQ)
Date Inspected:	02/08/2021 Inspected At:	25 KAKI BUKIT ROAD 4, #06-38 SYNERGY@KB
Estimated Period of Repair:	6.0 days	Singapore 417800

Adjuster: ADRIAN LING**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BONNET	Repair	825.00 FL	*- FL
2	1		*BONNET HINGES (LH)	Not Necessary	125.00 FL	*- FL
3	1		*FRONT BUMPER	Deformed	692.00 FL	*692.00 FL
4	1		*FRONT BUMPER SIDE RETAINER (LH)	Damaged	125.00 FL	*125.00 FL
5	1		*FRONT BUMPER BRACKET	Not Necessary	155.00 FL	*- FL
6	1		*FRONT BUMPER REINFORCEMENT	Bent	485.00 FL	*327.00 FL
7	1		*FRONT BUMPER SPONGE	Cracked	275.00 FL	*131.00 FL
8	1		*FRONT BUMPER LOWER GRILLE (LH)	Not Necessary	120.00 FL	*- FL
9	1		*FRONT BUMPER FOG LAMP ASSY (LH)	Not Necessary	380.00 FL	*- FL
10	1		*FRONT SUPPORT PANEL TOP GARNISH	Not Necessary	155.00 FL	*- FL
11	4		*FRONT SUPPORT PANEL TOP GARNISH CLIP	Not Necessary	30.00 FL	*- FL
12	1		*FRONT HEADLAMP (LH)	Cracked	1,038.00 FL	*1,038.00 FL
13	1		*FRONT HEADLAMP BRACKET (LH)	Not Necessary	88.00 FL	*- FL
14	1		*FRONT HEADLAMP PANEL (LH)	Repair	433.00 FL	*- FL
15	1		*FRONT FENDER (LH)	Dented	975.00 FL	*796.00 FL
16	1		*FRONT FENDER INNER SHIELD (LH)	Deformed	255.00 FL	*255.00 FL
17	8		*FRONT FENDER INNER SHIELD CLIP (LH)	Necessary	28.00 FL	*28.00 FL
18	1		*FRONT FENDER QUARTER GLASS	Not Necessary	285.00 FL	*- FL
19	1		*FRONT SHOCK ABSORBER (LH)	Not Necessary	535.00 FL	*- FL
20	1		*FRONT LOWER ARM (LH)	Not Necessary	569.00 FL	*- FL
21	1		*FRONT KNUCKLE ARM (LH)	Not Necessary	538.00 FL	*- FL
22	1		*FRONT KNUCKLE ARM BEARING (LH)	Not Necessary	295.00 FL	*- FL
23	1		*FRONT STABILIZER BAR LINKAGE (LH)	Not Necessary	238.00 FL	*- FL
24	1		*FRONT TIE ROD END (LH)	Not Necessary	195.00 FL	*- FL
25	1		*FRONT SPORTS RIMS (LH)	Cut	550.00 FS	*450.00 FS
26	1		*FRONT TYRES (LH)	Not Necessary	380.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	9,769.00	3,842.00
- List Item Discount on L Items 25.00/25.00% (\$\$)	2,209.75	848.00
Total Parts (\$\$)	7,559.25	2,994.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO SUPPLY LABOUR AND PARTS TO REPAIR AND REPLACE ABOVE MENTIONED PARTS	New	1,600.00	700.00
2	TO SUPPLY LABOUR AND PAINT TO SPRAY ACCIDENT AFFECTED AREA	New	900.00	700.00
3	TO SUPPLY LABOUR TO RE-WIRE REPLACE PARTS	New	90.00	30.00
4	TO SUPPLY LABOUR TO SPRAY ANTI RUST ON PANEL	New	90.00	40.00
5	TO SUPPLY LABOUR TO REPLACE UNDER CARRIAGE PARTS	New	280.00	0.00
6	TO SUPPLY LABOUR TO CONDUCT WHEEL ALIGNMENT	New	180.00	80.00
7	TO SUPPLY LABOUR TO STRAIGHTEN CHASSIS FRAME	New	180.00	0.00
Gross Labour Cost (S\$)			3,320.00	1,550.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >