

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/GRB21008042/EES3Q2
Date: 06/10/2021**REFERENCE**

Handling Insurer:	India International Insurance Pte Ltd	Policy No:	D21MFL0000447
Claimant Vehicle No :	SLS2197K	Insured Vehicle No :	SLU2573Y
Date of Loss:	09/07/2021	Nature of Claim:	TP
		Claim No:	MFL2021D0002958

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLS2197K		
Make & Model:	KIA CERATO, 1.6 (A)	Engine No:	G4FGHH678895
Reg. Date:	14/09/2017 (Man. Year: 2017)	Chassis No:	KNAFZ411MJ5740972
Colour:	Blue	Odometer:	95498 km
Engine Capacity:	1591 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	215/45Z R17	Rear Tyre Size:	215/45Z R17
Front Left Side:	Toyo 4 mm	Rear Left Side:	Toyo 4 mm
Front Right Side:	Toyo 4 mm	Rear Right Side:	Toyo 4 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,750.00	4,326.00	1,424.00	24.77
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,110.00	3,965.00	2,145.00	35.11
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	11,860.00	8,291.00	3,569.00	30.09
+ GST 7.00/7.00% (S\$)	830.20	580.37	249.83	30.09

Nett Amount (S\$)	12,690.20	8,871.37	3,818.83	30.09
+ Car Rental (7.0 x S\$100.00/day + 7.00% GST) (S\$)		749.00		
+ Doc/Search Fee (S\$)		7.45		
+ Medical Report (S\$)		216.10		
Nett Liability (S\$)		9,843.92		

INSPECTION

Date of Assignment: 29/07/2021

Date Inspected: 29/07/2021

Estimated Period of Repair: 4.0 days

Inspected At:

Cycle & Carriage KIA Pte Ltd (Pandan Gardens)
 209 Pandan Gardens
 Singapore 609339

Adjuster: CHEN TSUE YEE**Manager:** Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 31 Aug 2021)
Parts:	143	KIA CERATO 1.6 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLS2197K)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BODY PNL SEALANT	Not Necessary	80.00 FS	*- FS
2	1		*SUNDRIES	Necessary	50.00 FS	*20.00 FS
3	1		*NEW K3 GRAVITY BLUE B4U	Repair	1,177.00 FS	*- FS
4	1		*PANEL -FENDER ,RH	Dented	435.00 FS	*435.00 FS
5	1		*GUARD ASSY -FRONT WHEEL ,RH	Not Necessary	95.00 FS	*- FS
6	1		*LAMP ASSY ,HEAD ,RH	Cut	2,209.00 FS	*2,209.00 FS
7	1		*COVER -FR BUMPER	Broken	633.00 FS	*633.00 FS
8	1		*STRIP ASSY -FR BUMPER UPR	Not Necessary	29.00 FS	*- FS
9	1		*BRACKET -FR BUMPER SIDE MTG ,RH	Not Necessary	13.00 FS	*- FS
10	1		*WHEEL ASSY -ALUMINIUM	Cut	981.00 FS	*981.00 FS
11	1		*ORNAMENT -KIA NO.115	Necessary	32.00 FS	*32.00 FS
12	8		*CLIP	Necessary	16.00 FS	*16.00 FS

F=Franchise part. S=SpcNett.

Total Parts (\$\$)	5,750.00	4,326.00
---------------------------	-----------------	-----------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	RENEW FR BUMPER ,FR BUMPER BODY KIT & RHF FENDER REPAIR RHF DOOR	New	2,560.00	1,280.00
2	RESPRAY RHF DOOR ,RHF FENDER ,FR BUMPER & FR BUMPER BODY KIT	New	2,750.00	1,925.00
3	RENEW RHF SPORT RIM & TRANSFER TYRE	New	80.00	80.00
4	CHECK WIRING ELECTRICAL SYSTEM	New	80.00	80.00
5	TO CARRY OUT DIAGNOSTIC CHECK ON ELECTRICAL CONTROL SYSTEM	New	300.00	300.00
6	TO CONDUCT COMPUTERIZE WHEEL ALIGNMENT	New	180.00	180.00
7	REMOVE & REFIT FR PARKING ASSIST SENSOR	New	80.00	80.00
8	APPLY ANTI CORROSION ON AFFECTED AREAS	New	80.00	40.00
Gross Labour Cost (S\$)			6,110.00	3,965.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >