

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/AIG21008044/URA3Q2
Date: 26/10/2021**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1900251601
Claimant Vehicle No :	SDM2028S	Insured Vehicle No :	SJA919B
Date of Loss:	28/07/2021	Nature of Claim:	TP
		Claim No:	4825882077SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SDM2028S	Engine No:	B4204T231817293
Make & Model:	VOLVO S90, 2.0 T5 Momentum (A)	Chassis No:	YV1PS10BDH1007844
Reg. Date:	23/12/2016 (Man. Year: 2016)	Odometer:	135202 km
Colour:	White		
Engine Capacity:	1969 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	245/45 R18	Rear Tyre Size:	245/45 R18
Front Left Side:	Pirelli 6 mm	Rear Left Side:	Pirelli 6 mm
Front Right Side:	Pirelli 6 mm	Rear Right Side:	Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,652.00	2,556.45	1,095.55	30.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,885.00	1,250.00	1,635.00	56.67
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	6,537.00	3,806.45	2,730.55	41.77
Approved Total (Overridden) (S\$)		3,000.00		

(S\$)	6,537.00	3,000.00	3,537.00	54.11
+ GST 7.00/7.00% (S\$)	457.59	210.00	247.59	54.11
Nett Amount (S\$)	6,994.59	3,210.00	3,784.59	54.11
+ Car Rental (3.0 x S\$150.00/day + 7.00% GST) (S\$)		481.50		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		3,693.50		
Global Sum Settlement (S\$)		3,650.00		

INSPECTION

Date of Assignment: 10/08/2021

Date Inspected: 10/08/2021

Estimated Period of Repair: 3.0 days

Inspected At:

Specialists Motor Pte Ltd (HQ)
Blk 3018A Ubi Road 1, #01-24/25/26
Singapore 408711

Adjuster: MARCUS CHUA**Manager:** Jaslin Kok Chin Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR LAMP ASSY RH	Cracked	700.00 F	*689.00 FL
2	1		*REAR BUMPER FASCIA	Deformed / Warped	1,800.00 F	*1,795.00 FL
3	1		*SET REAR BUMPER CLIPS	Necessary	60.00 F	*60.00 FL
4	1		*REAR BUMPER SIDE RETAINER RH	Not Necessary	39.00 F	*- FL
5	2		*REAR BUMPER SENSOR	Shorted (1 PCS ONLY)	294.00 F	*147.00 FL
6	1		*REAR BUMPER DIFFUSER	Not Necessary	300.00 F	*- FL
7	1		*REAR END PANEL	Repair	163.00 F	*- FL
8	1		*REAR BOOT COVER EMBLEM (T5)	Not Necessary	72.00 F	*- FL
9	1		*REAR BOOT COVER EMBLEM (S90)	Not Necessary	69.00 F	*- FL
10	1		*REAR BOOT COVER EMBLEM (VOLVO)	Not Necessary	75.00 F	*- FL
11	1		*REAR END PANEL SEALER	Not Necessary	80.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	3,652.00	2,691.00
- List Item Discount on L Items 0.00/5.00% (\$)	0.00	134.55
Total Parts (\$)	3,652.00	2,556.45

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	CUT OUT RENEW KNOCKING & WELDING REAR FENDER RH ,REAR END PANEL,REMOVE & INSTALL ALL DAMAGE PARTS & REALIGN BODY	New	1,080.00	500.00
2	TUFF-KOTE ON DAMAGE PARTS	New	80.00	0.00
3	REMOVE & INSTALL REAR BUMPER SENSOR	New	100.00	50.00
4	SPRAY PAINTING ON DAMAGE PARTS	New	1,280.00	600.00
5	CHECK ALL LIGHTING AFTER REPAIRS	New	45.00	20.00
6	DIAGNOSTIC & RESET	New	300.00	80.00
Gross Labour Cost (S\$)			2,885.00	1,250.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >