

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/AIG21008047/KGA3Q2
Date: 18/10/2021**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1900050049-02
Claimant Vehicle No :	SMT7002P	Insured Vehicle No :	GBJ3038X
Date of Loss:	20/07/2021	Nature of Claim:	TP
		Claim No:	3355485431SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMT7002P		
Make & Model:	LEXUS RX300, 2.0 5DR SUV (4WD) LUXURY (A)	Engine No:	8AR4301382
Reg. Date:	14/07/2020 (Man. Year: 2020)	Chassis No:	JTJBAMCA702112460
Colour:	Metallic Grey	Odometer:	8472 km
Engine Capacity:	1998 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	235/55 R20	Rear Tyre Size:	235/55 R20
Front Left Side:	Dunlop 9 mm	Rear Left Side:	Dunlop 9 mm
Front Right Side:	Dunlop 9 mm	Rear Right Side:	Dunlop 9 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,385.00	1,818.80	566.20	23.74
Miscellaneous Items	0.00	0.00	0.00	
Labour	780.00	485.00	295.00	37.82
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	3,165.00	2,303.80	861.20	27.21
Approved Total (Overridden) (S\$)		1,850.00		

(S\$)	3,165.00	1,850.00	1,315.00	41.55
+ GST 7.00/7.00% (S\$)	221.55	129.50	92.05	41.55
Nett Amount (S\$)	3,386.55	1,979.50	1,407.05	41.55
+ Loss of Use (3.0 x S\$80.00/day) (S\$)		240.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		2,221.50		
Global Sum Settlement (S\$)		2,200.00		

INSPECTION

Date of Assignment: 29/07/2021

Date Inspected: 29/07/2021

Estimated Period of Repair: 2.0 days

Inspected At: Optima Werkz Pte Ltd (HQ)
6 Kung Chong Road
Singapore 159143

Adjuster: KENNETH KONG**Manager:** Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Buckled	996.00 FL	*996.00 FL
2	1		*REAR BUMPER LOWER LIP COVER	Dented / Cut	708.00 FL	*525.00 FL
3	1		*REAR BUMPER GARNISH COVER LH	Dented	211.00 FL	*211.00 FL
4	1		*REAR BUMPER REFLECTOR LH	Serviceable	75.00 FL	*- FL
5	1		*REAR EXHAUST TAIL LH	Serviceable	260.00 FL	*- FL
6	1		*REAR BUMPER CLIPS	Necessary	60.00 FS	*60.00 FS
7	1		*REAR BUMPER REVERSE SENSOR	Shorted	300.00 FS	*200.00 FS
					Sub Total (\$\$)	2,610.00
					- List Item Discount on L Items 10.00/10.00% (\$\$)	225.00
					Total Parts (\$\$)	2,385.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	LABOUR CHARGES TO REMOVE ,REPLACE ,REFIX & READJUST REAR ACCIDENT AREAS & ETC	New	300.00	200.00
2	LABOUR CHARGES FOR PAINTING & TO SUPPLY PAINT & FURNISHING MATERIALS AT REAR BUMPER & ETC	New	300.00	220.00
3	LABOUR CHARGES TO REMOVE & REPLACE REAR BUMPER REVERSE SENSOR & ETC	New	100.00	50.00
4	TO CHECK WIRING & ELECTRICAL SYSTEM & ETC	New	80.00	15.00
Gross Labour Cost (\$\$)			780.00	485.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >