

Date: 27.07.2021
 Vehicle No: SMT7002P
 Model: LEXUS RX300 SUV
 Chassis: JTJBAMCA702112460-2020
 Reg.Year: 2020

Third Party Insurer: AIG
 Third Party Veh No: GBJ3038X
 Date of Accident: 20.07.2021
 Estimator: TING AN
 Surveyor:

Not Notwork
Recovery B4 paint

2 days

ESTIMATE

NO.	DESCRIPTION	QTY	UNIT S\$	AMOUNT S\$
1	REAR BUMPER	1		<i>Bu</i> \$996.00
2	REAR BUMPER LOWER LIP COVER	1		<i>Nil / G</i> \$708.00
3	REAR BUMPER GARNISH COVER LH	1		<i>Nil</i> \$211.00
4	REAR BUMPER REFLECTOR LH	1		<i>IL</i> \$75.00
5	REAR EXHAUST TAIL LH	1		\$260.00
SUB TOTAL				\$2,250.00
LESS 10%				-\$225.00
PARTS TOTAL				\$2,025.00

NO.	SPECIAL NETT	QTY	UNIT S\$	AMOUNT S\$
1	REAR BUMPER CLIPS	1		<i>m</i> \$60.00
2	REAR BUMPER REVERSE SENSOR	1		\$300.00
S/N TOTAL				\$360.00

LABOUR CHARGES:

LABOUR CHARGES TO REMOVE, REPLACE, REFIX & READJUST REAR ACCIDENT AREAS & ETC. \$300.00 *200*

LABOUR CHARGES FOR PAINTING & TO SUPPLY PAINT & FURNISHING MATERIALS AT REAR BUMPER & ETC. \$300.00 *220*

LABOUR CHARGES TO REMOVE & REPLACE REAR BUMPER REVERSE SENSOR & ETC. \$100.00 *50*

TO CHECK WIRING & ELECTRICAL SYSTEM & ETC. \$80.00 *15*

LABOUR TOTAL \$780.00

VIC / TING AN TOTAL \$3,165.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed

• Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Head office

6 Kung Chong Road Singapore 159143

Tel: (+65) 6472 1313 | Fax: (+65) 6472 2112

9A Serangoon North Ave 5 Singapore 554500

Tel: (+65) 6484 9919 | Fax: (+65) 6481 1993

Branch (Motor Insurance Claims)

Blk 10 Ang Mo Kio Ind. Park 2A #01-05 Singapore 568047

Tel: (+65) 6481 1522 | Fax: (+65) 6481 1011

