



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMM 304B

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b><u>REPLACEMENT OF PARTS</u></b>			
1	REAR BUMPER (CONSISTENT)	DEFORMED	828.90	828.90
2	REAR BUMPER SIDE HOLDER @\$32.00 (CONSISTENT)	NOT NECESSARY	64.00	-
1	SPARE TYRE PANEL UNDERCOVER (CONSISTENT)	NOT NECESSARY	241.20	-
	LESS 20% DISCOUNT		-	-165.78
			1,134.10	663.12
	<b><u>SPECIAL NETT ITEMS</u></b>			
1	REAR BUMPER CLIPS (SN) (CONSISTENT)	NOT NECESSARY	30.00	-
1	REAR BUMPER TOP CHROME (SN) (CONSISTENT)	BENT	180.00	150.00
1	REVERSE SENSOR (SN) (CONSISTENT)	NOT NECESSARY	280.00	-
1	SPARE TYRE PANEL UNDERCOVER CLIPS (SN) (CONSISTENT)	NOT NECESSARY	30.00	-
			520.00	150.00
	<b><u>LABOUR</u></b>			
	PANEL BEATING.		400.00	200.00
	SPRAY PAINTING.		400.00	200.00
	WIRING.		50.00	30.00
	TO REMOVE REVERSE SENSOR .		100.00	50.00
			950.00	480.00
	<b>GRAND TOTAL</b>		<b>2,604.10</b>	<b>1,293.12</b>
	<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>			<b>1,000.00</b>

Report Ref No. CC4/ASM21008052/Ags3q2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.