



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. PC 3100U

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b><u>REPLACEMENT OF PARTS</u></b>			
1	WORKART (CONSISTENT)	NECESSARY	500.00	300.00
1	FRONT BUMPER (CONSISTENT)	TO REPAIR SEE LABOUR	1,384.00	-
1	FRONT WINDSCREEN (CONSISTENT)	CRACKED	4,370.30	4,370.30
1	FRONT WINDSCREEN RUBBER (CONSISTENT)	NECESSARY	262.30	262.30
8	SEALANT @\$42.70 (CONSISTENT)	NECESSARY	341.60	341.60
1	SET RHS WING MIRROR (CONSISTENT)	CRACKED	1,591.99	1,591.99
			8,450.19	6,866.19
	<b><u>LABOUR</u></b>			
	REPAIR LABOUR FOR FRONT AND RHS PORTIONS.		3,500.00	2,560.00
	SPRAY PAINTING FOR FRONT AND RHS PORTION .		2,500.00	2,200.00
	WIRING.		80.00	80.00
	LABOUR FOR FRONT WINDSCREEN.INCLUSIVE OF THE REPAIR OF FRONT BUMPER.		700.00	500.00
			6,780.00	5,340.00
	<b>GRAND TOTAL</b>		<b>15,230.19</b>	<b>12,206.19</b>
	<b>RECOMMENDED COST OF REPAIRS</b>			<b>12,206.19</b>

Report Ref No. CC4/ASM18017663/T1ga3q2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.