



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AXA INSURANCE PTE LTD 8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811 ATTN:RICHARD ANG			Ref: CC4/ASM18017663/T1ga3q2 Date: 12/12/2019 Code: ASM	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
Insured Veh.	PC 8811T	Veh. Inspected	PC 3100U	
Policy No.	VFX/P2061409	Coverage (\$)	0.00	
Claim No.	S8M00X3W	Excess (\$)	0.00	
Assign From		Assign Date	27/09/2018	
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model	ISUZU LT434P	c.c	7790	
Engine No.	HIDDEN	Year of Reg.	2015	
Chassis No.	JALLT434PE7000082	Colour	SILVER	
Odometer	230143 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	GOOD			
<b>3. Conditions of Tyres</b>				
	Size	Make	Balance	
R/H Front Tyre	295/80 R22.5	BRIDGESTONE	8 mm	
L/H Front Tyre	295/80 R22.5	BRIDGESTONE	8 mm	
R/H Rear Tyre	295/80 R22.5 (D)	BRIDGESTONE	8/8 mm	
L/H Rear Tyre	295/80 R22.5 (D)	BRIDGESTONE	8/8 mm	
<b>4. Description of Damages</b>				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT O/S PORTION.  DAMAGES SEE DETAILS.				
<b>5. General Information</b>				
Accident Date	25/09/2018	Inspection Date	28/09/2018	
Survey held at	SC AUTO INDUSTRIES (S) PTE LTD 51, SENOKO ROAD SINGAPORE 758133			
<b>5a. Remarks</b>				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
<b>5b. Estimate Days of Repair</b>				
ESTIMATED NORMAL PERIOD FOR REPAIR:			4 Working Days	