



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. FBM 3746U

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b><u>REPLACEMENT OF PARTS</u></b>			
1	FRONT FLASHER LAMP LH	SCRATCHED	108.00	65.00
1	FRONT FLASHER LAMP RH	SERVICEABLE	108.00	-
1	WING MIRROR RH	SERVICEABLE	118.00	-
1	HANDLE BAR	SERVICEABLE	192.00	-
1	LH CLUTCH LEVER	SCRATCHED	85.00	58.00
1	RIDER FOOT REST (RH)	MISSING	65.00	40.00
1	RIDER FOOT REST BRACKET (RH)	SCRATCHED	120.00	120.00
1	RIDER FOOT REST (LH)	DISTORTED	65.00	40.00
1	RIDER FOOT REST BRACKET (LH)	CUT	120.00	120.00
1	GEAR PEDAL	SERVICEABLE	85.00	-
1	BRAKE PEDAL	BENT	90.00	65.00
1	EXHAUST COVER WITH CHROME	SCRATCHED	120.00	120.00
1	ENGINE CRANK CASE	SCRATCHED	185.00	135.00
2	ENGINE CRANK CASE GASKET	NECESSARY	85.00	35.00
1	SET LH COVER	SCRATCHED	220.00	220.00
1	SET RH COVER	SERVICEABLE	220.00	-
	LESS 10% DISCOUNT		-198.60	-101.80
			<b>1,787.40</b>	<b>916.20</b>
	<b><u>SPECIAL NETT ITEMS</u></b>			
1	FRONT FORK SEAL (SN)	NOT NECESSARY	60.00	-
1	FRONT FORK OIL (SN)	NOT NECESSARY	80.00	-
1	SET HAND GUARD (SN)	N/S SCRATCHED	250.00	120.00
1	ENGINE GUARD (TOP) (SN) }	SCRATCHED	280.00	250.00
1	ENGINE GUARD (BOTTOM) (SN) }		350.00	-
1	BTL ENGINE OIL (SN)	NECESSARY	80.00	50.00
1	REAR BOX (SN)	SCRATCHED	450.00	150.00
1	REAR BOX BRACKET (SN)	SERVICEABLE	165.00	-
1	ERP UNIT (SN)	SCRATCHED	170.00	130.00
1	ERP UNIT BRACKET (SN)	NOT NECESSARY	68.00	-
1	SET BODY STICKER (SN)	NECESSARY	220.00	150.00

Report Ref No. CS/SMR21008056/R1uf3e2



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	NO. PLATE (FRONT) (SN)	NOT NECESSARY	30.00	-
			2,203.00	850.00
	<b><u>LABOUR</u></b>			
	TO REALIGN FRONT FORK.		150.00	80.00
	TO REPAIR AND REPLACE ENGINE CRANK CASE.		300.00	120.00
	TO R&R FRONT SUSPENSION, HANDLE BAR, HEADLAMP, SIDE FAIRING, AND ATTACHEMENTS.		400.00	300.00
			850.00	500.00
<b>GRAND TOTAL</b>			<b>4,840.40</b>	<b>2,266.20</b>
<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>				<b>1,800.00</b>

Report Ref No. CS/SMR21008056/R1uf3e2

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

ANG BRYAN TANI

Automotive Assessor / Investigator

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.