

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/MSG21008060/DVF3N2**Date:** 05/05/2022REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	1000891448
Claimant Vehicle No :	SHC3548G	Insured Vehicle No :	SJV7422K
Date of Loss:	27/07/2021	Nature of Claim:	TP
		Claim No:	260589

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHC3548G	Engine No:	G4LEKU402412
Make & Model:	HYUNDAI AE IONIQ HEV FL, 1.6 DCT (A)	Chassis No:	KMHC851CVLU188129
Reg. Date:	07/11/2019 (Man. Year: 2019)	Odometer:	0 km
Colour:	Blue		
Engine Capacity:	1580 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/65R15	Rear Tyre Size:	195/65R15
Front Left Side:	West Lake 5 mm	Rear Left Side:	West Lake 5 mm
Front Right Side:	West Lake 5 mm	Rear Right Side:	West Lake 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	58,758.72	33,659.28	25,099.44	42.72
Miscellaneous Items	0.00	0.00	0.00	
Labour	7,460.00	2,830.00	4,630.00	62.06
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	66,218.72	36,489.28	29,729.44	44.90
Approved Total (Overridden) (S\$)		29,000.00		
(S\$)	66,218.72	29,000.00	37,218.72	56.21
+ GST 7.00/7.00% (S\$)	4,635.31	2,030.00	2,605.31	56.21
Nett Amount (S\$)	70,854.03	31,030.00	39,824.03	56.21

INSPECTION

Date of Assignment:	29/07/2021	
Date Inspected:	30/07/2021	Inspected At: Bifrost Auto Pte Ltd (sin Ming) (HQ) Blk 9 Sector C, #01-42 Sin Ming Industrial Estate Singapore 575644
Estimated Period of Repair:	14.0 days	

Adjuster: BRYAN TANI**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 11 Mar 2022)
Parts:	143	HYUNDAI AE IONIQ HEV FL 1.6 DCT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SHC3548G)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BONNET	Bent/Dented	2,253.80 FL	*2,253.80 FL
2	2		*BONNET HINGE (LH/RH)	Bent	237.40 FL	*237.40 FL
3	1		*BONNET MOULDING	Not fitted	41.40 FL	*- FL
4	1		*BONNET LOCK	Bent	127.30 FL	*127.30 FL
5	1		*BONNET INSULATOR	Deformed/Broken	230.10 FL	*230.10 FL
6	1		*BONNET INSULATOR CLIPS	Necessary	15.00 FL	*15.00 FL
7	1		*BONNET CABLE	Not Necessary	135.60 FL	*- FL
8	1		*RADIATOR GRILLE NEW MODEL	Dislodged	1,568.60 FL	*1,568.60 FL
9	2		*FLAP ASSY ACTIVE AIR UPPER (LH/RH)	Dislodged	1,649.20 FL	*712.00 FL
10	1		*SPEAKER ASSY-VESS	Cracked	554.40 FL	*554.40 FL
11	1		*UNIT ASSY-SMART CRU (RADAR SENSOR)	Not Necessary	2,910.90 FL	*- FL
12	1		*FLAP ASSY ACTIVE WIRE	Dislodged/Torn	765.30 FL	*765.30 FL
13	1		*FRONT NUMBER PLATE GARNISH	Dislodged	188.00 FL	*188.00 FL
14	1		*FRONT BUMPER COVER	Dislodged	418.30 FL	*418.30 FL
15	1		*FRONT BUMPER TOP COVER	Dislodged	476.30 FL	*476.30 FL
16	1		*FRONT BUMPER SPONGE	Dislodged	186.90 FL	*186.90 FL
17	1		*FRONT BUMPER REINFORCEMENT	Dented	1,075.10 FL	*394.80 FL
18	2		*FRONT BUMPER REINFORCEMENT ABSORBER (LH/RH)	Dented	373.00 FL	*373.00 FL
19	1		*FRONT BUMPER TOWING COVER	Dislodged	29.00 FL	*29.00 FL
20	1		*FRONT BUMPER MOULDING CENTRE UPPER	Dislodged	368.50 FL	*368.50 FL
21	1		*FRONT BUMPER MOULDING	No such part	93.60 FL	*- FL
22	1		*FRONT BUMPER LOWER STIFFNER	Bent	285.10 FL	*285.10 FL
23	1		*FRONT BUMPER LOWER GRILLE	Dislodged	365.30 FL	*365.30 FL
24	1		*FRONT BUMPER LOWER GRILLE MOULDING	Dislodged	127.60 FL	*127.60 FL
25	1		*FRONT BUMPER LIP	Dislodged	35.10 FL	*35.10 FL
26	2		*FRONT BUMPER BRACKET TOP (LH/RH)	Dislodged	70.00 FL	*70.00 FL
27	1		*FRONT BUMPER BRACKET (LH/RH)	Ns Dislodged/Os Not Necessary	56.00 FL	*28.00 FL
28	2		*FRONT BUMPER RETAINER MOUNTING (LH/RH)	Not Necessary	130.60 FL	*- FL
29	10		*FRONT BUMPER CLIPS	Necessary	25.00 FL	*25.00 FL
30	2		*FRONT BUMPER GRILLE (LH/RH)	Dislodged	373.80 FL	*373.80 FL
31	2		*FRONT BUMPER AIR DUCT (LH/RH)	Dislodged	307.60 FL	*307.60 FL
32	1		*DAY LIGHT,LH	Dislodged	642.50 FL	*642.50 FL
33	1		*DAY LIGHT,RH	Dislodged	642.50 FL	*642.50 FL
34	1		*DAY LIGHT,WIRE	Dislodged	585.50 FL	*585.50 FL
35	1		*BUZZER ASSY,PIEZO (LH)	Not Necessary	388.00 FL	*- FL
36	1		*HEADLAMP SUPPORT PANEL ASSY	Broken	949.30 FL	*949.30 FL
37	2		*HEADLAMP (LH/RH)	O/s Cracked/N/s Dislodged	7,974.60 FL	*4,795.20 FL
38	2		*HORN UNIT (LH/RH)	Cracked/Broken	145.60 FL	*145.60 FL
39	1		*HORN WIRE	Not Necessary	386.70 FL	*- FL
40	1		*RADIATOR INVERTER	Bent	884.80 FL	*884.80 FL
41	1		*RADIATOR	Bent	710.50 FL	*710.50 FL
42	1		*RADIATOR FAN BLOWER MOTOR ASSY	Broken	1,226.60 FL	*1,226.60 FL
43	2		*RADIATOR AIR GUIDE (LH/RH)	Deformed	152.80 FL	*152.80 FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
44	2		*RADIATOR AIR GUIDE,UPR (LH/RH)	Not Necessary	255.00 FL	*- FL
45	1		*RADIATOR HOSE UPPER	Not Necessary	166.20 FL	*- FL
46	1		*RADIATOR HOSE LOWER	Not Necessary	156.20 FL	*- FL
47	1		*RADIATOR TANK RESERVOIR	Not Necessary	196.50 FL	*- FL
48	1		*FRONT FENDER (LH/RH)	O/s Dented/N/s Not Necessary	981.40 FL	*490.70 FL
49	1		*FRONT FENDER APRON PANEL (LH)	Not Necessary	756.20 FL	*- FL
50	1		*FRONT FENDER APRON PANEL UPPER (LH)	Not Necessary	329.00 FL	*- FL
51	1		*FRONT FENDER SHIELD (LH/RH)	Os Dislodged/Ns Not Necessary	329.40 FL	*164.70 FL
52	1		*AIRCON CONDENSER	Bent	663.60 FL	*663.60 FL
53	1		*AIRCON SUCTION & LIQUID HOSE	Bent	679.60 FL	*679.60 FL
54	1		*AIRCON METAL HOSE-SMALL	Not Necessary	186.50 FL	*- FL
55	1		*AIRCON METAL HOSE-BIG	Not Necessary	352.10 FL	*- FL
56	1		*FRONT WINDSCREEN MOULDING	Not Necessary	157.30 FL	*- FL
57	1		*FRONT WINDSCREEN PILLAR OUTER RH	Dented	3,764.90 FL	*310.70 FL
58	1		*WIPER CONTAINER ASSY	Deformed	385.40 FL	*385.40 FL
59	1		*DASHBOARD COMPLETE	Broken	4,724.00 FL	*1,474.00 FL
60	1		*PASSENGER AIR BAG	Activated	2,633.00 FL	*1,951.20 FL
61	1		*WIRING-ENGINE	Not Necessary	3,474.00 FL	*- FL
62	1		*STEERING AIRBAG COMPLETE	Activated	1,090.90 FL	*1,090.90 FL
63	1		*AIRBAG CONTROL MODULE	Activated	1,243.70 FL	*1,243.70 FL
64	1		*KNEE CONTROL AIRBAG MODULE ASSY	Activated	578.60 FL	*578.60 FL
65	1		*AIR BAG ASSY-PASSENGER	Repeated	1,951.20 FL	*- FL
66	1		*STEERING ANGLE ASSY	Activated	786.90 FL	*786.90 FL
67	1		*SENSOR ASSY IMPACT-FRT INPACT	Activated	643.90 FL	*643.90 FL
68	2		*AIRBAG SENSOR (LH/RH)	Not Necessary	696.20 FL	*- FL
69	1		*HYBRID SPARE TANK	Not Necessary	371.30 FL	*- FL
70	2		*FRT SAFETY BELT (ASSY)(LH/RH)	Activated	1,297.80 FL	*1,297.80 FL
71	2		*REAR SAFETY BELT (ASSY)(LH/RH)	Activated	1,026.40 FL	*1,026.40 FL
72	2		*FRONT FENDER UPPER GARNISH (LH/RH)	Not Necessary	535.00 FL	*- FL
73	1		*AIR CLEANER HOAUING ASSY	Broken	1,636.50 FL	*836.50 FL
74	1		*FRT DOOR RH	Dented	1,797.20 FL	*1,797.20 FL
75	1		*ELECTRONIC CLUTCH PUMP	Damaged/Broken	4,386.50 FL	*4,386.50 FL
76	1		*ELECTRONIC CLUTCH PUMP-INVERTER HPCU	Broken	864.30 FL	*864.30 FL
77	2		*FRONT CHASSIS MEMBER LH/RH	Repair	3,727.00 FL	*- FL
78	1		*FRONT DOOR COMFORT LOGO RH	Necessary	75.00 FS	*75.00 FS
79	1		*FRONT NO PLATE TRIM COVER }	Dislodged	30.00 FS	*45.00 FS
80	1		*FRONT NUMBER PLATE }	Dislodged	25.00 FS	*- FS
81	1		*COOLANT	Not Necessary	45.00 FS	*- FS
82	2		*EMBLEM-BLUE DRIVE (LH/RH)	Not Necessary	53.20 FS	*- FS
83	1		*FRONT WINDSCREEN SEALANT	Not Necessary	46.00 FS	*- FS
84	1		*FRONT ERP STICKER	Not Necessary	30.00 FS	*- FS
85	1		*INVERTER COOLANT	Not Necessary	65.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$) 73,356.10 42,044.10
- List Item Discount on L Items 20.00/20.00% (S\$) 14,597.38 8,384.82

Total Parts (S\$) 58,758.72 33,659.28

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING	New	1,800.00	1,200.00
2	SPRAY PAINTING CHARGE	New	1,600.00	1,000.00
3	WIRING CHARGE	New	100.00	30.00
4	TUFF KOTE	New	100.00	40.00
5	TOWING CHARGE	New	80.00	0.00
6	FOUR WHEEL ALIGNMENT	New	120.00	0.00
7	REMOVE/REFIX UNDERCARRIAGE (FRT)	New	400.00	0.00
8	RE-SET FRT ABS SYSTEM	New	200.00	0.00
9	REMOVE/REFIX RADIATOR	New	90.00	50.00
10	REMOVE/REFIX AIRCON & REFILL GAS	New	130.00	80.00
11	REMOVE/REFIX FUSE BOX	New	120.00	0.00
12	REMOVE/REFIX FRONT WINDSCREEN GLASS	New	120.00	0.00
13	REMOVE/REFIX ENGINE	New	600.00	0.00
14	REMOVE/REFIX DASHBOARD }	New	350.00	250.00
15	REMOVE/REFIX AIR BAG/STEERING WHEEL DASHBOARD/SEAT }	New	550.00	0.00
16	DIAGNOSTIC & RESETTING TO ERASE FAULT CODE }	New	550.00	180.00
17	DIAGNOSTIC & RESETTING ADAS OPTICAL SENSOR }	New	550.00	0.00
Gross Labour Cost (\$\$)			7,460.00	2,830.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >