

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT					
	AXA INSURANCE PTE LTD		Ref:	CS3/ASM21008062/R1uce2	
	8 SHENTON WAY #24-01 AXA TOWER SINGAPORE 068811		Date	: 07/10/2021	
	ATTN: CHAN KIAN	I CHUAN	Code	e: ASM	
1.	Policy Particulars :- (THIRD PARTY CLAIM)				
	Insured Veh.	SHC 3248Y	Veh. Inspected	JTR 355	
	Policy No.	VFX/P2419138	Coverage (\$)	0.00	
	Claim No.	S1M03EKN	Excess (\$)	0.00	
	Assign From	CHAN KIAN CHUAN	Assign Date	29/07/2021	
2.	Vehicle Particulars & Condition				
	Make & Model	HONDA	c.c	0	
	Engine No.	HIDDEN	Year of Reg.		
	Chassis No.		Colour	MULTI COLOUR	
	Odometer	36685 KM	Steering	IN ORDER	
	Brakes	IN ORDER	Modification	SPORTS RIM	
	General	FAIR			
3.	3. Conditions of Tyres				
		Size	Make	Balance	
	R/H Front Tyre	70/90-17	DUNLOP	3 mm	
	L/H Front Tyre			mm	
	R/H Rear Tyre	80/90-17	DUNLOP	3 mm	
	L/H Rear Tyre			mm	
4.	Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE O/S AND N/S BODY.		S AND N/S BODY.		
5.	General Information				
	Accident Date	19/07/2021	Inspect Date / Time	29/07/2021 (04:43 PM)	
	Survey held at	PROJECT 8 MOTORWORKS			
	61 WOODLANDS INDUSTRIAL PARK E9, #01-03, E9 PREMIUM, SINGAPORE 757047				
5a.	Remarks				
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$3,000-\$4,000				
5b.	b. Estimate Days of Repair				
	ESTIMATED NORI	ESTIMATED NORMAL PERIOD FOR REPAIR: 4 Working Days			

Report Ref No. CS3/ASM21008062/R1uce2

Inspected By

Automotive Assessor

MOHAMMED RASUL BIN MOHD YUNUS

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser