

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/GRB21008065/UBS3Q2
Date: 20/10/2021**REFERENCE**

Handling Insurer:	India International Insurance Pte Ltd	Policy No:	D21MFL0000447
Claimant Vehicle No :	SKX1891G	Insured Vehicle No :	SLM7833G
Date of Loss:	23/07/2021	Nature of Claim:	TP
		Claim No:	MFL2021D0003213

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKX1891G		
Make & Model:	HONDA CITY, 1.5 VTEC (A)	Engine No:	R18A12048430
Reg. Date:	24/09/2007 (Man. Year: 2007)	Chassis No:	JHMF16307S224282
Colour:	Silver	Odometer:	178756 km
Engine Capacity:	1799 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	205/55Z R16	Rear Tyre Size:	205/55Z R16
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,026.31	29.25	997.06	97.15
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,580.00	1,290.00	290.00	18.35
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	2,606.31	1,319.25	1,287.06	49.38
+ GST 7.00/7.00% (S\$)	182.44	92.35	90.09	49.38

Nett Amount (\$)	2,788.75	1,411.60	1,377.15	49.38
Global Sum Settlement (\$)		0.00		

INSPECTION

Date of Assignment:	29/07/2021		
Date Inspected:	10/08/2021	Inspected At:	Kah Motor Co Sdn Bhd (Ubi) 15 Ubi Road 4 Singapore 408610
Estimated Period of Repair:	2.0 days		

Adjuster:	MARCUS CHUA	Manager:	CHUA ZHEN LI
------------------	-------------	-----------------	--------------

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 20 Oct 2021)
Parts:	143	HONDA CITY 1.5 VTEC (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKX1891G)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FACEREAR BUMPER	Repair	601.42 FS	*- FS
2	1		*CLIP ,ABUMPER (2 PCS)	Necessary	5.85 FS	*5.85 FS
3	2		*CLIP ,ABUMPER	Necessary	23.40 FS	*23.40 FS
4	1		*SPACERL RR BPR SIDE	Not Necessary	12.82 FS	*- FS
5	1		*SPACERR.RR BUMPER SIDE	Not Necessary	12.82 FS	*- FS
6	4		*ACT RR SENSOR	Serviceable	320.00 FS	*- FS
7	1		*SUNDRIES	Not Necessary	50.00 FS	*- FS
					Total Parts (S\$)	1,026.31
						29.25

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	REMOVE & REFIX REVERSE SENSORS	New	180.00	120.00
2	REMOVE & RENEW RR BUMPER INCLUDING FITTINGS ON	New	800.00	650.00
3	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS	New	600.00	520.00
Gross Labour Cost (\$\$)			1,580.00	1,290.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >