



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

CHINA TAIPING INSURANCE (S) PTE LTD

INV No. AC2201401

3 ANSON ROAD #16-00
SPRINGLEAF TOWER
SINGAPORE 079909

INV Date 15/03/2022
Reference CC6/CTI21008071/Uea3q2
Code CTI

PROFESSIONAL SERVICE FEE

Vehicle No. SMF 8572C
Insured Veh. SMY 3791U
Claim No. SNM21D204174/C02
Policy No. DMPCSNW00086442100
Accident Date 27/07/2021
Inspection Date 29/07/2021

Description	Total
Third Party Express Settlement	400.00
Subtotal	400.00
GST (7%)	28.00
Grand Total	428.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
CHINA TAIPING INSURANCE (S) PTE LTD 3 ANSON ROAD #16-00 SPRINGLEAF TOWERSINGAPORE 079909			Ref: CC6/CTI21008071/Uea3q2 Date: 15/03/2022 Code: CTI	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SMY 3791U	Veh. Inspected	SMF 8572C	
Policy No.	DMPCSNW00086442100	Coverage (\$)	0.00	
Claim No.	SNM21D204174/C02	Excess (\$)	0.00	
Assign From		Assign Date	29/07/2021	
2. Vehicle Particulars & Condition				
Make & Model	HONDA HR-V (A)	c.c	1496	
Engine No.	HIDDEN	Year of Reg.	2018	
Chassis No.	JHMRU1810JX200636	Colour	BLUE	
Odometer	58976 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	215/60 R16	DUNLOP	7 mm	
L/H Front Tyre	215/60 R16	DUNLOP	7 mm	
R/H Rear Tyre	215/60 R16	DUNLOP	7 mm	
L/H Rear Tyre	215/60 R16	DUNLOP	7 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	27/07/2021	Inspection Date	29/07/2021	
Survey held at	ASIA MOTORSPORTS SOLUTION PTE LTD 37A EVERITT ROAD SINGAPORE 428586			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			5 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMF 8572C

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	REAR BUMPER ASSY	DENTED / DEFORMED	1,209.00	798.10
2	REAR BUMPER RETAINER	NOT NECESSARY	166.00	-
1	REAR BUMPER LEFT REFLECTOR	NOT NECESSARY	95.00	-
1	REAR BUMPER RIGHT REFLECTOR	NOT NECESSARY	95.00	-
1	REAR BUMPER UNDER COVER	DISTORTED	787.00	345.20
1	REAR BUMPER RIGHT SIDE LOWER PANEL	NO SUCH PARTS	787.00	-
1	REAR LEFT SIDE BUMPER	DEFORMED / WARPED	355.00	195.00
1	REAR RIGHT SIDE BUMPER	NOT NECESSARY	355.00	-
1	REAR TAILGATE ASSY	BADLY DENTED	1,887.00	877.90
1	REAR TAILGATE WEATHERSTRIP	TWISTED	188.00	101.30
1	REAR TAILGATE HRV EMBLEM	NECESSARY	68.00	38.00
1	REAR TAILGATE IVTEC EMBLEM	NECESSARY	68.00	35.00
1	REAR TAILGATE CENTRE LOGO	NOT NECESSARY	68.00	-
1	REAR TAILGATE LOCK SENSOR	CRACKED	289.00	85.20
1	REAR TAILGATE LOCK	BENT / TWISTED	175.00	105.40
1	REAR TAILGATE LOCK CATCH	NOT NECESSARY	68.00	-
2	REAR TAILGATE DAMPER	NOT NECESSARY	276.00	-
2	REAR TAILGATE RUBBER STOPPER	NOT NECESSARY	68.00	-
1	REAR TAILGATE INNER HANDLE	NOT NECESSARY	88.00	-
1	REAR TAILGATE OUTER GARNISH	NOT NECESSARY	678.00	-
1	REAR TAILGATE OUTER GARNISH CHROME	NOT NECESSARY	98.00	-
1	REAR TAILGATE INNER TRIM BOARD	DEFORMED / CRACKED	476.00	280.40
1	REAR LEFT TAILGATE TAILLAMP	CRACKED	423.00	276.90
1	REAR RIGHT TAILGATE TAILLAMP	NOT NECESSARY	423.00	-
1	REAR LEFT TAILLAMP	CRACKED	866.00	482.40
1	REAR RIGHT TAILLAMP	NOT NECESSARY	866.00	-
2	REAR NO PLATE LAMP	NOT NECESSARY	120.00	-
1	REAR END PANEL TOP GARNISH	TWISTED	118.00	118.00
1	REAR END PANEL	BADLY DENTED	1,272.00	382.70

Report Ref No. CC6/CTI21008071/Uea3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	REAR EXHAUST MUFFLER ASSY	NOT NECESSARY	1,297.00	-
2	REAR EXHAUST MUFFLER RUBBER MOUNTING	NOT NECESSARY	66.00	-
1	REAR FLOOR PANEL TOP BOARD	TORN	1,670.00	316.00
1	REAR FLOOR PANEL TOOLS SPONGE	TORN	298.00	298.00
1	REAR WIPER BLADE ASSY	NOT NECESSARY	166.00	-
1	REAR WINDSCREEN GLASS MOULDING	NECESSARY	288.00	118.00
1	REAR LEFT FENDER SIDE PROTECTOR	TORN	195.00	180.10
1	REAR RIGHT FENDER SIDE PROTECTOR	NOT NECESSARY	195.00	-
	LESS 20% DISCOUNT		-3,321.40	-1,006.72
			13,285.60	4,026.88
	<u>SPECIAL NETT ITEMS</u>			
1	SET REAR BUMPER CLIPS (SN)	NECESSARY	60.00	40.00
1	SET REAR BUMPER REVERSE SENSOR (SN)	SHORTED	1,200.00	200.00
1	REAR NO PLATE WITH GARNISH (SN)	NOT NECESSARY	100.00	-
4	REAR END LOWER PANEL TOP GARNISH CLIPS (SN)	NOT NECESSARY	30.00	-
1	REAR END PANEL SEALANT (SN)	NECESSARY	100.00	50.00
1	REAR WINDSCREEN GLASS SEALANT (SN)	NECESSARY	100.00	40.00
1	SET REAR TAILGATE INNER TRIM BOARD CLIPS (SN)	NECESSARY	60.00	45.00
6	REAR TAILGATE OUTER GARNISH CLIPS (SN)	NOT NECESSARY	40.00	-
1	REAR VIEW CAMERA (SN)	NOT NECESSARY	500.00	-
1	REAR FLOOR PANEL SEALANT (SN)	NOT NECESSARY	150.00	-
1	REAR FLOOR PANEL INSULATOR PAD (SN)	NOT NECESSARY	180.00	-
6	REAR LEFT FENDER SIDE PROTECTOR CLIPS (SN)	NOT NECESSARY	30.00	-
6	REAR RIGHT FENDER SIDE PROTECTOR CLIPS (SN)	NOT NECESSARY	30.00	-
			2,580.00	375.00
	<u>LABOUR</u>			
	LABOUR FOR PANEL BEATING ,CUT ,WELD ,STRAIGHTEN REAR AFFECTED AREAS AND REPLACE REAR DAMAGED PARTS INCLUDING FLOOR PANEL .		1,400.00	850.00
	TO PUTTY AND SPRAY PAINTING REAR PORTION .		1,400.00	1,000.00
	TO CHECK REAR LIGHTING AND WIRING .		50.00	20.00
	TO REMOVE AND INSTALL REAR TAILGATE LOCK MECHANISM.		80.00	60.00

Report Ref No. CC6/CTI21008071/Uea3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO REMOVE AND INSTALL REAR EXHAUST MUFFLER ASSY .	NOT NECESSARY	120.00	-
	TO REMOVE AND INSTALL REAR INNER GARNISH AND TRIM TO FACILITATE THE REPAIR.		140.00	80.00
	TO APPLY ANTI RUST PROOFING TO REAR AFFECTED AREA.		140.00	60.00
	TO REMOVE AND INSTALL REAR BUMPER REVERSE SENSOR .		80.00	50.00
	TO REMOVE AND INSTALL REAR WINDSCREEN GLASS TO FACILITATE THE REPAIR .		140.00	120.00
	TO REMOVE AND INSTALL REAR VIEW CAMERA.	NOT NECESSARY	80.00	-
	TOWING SERVICE.	NOT NECESSARY	100.00	-
			3,730.00	2,240.00
GRAND TOTAL			19,595.60	6,641.88
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				5,300.00

Report Ref No. CC6/CTI21008071/Uea3q2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SMF 8572C

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R






LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SMF 8572C

RE-INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SMF 8572C

RE-INSPECTION

