

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/III21008073/GPA3Q2**Date:** 30/06/2022REFERENCE

Handling Insurer: India International Insurance Pte Ltd Policy No: D19MFL0005549_01

Claimant Vehicle No : SLB7565M **Insured Vehicle No :** GBJ970Z

Date of Loss: 25/07/2021 Nature of Claim: TP Claim No: MFL2021D0003347

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLB7565M**

Make & Model: NISSAN NOTE, 1.2 (A) Engine No: HR12172788B

Reg. Date: 21/04/2016 (Man. Year: 2016) Chassis No: JN1TBAE12Z0982393

Colour: Red Odometer: 84698 km

Engine Capacity: 1198 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 185/65 R15 Rear Tyre Size: 185/65 R15

Front Left Side: Dunlop 6 mm Rear Left Side: Dunlop 6 mm

Front Right Side: Dunlop 6 mm Rear Right Side: Dunlop 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	14,037.90	7,919.64	6,118.26	43.58
Miscellaneous Items	851.00	441.00	410.00	48.18
Labour	3,630.00	1,510.00	2,120.00	58.40
Paintwork Labour	1,200.00	1,150.00	50.00	4.17
Towing	0.00	0.00	0.00	
Gross Total (S\$)	19,718.90	11,020.64	8,698.26	44.11
+ GST 7.00/7.00% (S\$)	1,380.33	771.44	608.89	44.11
Nett Amount (S\$)	21,099.23	11,792.08	9,307.15	44.11
+ Car Rental (10.0 x S\$100.00/day) (S\$)		1,000.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		12,799.53		
Global Sum Settlement (S\$)		12,700.00		

INSPECTION

Date of Assignment: 29/07/2021 Present Location: Progressive Car Care Pte Ltd (HQ)

Date Inspected: 29/07/2021 Inspected At: Progressive Car Care Pte Ltd (HQ)
Blk 3022A Ubi Road 1, #01-45/46
Singapore 408716

Estimated Period of Repair: 8.0 days

Adjuster: XING GUO QIANG**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 28 Dec 2021)
Parts:	144	NISSAN NOTE 1.2 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLB7565M)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1	NA	*FRONT BUMPER	Deformed	494.30 F	*448.00 FN
2	2	NA	*FRONT BUMPER SIDE HOLDER - LH & RH	Cut	55.00 F	*55.00 FN
3	10	NA	*FRONT BUMPER CLIPS	Necessary	44.00 F	*27.00 FN
4	1	NA	*FRONT BUMPER FOG LAMP - LH	Not Necessary	321.60 FS	*- FS
5	1	NA	*FRONT BUMPER FOG LAMP - RH	Not Necessary	321.60 FS	*- FS
6	1	NA	*FRONT BUMPER REINFORCEMENT	Bent	419.70 F	*419.70 FN
7	1	NA	*FRONT BUMPER FOAM	Cracked	240.90 F	*218.00 FN
8	1	NA	*FRONT BUMPER TOP COVER	Broken	27.00 F	*27.00 FN
9	5	NA	*FRONT BUMPER TOP COVER CLIPS	Necessary	22.00 F	*22.00 FN
10	1	NA	*FRONT BUMPER UNDER COVER	Cut	378.40 F	*378.40 FN
11	10	NA	*FRONT BUMPER UNDER COVER CLIPS	Necessary	44.00 F	*27.00 FN
12	1	NA	*FRONT BONNET	Bent	847.80 F	*847.80 FN
13	1	NA	*FRONT BONNET HINGE - LH	Bent	42.00 F	*42.00 FN
14	1	NA	*FRONT BONNET HINGE - RH	Not Necessary	42.00 F	*- FN
15	1	NA	*FRONT BONNET INSULATOR	Not Necessary	89.70 F	*- FN
16	4	NA	*FRONT BONNET LOCK	Not Necessary	317.60 F	*- FN
17	1	NA	*LOGO	Not Necessary	64.90 F	*- FN
18	1	NA	*FRONT BONNET CABLE	Not Necessary	39.60 FS	*- FS
19	1	NA	*FRONT FENDER - LH	Buckled	544.40 F	*544.40 FN
20	1	NA	*FRONT FENDER COWLING - LH	Torn	100.50 F	*100.50 FN
21	10	NA	*FRONT FENDER COWLING CLIPS - LH	Necessary	44.00 F	*44.00 FN
22	1	NA	*FRONT WHEELHOUSE PANEL - LH	Repair	431.60 F	*- FN
23	1	NA	*FRONT GRILLE ASSY W/NISSAN LOGO	Cracked	276.70 F	*276.70 FN
24	1	NA	*FRONT SUPPORT PANEL ASSY (TOP)	Not Necessary	323.20 F	*- FN
25	1	NA	*FRONT SUPPORT PANEL TOP GARNISH	Broken	276.70 F	*276.70 FN
26	10	NA	*FRONT SUPPORT PANEL TOP GARNISH CLIPS	Necessary	44.00 F	*27.00 FN
27	2	NA	*FRONT HEADLAMP ASSY	Cracked	3,229.20 F	*3,229.20 FN
28	1	NA	*AIRCON CONDENSER	Not Necessary	696.90 FS	*- FS
29	1	NA	*AIRCON CONDENSER SIDE GARNISH - LH	Deformed	38.40 FS	*38.40 FN
30	1	NA	*AIRCON CONDENSER SIDE GARNISH - RH	Deformed	38.40 FS	*38.40 FN
31	1	NA	*FUSE BOX (UPPER)	Broken	48.30 F	*48.30 FN
32	1	NA	*FUSE BOX (MIDDLE)	Broken	48.30 F	*48.30 FN
33	1	NA	*FUSE BOX (LOWER)	Broken	39.80 F	*39.80 FN
34	1	NA	*FRONT RIM - LH (NPA)	Repeated	0.00 F	*- FS
35	1	NA	*FRONT LOWER ARM - LH	Bent	195.50 F	*195.50 FN
36	1	NA	*FRONT KNUCKLE - LH	Jammed	382.50 FS	*382.50 FN
37	1	NA	*FRONT KNUCKLE BEARING - LH	Jammed	134.60 FS	*134.60 FN
38	1	NA	*FRONT WHEEL HUB - LH	Bent	221.10 FS	*221.10 FN
39	1	NA	*FRONT ABSORBER - LH	Bent	294.30 FS	*294.30 FN
40	1	NA	*FRONT ABSORBER TOP MOUNTING - LH	Bent	90.60 F	*90.60 FN
41	1	NA	*STEERING RACK	Not Necessary	1,470.80 FS	*- FS
42	1	NA	*CROSSMEMBER	Not Necessary	323.60 FS	*- FS
43	1	NA	*RADIATOR	Not Necessary	584.00 FS	*- FS
44	1	NA	*RADIATOR TOP HOSE	Not Necessary	36.10 FS	*- FS
45	1	NA	*RADIATOR LOWER HOSE	Not Necessary	54.90 FS	*- FS

Report was unsubmitted during this print-out.

6/30/22, 9:51 AM

Adjuster Report

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
Supplementary #1						
46	1		*STEERING RACK TIE ROD END R/F	Bent	129.90 FS	*129.90 FN
47	1		*STEERING RACK TIE ROD R/F	Bent	127.50 F	*127.50 FN
F=Franchise part. S=SpcNett. N=NettItemDisc.						
Sub Total (S\$)					14,037.90	8,799.60
- Nett Item Discount on N Items 0.00/10.00% (S\$)					0.00	879.96
Total Parts (S\$)					14,037.90	7,919.64
Report was unsubmitted during this print-out.						

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
Miscellaneous Items				
1	1	BATTERY (NOT NECESSARY)	200.00	0.00
2	1	FRONT NUMBER PLATE WITH CASING (CUT)	50.00	40.00
3	1	FRONT TYRE - LH (CUT)	280.00	90.00
4	1	QUARTER GLASS SEALANT (NECESSARY)	10.00	10.00
5	1	TO REFILL RADIATOR COOLANT (NECESSARY)	50.00	40.00
6	1	OD/TP Case (Insurer)	11.00	11.00
Supplementary #1				
7	1	RIM , R/F USED (CUT)	250.00	250.00
Sub Total (\$\$)			851.00	441.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Paintwork Labour				
1	TO RESPRAY PAINT ON FRONT HEAD; LH FRONT DOOR; SUPPORT PANEL & WHEELHOUSE PANEL; DOOR PILLAR	New	1,200.00	1,150.00
Labour Items				
2	TO KNOCK OUT DENTS; STRAIGHTEN FRONT CHASSIS; CUT/WELD SUPPORT PANEL; LH FRONT WHEEL HOUSE; REMOVE; REPLACE ACCIDENT PARTS	New	1,600.00	800.00
3	TO REMOVE; REFIX FENDER QUARTER GLASS	New	80.00	60.00
4	TO REMOVE; REPLACE CROSSMEMBER; STEERING RACK	New	500.00	350.00
5	TO 4 WHEEL ALIGNMENT	New	100.00	60.00
6	TO REMOVE; REPLACE RIM & REBALANCING	New	50.00	30.00
7	TO CHECK WIRING; SOCKETS INCLUDING FOCUS OF HEADLAMP	New	50.00	30.00
8	TO REMOVE; REPLACE CONDENSER AND REFILL GAS	New	100.00	100.00
9	TO RESET CHECK LIGHT	New	200.00	0.00
10	TO TUFF-KOTE	New	120.00	80.00
11	TO REMOVE; REPLACE FUSE BOX TOP; LOWER; CENTRE; TRANSFER FUSE AND RELATED PARTS	New	180.00	0.00
12	TO REMOVE; REPLACE FRONT CROSSMEMBER; LH FRONT UNDERCARRIAGE	New	650.00	0.00
Gross Labour Cost (\$\$)			4,830.00	2,660.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >